

**BULLETIN OF THE
NEW ZEALAND SOCIETY
FOR EARTHQUAKE ENGINEERING**

TWENTY-FIVEYEAR INDEX

VOLUME 1 (1968) TO VOLUME 25 (1992)

Compiled by A.J. (Tony) Bartlett

Key to Bulletin issues

Vol 1	1968	Vol 3	1970	Vol 13	1980	Vol 23	1990
Vol 2	1969	Vol 4	1971	Vol 14	1981	Vol 24	1991
		Vol 5	1972	Vol 15	1982	Vol 25	1992
		Vol 6	1973	Vol 16	1983		
		Vol 7	1974	Vol 17	1984		
		Vol 8	1975	Vol 18	1985		
		Vol 9	1976	Vol 19	1986		
		Vol 10	1977	Vol 20	1987		
		Vol 11	1978	Vol 21	1988		
		Vol 12	1979	Vol 22	1989		

Note: All volumes consist of four issues dated March, June, September and December - except three. The exceptions are:

Vol 1 (1968) - 2 issues, dated June/July and December

Vol 2 (1969) - 4 issues, dated February, June, September and December

Vol 4 (1971) - 3 issues, dated March, April and December

CONTENTS

<p>Index of authors 67</p> <p>Subject Index 83</p> <p>Australia/New Zealand Standards <i>see</i> Standards</p> <p>Base isolation <i>see</i> Earthquake Engineering</p> <p>Book reviews 83</p> <p>Bridges 83</p> <p>Building Construction 83</p> <p>Buildings (includes public buildings, high-rise buildings, multistorey buildings) 84</p> <p>Building contents (includes building services, non-structural elements) 84</p> <p>Civil Defence 84</p> <p>Codes <i>see</i> Standards</p> <p>Conferences and seminars 85</p> <p>Disaster relief (includes disaster assistance) 85</p> <p>Discussion 85</p> <p>Earthquake damage (includes restoration, reconstruction): <i>and see</i> <i>Reconnaissance reports</i> 86</p> <p>Earthquake engineering 87</p> <p>Earthquakes general 89</p> <p>Earthquakes in New Zealand 89</p> <p>Earthquake mitigation 91</p> <p>Earthquake prediction (includes earthquake warning systems) 91</p> <p>Earthquake resistant structures <i>and see</i> <i>Seismic design</i> 91</p> <p>Earthquake risk buildings <i>and see</i> <i>Refurbishment and retrofitting</i> 92</p> <p>Economics 92</p> <p>Editorials and Leading Articles 93</p> <p>Electric power (includes power plants, power transmission) 93</p> <p>Energy-absorbing devices <i>see</i> Earthquake engineering</p> <p>Engineering education (includes engineering qualification, registration) 93</p> <p>Errata 93</p> <p>General 93</p> <p>Geology (includes geophysics) 93</p> <p>Geomechanics 94</p> <p>Ground response (includes ground shaking, soil testing, liquefaction) 94</p>	<p>Industrial plants 95</p> <p>Insurance 95</p> <p>Law (includes law and order, policing) 95</p> <p>Letters 95</p> <p>Life members 96</p> <p>Lifelines 96</p> <p>Masonry 96</p> <p>Modified Mercalli Scale <i>and see</i> <i>Seismology</i> 96</p> <p>New Zealand National Society for Earthquake Engineering (NZNSEE) <i>and see</i> <i>Reconnaissance reports and Life</i> <i>members</i> 96</p> <p>Obituaries 97</p> <p>Planning 97</p> <p>Policing <i>see</i> Law</p> <p>Prestressed concrete 97</p> <p>Railways 98</p> <p>Reconnaissance reports 98</p> <p>Reconstruction <i>see</i> Earthquake damage</p> <p>Refurbishment and retrofitting <i>and see</i> <i>Earthquake risk buildings</i> 98</p> <p>Reinforced concrete (includes high strength concrete) 98</p> <p>Research (includes testing) 100</p> <p>Retrofitting <i>see</i> Refurbishment</p> <p>Roading 102</p> <p>Seismic analysis and response 102</p> <p>Seismic design <i>and see</i> <i>Earthquake resistant</i> <i>structures</i> 103</p> <p>Seismic hazards (includes seismic risk) 108</p> <p>Seismic zoning 108</p> <p>Seismology 109</p> <p>Soils <i>see</i> Ground Response, Geology</p> <p>Standards 110</p> <p>Steel 111</p> <p>Strong motion seismology 112</p> <p>Timber 112</p> <p>Tsunamis 112</p> <p>Volcanoes 112</p>
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

INDEX OF AUTHORS

A

- Adams, J. Earthquakes, landslides, and large dams in New Zealand. 14(2) 93
- Adams, R.D. An immediate field survey of the San Fernando, Los Angeles earthquake, February 9, 1971. 4(3) 335
- D.S.I.R. microzoning programme. 2(3) 282
- Developments in studies of earthquake risk. 8(1) 1
- Editorial - How beneficial is earthquake prediction? 5(4) ii
- Microzoning for earthquake effects in the Wellington City area. 5(3) 106
- Principal New Zealand earthquakes during the year 1972. 6(1) 48
- Principal New Zealand earthquakes during the year 1973. 7(1) 48
- Principal earthquakes during the year 1976. 10(1) 52
- Principal earthquakes during the year 1977. 11(1) 62
- Properties of aftershock sequences. 1(2) 113
- The Haicheng, China, earthquake of February, 1975: the first successfully predicted major earthquake. 9(1) 32
- The New Zealand seismograph network. 1(2) 116
- Who says earthquakes don't happen here? 7(2) 52
- Adams, R.D.: Eiby, G.A.: Lowry, M.A. A preliminary seismological report (*Inangahua earthquake 1968*). 2(1) 9
- Adams, R.D.: Kean, R.J. The Dunedin earthquake, 9 April 1974, Part 1: seismological studies. 7(3) 115
- Adams, R.D.: Muir, M.G.: Kean, R.J. Te Aroha earthquake, 9 January 1972. 5(2) 54
- Ahmadi, G. see Mostaghel, N.
- Aiken, I.D.: Nims, D.K.: Kelly, J.M. Comparative study of four passive energy dissipation systems. 25(3) 175
- Algermissen, S.T. Techniques and parameters for earthquake risk assessment. 22(4) 202
- Allardice, N.W. NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section K Parts, portions and secondary elements. 10(2) 102
- Allardice, N.W.: Fenwick, R.C.: Taylor, P.W.: Williams, R.L. NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section D Foundations for ductile frames. 11(2) 122
- Allwood, M.J.R. Bay of Plenty earthquake: an outline of the Earthquake and War Damage Commission's role. 21(2) 113
- Anderson, H. see Smith, E.G.C.
- Anderson, P.D.: Osborne, T.W.J. Damage from Greymouth to Hokitika (*Inangahua earthquake 1968*). 2(1) 147
- Anderson, P.D.: Smith, F.R.: Quinn, F. Damage in the Greymouth area (*Inangahua earthquake 1968*). 2(1) 139
- Andiono, T.: Park, R. Seismic design considerations of the properties of New Zealand manufactured steel reinforcing bars. 19(3) 213
- Andrews, A.L. 1979 South Pacific Regional Conference on earthquake engineering - conference report. 12(2) 175
- A note about base shear. 2(2) 171
- Building damage in Westport (*Inangahua earthquake 1968*). 2(1) 126
- Design of seismic resistant prestressed concrete structures. 9(3) 175
- Discussion - A consideration of P-delta effects in ductile reinforced concrete frames, by T. Paulay (Vol 11(3)). 11(3) 196
- Discussion - A consideration of P-Delta effects in ductile reinforced concrete frames, by T. Paulay (11(3)). 12(4) 357
- Editorial - Macrozoning for earthquake engineering. 5(3) ii
- Lateral flexibility and seismic deflection estimates How good is good enough? 1(1) Unpaged
- Slenderness effects in earthquake resisting frames. 10(3) 154
- Andrews, A.L. see Hutchison, D.L.
- Andrews, A.L. see Park, R.
- Andrews, A.L.: Butcher, G.W. Technical note: Intensity of shaking generated by large shallow New Zealand earthquakes. 25(4) 358
- Andriono, T.: Carr, A.J. A simplified earthquake resistant design method for base isolated multistorey structures. 24(3) 238
- Reduction and distribution of lateral seismic inertia forces on base isolated multistorey structures. 24(3) 225
- Ansell, J. see Smith, E.G.C.
- Aoyama, H. Obituary - Professor Kiyushi Muto. 22(2) 132
- Aoyama, H. Recent developments in seismic design of reinforced concrete buildings in Japan. 24(4) 333
- Armstrong, F.N. Civil defence at the local body level. 2(4) 371
- Armstrong, I.C. Capacity design of reinforced concrete frames for ductile earthquake performance. 5(4) 133
- Design of shear walls for seismic resistance. 10(1) 17
- Full-strength butt welds of reinforcing bars by the pressure-gas process. 4(2) 270
- Armstrong, I.C.: Page, W.J. Pressure-gas butt welding of reinforcing bars. 2(3) 329
- Arnold, C. Building configuration: the architecture of seismic design. 17(2) 83
- The seismic response of nonstructural elements in buildings. 24(4) 306

B

- Babor, J. see Dowrick, D.J.
- Baguley, D.E. see Tyler, R.G.
- Barker, P.R. see Stephenson, W.R.
- Beamish, M.J. Cyclic loading tests on steel portal frame knee joints. 20(1) 42
- Beanland, S. Timing of the last large earthquake on the Wellington fault from the Tararua ranges to Woodville. 22(1) 4
- Beck, J.L. see Hefford, R.T.
- Beck, J.L.: Randal, P.M.: Hefford, R.T. Technical note: Computer analyses of New Zealand earthquake accelerograms - Volume 1. 15(1) 46
- Begg, J.G. see Dellow, G.D.
- Bennett, J.R. see Chandler, T.M.
- Bent, D.P. see Shephard, R.B.
- Bentley, R.J. Earthquake risk buildings in Wellington. 11(3) 200

- Bentley, R.J. (contd) Kaiwharawhara
reclamation. 13(2) 203
Report on the second (1978) microzonation
conference. 12(1) 72
- Berrill, J.B. Distribution of scatter in New Zealand
accelerograph data. 18(2) 151
Seismic hazard analysis and design loads. 18(2) 139
Suggested extensions of the New Zealand strong
motion accelerograph network. 12(3) 264
Technical note - A note on the 1976, Gazli
accelerogram. 10(4) 238
- Berrill, J.B. see Fairless, G.J.
Berrill, J.B. see Lai Cho Sim.
Berrill, J.B. see Matthewson, M.B.
Berrill, J.B. see Peek, R.
Berrill, J.B. see Shephard, R.B.
- Berrill, J.B.: Bienvenu, V.C.: Callaghan, M.W.
Liquefaction in the Buller region in the 1929
and 1968 earthquakes. 21(3) 174
- Berrill, J.B.: Priestley, M.J.N.: Chapman, H.E.
NZNSEE discussion group on the seismic design
of bridges. Section 2: Design earthquake
loading and ductility demand. 13(3) 232
- Berrill, J.B.: Priestley, M.J.N.: Peek, R. Further
comments on seismic design loads for bridges.
14(1) 3
- Berryman, K. Reconnaissance field investigation of
the Landers earthquake (Ms 7.5) of June 28, 1992,
San Bernardino County, California, USA. 25(3) 230
- Berryman, K.R. Rate of movement and geometry of
the southern segment of the Wellington Fault.
22(1) 4
- Berryman, K.R. see Matuschka, T.
Berryman, K.R. see Smith, W.D.
- Berryman, K.R.: Darby, D.J. Progress in earth
science research of benefit to the earthquake
insurance industry 23(2) 130
- Bertero, V.V. Identification of research needs for
improving the aseismic design of building
structures. 9(1) 1
- Bertero, V.V.: Mahin, S.A.: Hollings, J. Response
of a reinforced concrete shear wall structure
during the 1972 Managua earthquake. 7(3) 95
- Bienvenu, V.C. see Berrill, J.B.
- Billings, I.J. 3rd US-Japan workshop on the
improvement of building structural design and
construction practices, July 29-August 1
1988 Tokyo, Japan. 22(2) 73
- Binney, J.R. see Sharpe, R.D.
- Binney, J.R.: Paulay, T. NZNSEE discussion group
on reinforced concrete walls and diaphragms.
Section F: Foundations for shear wall
structures. 13(2) 171
- Bird, D.I.D. Insurance assessments in Inangahua
(*Inangahua earthquake 1968*). 2(1) 111
- Bird, D.I.D.: Gentry, S.C.: Hollings, J.P. Building
damage in the Reefon area (*Inangahua earthquake
1968*). 2(1) 130
- Birss, G.R. Methodology for the assessment of the
damage cost resulting from a large earthquake in
the vicinity of Wellington. 18(3) 215
- Bishop, D.G. The Dunedin earthquake, 9 April, 1974
Part 2: local effects. 7(3) 123
- Blackwell, F.N. A study of the earthquake resistance
of domestic break pressure tanks. 12(2) 168
- Blackwell, F.M. Letter - Editorial comment on
Building Services. 7(1) 50
- Blaikie, E.L. Column strength requirements in
multi-storey seismic frames. 22(3) 135
- Blakeley, R.W.G. A review of the new code
provisions for separation of elements and
buildings. 7(3) 130
Prestressed concrete seismic design. 6(1) 2
NZNSEE discussion group on seismic design of
ductile moment resisting reinforced concrete
frames. Section J Design of beam-column joints.
10(4) 226
South Pacific Regional Conference on Earthquake
Engineering 13-15 May, 1975. 8(2) 170
- Blakeley, R.W.G. see Wood, J.H.
- Blakeley, R.W.G.: Charleson, A.W.: Hitchcock, H.C.:
Megget, L.M.: Priestley, M.J.N.: Sharpe, R.D.:
Skinner, R.I. Recommendations for the design
and construction of base isolated structures.
12(2) 136
- Blakeley, R.W.G.: Cooney, R.C.: Megget, L.M.
Seismic shear loading at flexural capacity in
cantilever wall structures. 8(4) 278
- Blakeley, R.W.G.: Cormack, L.G.: Stockwell, M.J.
NZNSEE discussion group on the seismic design
of bridges. Section 6: Mechanical energy
dissipating devices. 13(3) 264
- Blakeley, R.W.G.: Edmonds, F.D.: Megget, L.M.:
Wood, J.H. Cyclic load testing of two refined
reinforced concrete beam-column joints. 12(3) 238
- Blakeley, R.W.G.: Megget, L.M.: Priestley, M.J.N.
Seismic performance of two full-size re-
inforced concrete beam-column joint units. 8(1) 38
- Blakeley, R.W.G.: Park, R. Ductility of
prestressed concrete members. 4(1) 145
- Blakeley, R.W.G.: Park, R.: Shepherd, R. A review
of the seismic resistance of prestressed
concrete. 3(1) 3
- Blenkinsopp, J.G. Civil defence at No. 1 sub-region
level, Auckland Regional Authority. 2(4) 357
- Blick, G.H. Geodetic observations in the
Wellington Region. 22(1) 6
- Bloxam, M.J.: North, P.J. Tauranga Harbour
crossing, Stella Passage bridge - seismic
design. 23(3) 220
- Bluck, B.C. Discussion - Classification of high
earthquake risk buildings Draft Code of
Practice, 2 March 1972. 5(3) 108
The need for a strengthening code. 7(2) 88
- Boardman, P.R. Case studies: earthquake risk
buildings. 4. Restoration of old Auckland
Customhouse. 16(1) 73
- Boardman, P.R.: Wood, B.J.: Carr, A.J. Union
House - a cross braced structure with
energy dissipators. 16(2) 83
- Borcherdt, R.D. On the observation,
characterisation and predictive GIS mapping
of strong ground shaking for seismic zonation
(a case study in the San Francisco Bay
region, California). 24(4) 287
- Bourke, L.P. Ministry of Civil Defence -
Northern Region. 2(4) 347
- Bowman, I. Conservation of historic buildings in a
seismic zone: a New Zealand perspective. 21(2) 128
- Bowman, I. see Hopkins, D.C.
- Boyce, W.H. Earthquake engineering research at the
Papua and New Guinea Institute of Higher
Technical Education. 2(4) 482
Treatment of earthquake accelerograms. 3(4) 163
- Bracegirdle, A. Seismic stability of reinforced
earth retaining walls. 13(4) 347
- Brennan, E. see Rynn, J.M.W.
- Bridgeman, D.O. see Priestley, M.J.N.

- Britton, N.R. Society, prediction and warning: current assumptions on the implications of earthquake forecasting. 13(4) 365
The social implications of earthquake predictions and warnings on and for organisations. 11(1) 15
- Brown, B.J. Seismic design of pallet racking systems. 16(4) 291
- Brunsdon, D.R. Letter - The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions (25(2) pp 77-144) 25(4) 361
Second Conference on Tall Buildings in Seismic Regions. May 16 and 17, 1991, Los Angeles, California, U.S.A. 24(3) 207
The December 28, 1989 Newcastle, Australia Earthquake. 23(2) 102
- Brunsdon, D.R. see Park, R.
- Brunsdon, D.R.: Priestley, M.J.N. Assessment of seismic performance characteristics of reinforced concrete buildings constructed between 1936 and 1975. 17(3) 163
- Brunsdon, D.R.: Shephard, R.B. NZNSEE study group for structures of limited ductility: 4. The evaluation of existing structures. 19(4) 325
- Bryant, A.H.: Gibson, J.A.: Mitchell, T.N.: Thurston, S.J. Nailed moment joints in timber structures. 14(4) 223
- Buchanan, A.H. Developments in design of wood structures for earthquake resistance. 16(2) 156
Diagonal beam reinforcing for ductile frames. 12(4) 346
NZNSEE study group for structures of limited ductility: 2. Design of building structures of limited ductility 2.5 Timber. 19(4) 313
- Buchanan, A.H. see Moss, P.J.
- Buchanan, A.H. see Park, R.
- Buchanan, B.W. see Irvine, H.M.
- Buchanan, B.W. see Kolston, D.
- Bull, D.K. see Park, R.
- Bunce, G.K. Earthquake recording instrument: type M.O.2 strong motion accelerograph. 2(3) 308
- Burns, R.J. Book review: Aseismic design analysis of buildings, by Kiyoshi Muto. 7(3) 147
- Burns, R.J. NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section A Introduction and philosophy. 10(2) 69
Conclusion. 11(2) 121
- Busby, M.J. see Safi, B.F.
- Butcher, G.W. 1975 Seminar on NZS 4203. Design loadings. 9(1) 56
Steel design. 6(2) 71
Steel seismic design. 3(2) 60
The New Zealand Loadings Code and its application to the design of seismic resistant prestressed concrete structures. 9(3) 162
- Butcher, G.W. see Andrews, A.L.
- Butcher, G.W. see Hutchison, D.L.
- Butcher, G.W. see Spring, K.C.F.
- Butcher, G.W. see Walpole, W.R.
- Butterworth, J.W.: Spring, K.C.F. NZNSEE study group for the seismic design of steel structures. Section D Column Design. 18(4) 344
- Buxton, F.N. Case studies: earthquake risk buildings 1. The upgrading of Middle School, cnr Jed and Don streets, Invercargill. 16(1) 60
- Callaghan, M.W. see Berrill, J.B.
- Campbell, M.D.: McKay, G.R.: Williams, R.L. The Tonga earthquake of 23 June, 1977 - some initial observations. 10(4) 208
- Carr, A.J. see Andriano, T.
- Carr, A.J. see Boardman, P.R.
- Carr, A.J. see Cooke, N.
- Carr, A.J. see Dean, J.A.
- Carr, A.J. see Edmonds, F.D.
- Carr, A.J. see Goodsir, W.J.
- Carr, A.J. see Kivell, B.T.
- Carr, A.J. see Moss, P.J.
- Carr, A.J. see Paulay, T.
- Carr, A.J. see Priestley, M.J.N.
- Carr, A.J. see Sharpe, R.D.
- Carr, A.J. see Tjondro, J.A.
- Carr, A.J.: Moss, P.J. Elastic soil-structure interaction. 4(2) 258
- Cathie, M.C.: Leuchars, J.M. Case studies: earthquake risk buildings 2. Upgrading of AMP Society branch office corner Customhouse Quay and Hunter Street, Wellington. 17(1) 65
- Catley, T.J. see Jury, R.D.
- Chandler, A.M.: Hutchison, G.L. A modified approach to earthquake resistant design of torsionally coupled buildings. 21(2) 140
- Chandler, A.M.: Pappin, J.W.: Coburn, A.W. Vulnerability and seismic risk assessment of buildings following the 1989 Newcastle, Australia, earthquake. 24(2) 116
- Chandler, T.M.: Bennett, J.R. Damage in the Westport area (*Inangahua earthquake 1968*). 2(1) 128
- Chapman, H.E. NZNSEE study group for structures of limited ductility: 3. Design of bridge superstructures of limited ductility. 19(4) 319
- Chapman, H.E. see Berrill, J.B.
- Chapman, H.E. see Cormack, L.G.
- Chapman, H.E. see Park, R.
- Chapman, H.E. see Zahn, F.A.
- Chapman, H.E.: North, P.J.: Park, R. NZNSEE discussion group on the seismic design of bridges. Section 3: Capacity design principles and practice. 13(3) 242
- Charleson, A.W. see Blakeley, R.W.G.
- Charleson, A.W. see Thurston, S.J.
- Cheung, P.C.: Paulay, T.: Park, R. Some possible revisions to the seismic provisions of the New Zealand Concrete Design Code for Moment Resisting Frames. 25(1) 37
- Christianson, J. Case studies: earthquake risk buildings. 4. State Opera House - upgrading. 16(2) 175
- Chung, B.T. see Fenwick, R.C.
- Clark, W.D. see Hopkins, D.C.
- Clarke, W.D.: Glogau, O.A. Suspended ceilings: the seismic hazard and damage problem and some practical solutions. 12(4) 292
- Clendon, J.E. see Poole, R.A.
- Clifton, G.C. Discussion - Seismic response of low-rise buildings, by Moss, P.J.: Carr, A.J.: Buchanan, A.H. (19(3)). 20(1) 66
Letter. 15(3)
Structural steel test photographs. 16(4) 345
NZNSEE study group for the seismic design of steel structures. Section I Composite design. 18(4) 381
Section J Cold formed sections. 18(4) 397
- Clough, R.W. see Mayes, R.L.
- Coburn, A.W. see Chandler, A.M.

C

Calhaem, I.M. Pukaki earthquake of 17 December 1978. 12(1) 7

Connor, I.N. The San Antonio, Chile, earthquake of 3 March 1985. 18(2)	128
Cooke, N. see Moss, P.J.	
Cooke, N.: Carr, A.J.: Moss, P.J.: Tan Fun Kwai. The influence of non-geometric factors on the seismic behaviour of bridges on isolating bearings. 19(4)	263
Cooney, R.C. The structural performance of houses in earthquakes. 12(3)	223
Cooney, R.C. see Blakeley, R.W.G.	
Cormack, L.G. see Blakeley, R.W.G.	
Cormack, L.G. see Park, R.	
Cormack, L.G. see Standford, P.R.	
Cormack, L.G.: Park, R.: Chapman, H.E. NZNSEE discussion group on the seismic design of bridges. Section 5: Detailing for ductility and ductility capacity. 13(3)	262
Cousins, W.J. see Dowrick, D.J.	
Cousins, W.J.: Robinson, W.H.: McVerry, G.H. Recent developments in devices for seismic isolation. 25(3)	167
Craig, W.T. Rights and duties of owners and mortgagees (<i>Inangahua earthquake 1968</i>). 2(1)	119
Croad, R.N.: Mead, F.H.: Shepherd, R. The cyclic yield response of a steel star plate cruciform joint. 8(3)	204
Crookes, S.I. Leading article. 1(2)	2
Letter - Lateral flexibility and seismic deflection estimates How good is good enough? by A.L. Andrews (Vol 1(1)). 1(2)	21
Crosbie, R.L. see Priestley, M.J.N.	

D

Dai Ruitong see Park, R.	
Daisuke Kato: Shunsuke Otani: Hideo Katsumata: Hiroyuki Aoyama. Effect of wall base rotation on behaviour of reinforced concrete frame-wall building. 17(2)	106
Darby, D.J. Is strain concentrating about the Wellington fault? 22(1)	9
Darby, D.J. see Berryman, K.R.	
Darby, D.J.: Perrin, N.D. Mechanical strain gauge measurements at Te Marau[sic]. 19(2)	104
Davey, R.A. see Matthewson, C.D.	
Davidson, B.J. see Fenwick, R.C.	
Davidson, B.J. see Priestley, M.J.N.	
Davidson, C.C. Case studies: earthquake risk buildings. 2. Anglican parish of Blenheim: strengthening to the Church of the Nativity. 16(1)	64
Davis, R.O. see Peek, R.	
Dean, J.A. The performance of a ductile moment resisting connection between a precast concrete column and a timber beam. 19(2)	111
Dean, J.A. see Smith, P.C.	
Dean, J.A.: Stewart W.G.: Carr, A.J. The seismic behaviour of plywood sheathed shearwalls. 19(1)	48
Degenkolb, H.J. see Steinbrugge, K.V.	
Dellow, G.D. see Van Disson, R.J.	
Dellow, G.D.: Read, S.A.L.: Begg, J.G.: Van Disson, R.J.: Perrin, N.D. Distribution of geological materials in Lower Hutt and Porirua, New Zealand: a component of a ground shaking hazard assessment. 25(4)	332
Denham, D.: Small, G.R. Strong motion data centre. 4(1)	15
Despeyroux, J. see Ferry Borges, J.	
Dickey, W.L. see Mayes, R.L.	

Douglas, B.M.: Maragakis, E.A.: Nath, B. Calculating static deformations from quick-release accelerograms. 23(4)	239
Douglas, J.S. Inangahua earthquake 1968 damage to State Highways. 1(2)	49
Inangahua earthquake 1968 damage to State Highways. 2(1)	47
Dowrick, D.J. A revision of attenuation relationships for Modified Mercalli intensity in New Zealand earthquakes. 24(3)	210
An earthquake catastrophe damage assessment model with particular reference to central New Zealand. 16(3)	213
Edgecumbe earthquake - some notes on its source, ground motions, and damage in relation to safety. 21(3)	198
Hysteresis loops for timber structures. 19(2)	143
Preliminary field observations of the Chilean earthquake of 3 March 1985. 18(2)	119
Seismic hazard estimates for the Auckland area, and their design and construction implications. 25(3)	211
Dowrick, D.J. see Smith, P.C.	
Dowrick, D.J.: Babor, J.: Cousins, W.J.: Skinner, R.I. Seismic isolation of a printing press in Wellington, New Zealand. 25(3)	161
Dowrick, D.J.: Rhoades, D.A. Damage ratios for domestic buildings in the 1987 Edgecumbe earthquake. 23(2)	137
Dowrick, D.J.: Smith, E.G.C. Surface wave magnitudes of some New Zealand earthquakes 1901-1988. 23(3)	198
Dowrick, D.J.: Smith, P.C. Timber sheathed walls for wind and earthquake resistance. 19(2)	123
Duckworth, W.J.H. Damage to railway track (<i>Inangahua earthquake 1968</i>). 2(1)	59
Inangahua earthquake damage on railways. 1(2)	12
Dutchison, D.L. see Hutchison, D.L. (Inelastic dynamic analysis of two industrial buildings.)	

E

Earthquake Engineering Research Laboratory, California Institute of Technology. Engineering features of the San Fernando earthquake. 6(1)	22
Eddy, D.C.A.: Hands, B.B.: Preston, D.S.G. Damage, operation and reinstatement of Post Office communications services (<i>Inangahua earthquake 1968</i>). 2(1)	73
Edmonds, F.D. see Blakeley, R.W.G.	
Edmonds, F.D. see Norton, J.A.	
Edmonds, F.D.: Carr, A.J.: Goldsmith, P.R.: North, P.J.: Wood, J.H.: Preston, R.L. NZNSEE discussion group on the seismic design of bridges. Section 4: Bridge foundations. 13(3)	248
Edwards, G.H. A message from the Standards Association of New Zealand. 2(3)	270
Edwards, W.P. Discussion - Seismic design of public buildings, by R.B. Shephard and O.A. Glogau. Vol 2(4). 3(2)	91
The structural check of high rise building design. 5(2)	52
Eiby, G.A. A history of anti-seismic measures in New Zealand. 8(4)	255
A philosophy of seismic zoning. 4(1)	171
Anomalous intensities due to the Korakonui earthquake, 5 December, 1976. 10(4)	167
Intensities: a strictly subjective view. 9(3)	181

Principal New Zealand earthquakes in 1978.	
12(1)	66
Seismic risks to linear structures. 11(3)	203
The Lake Coleridge earthquakes of 1946.	
23(2)	150
The Milford Sound earthquake of 1976 May 4.	
11(3)	191
Time and place - a reminiscence. 21(3)	204
Tsunami risk in New Zealand. 1(2)	98
Eiby, G.A. see Adams, R.D.	
Eiby, G. see Smith, E.G.C.	
Elder, D.McG. see Priestley, M.J.N.	
Ellison, B.K. Earthquake damage to roads and bridges, Madang, T.P.N.G. - November 1970. 4(2)	243
Elms, D.G. Reliability-based risk factors. 13(1)	3
1975 Seminar on NZS 4203. Seismic torsional effects on buildings. 9(1)	79
Elms, D.G. see Irvine, H.M.	
Elms, D.G.: Richards, R. Seismic design of gravity retaining walls. 12(2)	114
Elms, D.G.: Silvester, D. Cost effectiveness of code base shear requirements for reinforced concrete frame structures. 11(2)	85
Emkin, L.Z. see Nicoletti, J.P.	
Engelhardt, M.D. see Popov, E.P.	
Esteva, L. Earthquake engineering research and practice in Mexico after the 1985 earthquakes. 20(3)	159
Evans, D.S. Case studies: earthquake risk buildings	
1. Strengthening of State Trinity Centre, Christchurch. 16(2)	162
Evans, G.L. A field test for dynamic soil properties. 4(2)	176
Considerations for a "design" earthquake. 5(2)	47
Damage to civil engineering works and resulting civil defence problems (<i>Inangahua earthquake 1968</i>). 2(1)	39
Letter - Microtremor recording. 7(1)	49
Evans, W.V. Epoxy injection for crack repair. 3(4)	179
Evison, F.F. Earthquake prediction. 11(1)	2
Geophysics at the Victoria University of Wellington. 2(4)	470
Evison, R.D.: Mowat, A.F. The seismic design of industrial plants. 15(4)	171
Evison, R.J. see Priestley, M.J.N.	

F

Fairless, G.J. Berrill, J.B. Liquefaction during historic earthquakes in New Zealand. 17(4)	280
Fajfar, P. see Fischinger, M.	
Falconer, B.H. Agadir, Morocco, reconstruction work six years after the earthquake of February 1960. 1(2)	72
Initial appraisal of building damage in Inangahua (<i>Inangahua earthquake 1968</i>). 2(1)	77
Preliminary comment on damage to buildings in the Inangahua earthquake. 1(2)	61
Falconer, B.H.: Lensen, G.J. Immediate field damage reconnaissance (<i>Inangahua earthquake 1968</i>). 2(1)	27
Falconer, T.J. see Park, R.	
Fapuder, F. see Fischinger, M.	
Fellows, D. see Smith, E.G.C.	
Fenwick, R.C. Discussion and authors' reply: P-delta effects in medium height moment resisting steel frames under seismic loading. (23(4) p.305) 25(1)	70
Seismic resistant joints for reinforced concrete structures. 14(3)	145

Strength degradation of concrete beams under cyclic loading. 16(1)	25
Fenwick, R.C. see Allardice, N.W.	
Fenwick, R.C. see Megget, L.M.	
Fenwick, R.C.: Davidson, B.J. Comparative analyses of a multi-storey frame and wall using the current and draft loading codes. 22(4)	181
Fenwick, R.C.: Davidson, B.J.: Chung, B.T. P-delta actions in seismic resistant structures. 25(1)	56
Fenwick, R.C.: Fong, A. The behaviour of reinforced concrete beams under cyclic loading. 12(2)	158
Fenwick, R.C.: Hopkins, D.C. Discussion of paper 'Comparison of recent New Zealand United States seismic design provisions for reinforced concrete beam-column joints and test results for four units designed according to the New Zealand Code', by R. Park & J.R. Milburn. 17(1)	69
Fenwick, R.C.: Irvine, H.M. Reinforced concrete beam-column joints for seismic loading. 10(3)	121
Reinforced concrete beam-column joints for seismic loading. 10(4)	174
Ferry Borges, J.: Despeyroux, J.: Maeda, Y.: Mazilu, P.: Robinson, J.R. Brief review of modern earthquake engineering. 4(3)	397
Fischinger, M.: Fajfar, P.: Capuder, F. Earthquake resistance of the "SCT" large panel building system. 20(4)	281
Fisher, R.W. see Lanigan, A.G.	
Fisher, R.W. see McGuire, J.F.	
Fisher, R.W.: Lanigan, A.G.: Stockwell, M.J. NZNSEE discussion group on the seismic design of bridges. Section 7: Small bridges. 13(3)	269
Fong, A. see Fenwick, R.C.	
Fowler, M. The insurance industry's role in town planning. 23(3)	165
The role of local bodies (<i>Earthquake prediction seminar, 1977</i>). 11(1)	40
Fraser, I.A.N. A new draft code for seismic design of buildings in Indonesia. 16(3)	247
Fraser, I.A.N. see Hollings, J.P.	
Fraser, I.A.N. see Jury, R.D.	
Fu Yu-An. Errata - Sliding-vibrating response of elastic structures, Vol 21 No. 3 September 1988 pp 190-197. 22(1)	59
Sliding-vibrating responses of elastic structures. 21(3)	190
Earthquakes and earthquake engineering in China. 20(4)	275
Fujii, M. see Miyamoto, A.	
Fujita, T. Earthquake isolation technology for industrial facilities - research, development and applications. 18(3)	224

G

Gaerty, L. see Park, R.	
Garden, R.J.P. A general introduction to the seismic design problem. 2(3)	202
Letter - Tsunami risk. 1(2)	97
Standards Association of New Zealand Comments on chapter 8 of NZSS 1900. 5(2)	51
The task of earthquake resistance design - a divergent problem. 4(2)	331
Garrett, I.J. Case studies: earthquake risk buildings. 3. Hastings Boys' High School administration buildings, Hastings, Hawkes Bay, New Zealand. 16(1)	69

- Gates, J.H. Discussion - the Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE reconnaissance team (23(1), 1-78). 23(4) 322
- Gaull, B. Accelerograph recordings of the Musa earthquake 16 September, 1972. 9(2) 115
- Geng Shujiang see Li Zhiming.
- Gentry, S.C. see Bird, D.I.D.
- Gibson, J.A. see Bryant, A.H.
- Gill, J.L. Earthquake insurance. 2(1) 116
- Gill, W.D. see Hutchison, D.L.
- Gillies, A.G. see Norton, J.A.
- Gillies, A.G.: Shepherd, R. Prediction of post-elastic seismic response of structures by a mode superposition technique. 16(3) 222
- Gillon, N.R. see Shephard, R.B.
- Gilmour, R.M.: Hitchcock, H.C. Use of yield ratio response spectra to design yielding members for improving earthquake resistance of brittle structure. 4(2) 285
- Glogau, O.A. 1975 Seminar on NZS 4203. Code philosophy. 9(1) 43
- 1979 South Pacific Regional conference on earthquake engineering - closing address. 12(2) 174
- Confined columns. 3(4) 181
- Discussion - Seismic resistance of reinforced concrete masonry shear walls with high steel percentages, by M.J.N. Priestley (Vol 10(1)). 11(1) 70
- Discussion - Some aspects of shear wall design, by T. Paulay. 5(4) 156
- NZNSEE discussion group on reinforced concrete walls and diaphragms. Section G: Low rise reinforced concrete buildings of limited ductility. 13(2) 182
- Separation of non-structural components in buildings. 9(3) 141
- The design of public buildings. 5(4) 128
- The objective of the New Zealand Seismic Design Code. 5(4) 113
- The role of the International Association for Earthquake Engineering. 3(1) 1
- Glogau, O.A. see Clark, W.D.
- Glogau, O.A. see Shephard, R.B.
- Godden, W.G. see Williams, D.
- Goldsmith, P.R. see Edmonds, F.D.
- Goodsir, W.J. see Paulay, T.
- Goodsir, W.J.: Paulay, T.: Carr, A.J. A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures. 16(3) 185
- Grant-Taylor, T.L.: Hancox, G.T.: Lensen, G.J.: Oborn, L.E.: Thompson, B.N.: Suggate, R.P. Active earth deformation. 12(4) 334
- Grapes, R. Paleoseismicity of the Wellington fault. 21(1) 12
- Greenbank, L.R. see Robinson, W.H.
- Greig, J.S. The role of the international reinsurance broker. 22(4) 227
- Grigg, A.N. The local authority engineer and high earthquake risk buildings. 7(2) 81
- Gurley, C.R.: Nicholls, J.S.F. Earthquake strengthening of old masonry with reference to the Auckland Ferry Building. 15(4) 199
- H
- Haas, J.E.: Mileti, D.S. Consequences of earthquake prediction on other adjustments to earthquakes. 9(4) 187
- Haines, A.J. Prediction of seismic wave amplitudes using the phase-front parabolic approximation. 17(2) 145
- Hall, C.W. A new building control system - its nature and some implications. 23(3) 168
- Hamblett, S.G.: Yeatman, H.W. Restoration in the Inangahua area (*Inangahua earthquake 1968*). 2(1) 92
- Hancox, G.T. see Grant-Taylor, T.L.
- Hands, B.B. see Eddy, D.C.A.
- Hatrick, A.V. Dams and earthquakes in New Zealand. 11(2) 94
- Seismic risk and design criteria. 13(1) 14
- Hefford, R.T. see Skinner, R.I.
- Hefford, R.T. see Beck, J.L.
- Hefford, R.T. see Hodder, S.B.
- Hefford, R.T. see McVerry, G.H.
- Hefford, R.T. see Tyler, R.G.
- Hefford, R.T.: Randal, P.M.: Skinner, R.I.: Beck, J.L.: Tyler, R.G. The New Zealand strong motion earthquake recorder network. 12(3) 256
- Hefford, R.T.: Randal, P.M. Procedures for operating the New Zealand strong-motion accelerograph network. 16(1) 45
- Hefford, R.T.: Tyler, R.G.: Skinner, R.I. The MO2A strong-motion accelerograph. 13(4) 374
- Heine, A.J. see Skinner, R.I.
- Heine, A.J. see Tyler, R.G.
- Hellberg, M. The effect of earthquake prediction on earthquake insurance in New Zealand. 11(1) 19
- Heng, N.K. see Priestley, M.J.N.
- Hidehiko Abe see Yutaka Nakamura.
- Hideo Katsumata see Daisuke Kato.
- Hiroyuki Aoyama see Daisuke Kato.
- Hiroyuki Aoyama. A method for the evaluation of the seismic capacity of existing reinforced concrete buildings in Japan. 14(3) 105
- Outline of earthquake provisions in the recently revised Japanese building code. 14(2) 63
- Hisahiro Hiraishi. Evaluation of shear and flexural deformations of flexural type shear walls. 17(2) 135
- Hitchcock, E.H. A note about N.Z.S. 1900 building codes and changes. 2(3) 271
- Hitchcock, H.C. Earthquake symposium; Melbourne Australia 1969. 2(4) 490
- The 1968 Inangahua earthquake and electricity services. 1(2) 4
- Hitchcock, H.C. (contd) The 1968 Inangahua earthquake and electricity services. 2(1) 65
- The specification of earthquake resistance for electricity system equipment. 6(4) 178
- Hitchcock, H.C. see Blakeley, R.W.G.
- Hitchcock, H.C. see Gilmour, R.M.
- Hitchcock, H.C. see Mayes, R.L.
- Hitchcock, H.C. see Winthrop, D.A.
- Hodder, S. see Reyners, M.
- Hodder, S.B. Computer processing of New Zealand strong-motion accelerograms. 16(3) 234
- Hodder, S.B. Technical note: Strong motion record from Turangi, 5 March 1984. 17(2) 154
- Hodder, S.B. see Kelly, J.M.
- Hodder, S.B. see Skinner, R.I.
- Hodder, S.B.: Skinner, R.I.: Hefford, R.T.: Randal, P.M. Strong motion records of the Milford Sound earthquake 1976 May 4. 11(3) 184
- Hodge, W.C. Planning for disaster. 22(4) 239
- Hodge, W.C.: Macfarlane, M. Effect of the Edgecumbe earthquake on mechanical and process equipment at the Tasman Mill. 21(3) 161
- Hoerner, J.B. see Lord, J.

Hogue, T. May 24, 1968 at Inangahua Junction. 2(1)	37
Hojjat Adeli. Ghaenat (Iran) earthquake of November 14, 1979. 14(1)	34
Hollings, J. see Bertero, V.V.	
Hollings, J.P. A philosophy for improving old buildings to resist earthquakes. 7(2)	78
A reinforced concrete building in Wellington. 2(4)	420
Reinforced concrete seismic design. 2(3)	217
Report on the 7th European Conference on Earthquake Engineering. 15(3)	168
The economics of earthquake engineering. 4(2)	205
Hollings, J.P. see Bird, D.I.D.	
Hollings, J.P. see Jury, R.D.	
Hollings, J.P.: Fraser, I.A.N. Earthquake damage to three railway bridges 1968 Inangahua earthquake. 1(2)	22
Holloway, R.H.F. Civil defence aspects (<i>Earthquake Prediction Seminar, 1977</i>). 11(1)	12
Holmes, I.L. Masonry construction for earthquakes. 1(1)	Unpaged
Hopkins, D.C. Book review - Seismic design of reinforced concrete and masonry buildings. 25(4)	362
Earthquake fault movement and town planning. 20(2)	79
Research reduces risks. 23(2)	121
Hopkins, D.C. see Fenwick, R.C.	
Hopkins, D.C. see Park, R.	
Hopkins, D.C.: Bowman, I. Discussion - Conservation of historic buildings in a seismic zone: a New Zealand perspective, by I. Bowman. 22(1)	57
Hopkins, D.C.: Clark, W.D.: Matuschka, T.: Sinclair, J.C. The Philippines earthquake of July 16, 1990 Report on field visit by the NZNSEE Reconnaissance Team. 24(1)	3
Hopkins, D.C.: Massey, W.E.: Pollard, J.L. Architectural elements in earthquake, a review of design and construction practice in New Zealand. 18(1)	21
Hopkins, D.C.: McKay, G.R.: Shephard, R.B. Earthquake risk buildings - how they stand up in court. 24(2)	107
Hopkins, D.C.: Robertson, T.W. Earthquake risk buildings - lessons from experience. 14(2)	54
Hudson, D.E. Strong motion seismology. 10(3)	113
Hughes, D.K. Shear modulus Gs. 20(1)	63
Hughes, P.R. see Rynn, J.M.W.	
Huizing, J.B.S. NZNSEE discussion group on the seismic design of bridges. Introduction. 13(3)	226
Hunt, B.: Priestley, M.J.N. Seismic response of elevated water reservoirs. 15(2)	68
Hutchinson, D.L. Technical note - Testing of small rectangular hollow sections having welded connections. 14(4)	253
Hutchinson, G.L.: Navidi, A. Evaluation of earthquake response of low-rise structures using design codes and local specifications. 16(4)	331
Hutchison, D.L. Buildings: research and development needs. 15(2)	93
Hutchison, D.L. see Thurston, S.J.	
Hutchison, D.L.: Andrews, A.L.: Butcher, G.W.: Kolston, D. Draft revision of NZS 4203:1984: seismic provisions. 19(3)	158
Hutchison, D.L.: Gill, W.D. Case studies: earthquake risk buildings 1. New Plymouth Girls' High School structural strengthening and upgrading of the 1926 block. 17(1)	57
Hutchison, D.L.: Spurr, D.D. Inelastic dynamic analysis of two industrial buildings. 19(2)	83

Hutchison, D.L.: Van Geldermalsen, T.J. Optimum design of reinforced concrete shear walls. 17(3)	185
Hutchison, D.L.: Yong, P.M.F. Cyclic testing of a brick wall strengthened with a plaster coating of glass reinforced cement. 15(4)	185
Hutchison, G.L. see Chandler, A.M.	

I

Ichinose, T. Rocking motion of a slender elastic body on rigid floor. 19(1)	18
Shear reinforcement of reinforced concrete inelastic interior beam-column joints. 20(2)	116
Ichinose, T. see Suzuki, T.	
Inomata, S. Aspects of the FIP recommendations for design of aseismic prestressed concrete structures. 9(3)	159
Irvine, H.M. The centre of earthquake loading on tall buildings. 9(4)	195
The Veracruz earthquake of 28 August, 1973. 7(1)	2
Irvine, H.M. see Fenwick, R.C.	
Irvine, H.M.: Elms, D.G.: Buchanan, B.W. Discussion - Slenderness effects in earthquake resisting frames, by A.L. Andrews, Vol 10(3). 11(1)	71
Iwasaki, T.: Kawashima, K. Damage to civil engineering structures due to the near Izu-Oshima earthquake of January 14, 1978. 12(2)	127
Seismic analysis of a highway bridge considering soil-structure interaction effects. 12(4)	305
Iwasaki, Y.T. see Yoshikawa, S.	

J

Jacob, P. Earthquake and business interruption: a policy for survival? 22(4)	232
Jennings, D.N. Research requirements related to the design of seismic resistant highway bridges. 15(3)	154
Technical Note: Priorities for research requirements related to the design of seismic resistant highway bridges. 15(4)	220
Jennings, P.C. Earthquakes and tall buildings. 3(2)	51
Jennings, P.C. see Wood, J.H.	
Jhaveri, D.P. see Nicoletti, J.P.	
Johnstone, N.D.: Walpole, W.R. Behaviour of steel beam-column connections, made using bolted end plates. 15(2)	82
Jury, R.D.: Hollings, J.P.: Catley, T.J. Design of a curved 414m long continuous concrete railway bridge to resist earthquake motions. 22(1)	50
Jury, R.D.: Hollings, J.P.: Fraser, I.A.N. The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea. 15(3)	123

K

Kasai, K. see Popov, E.P.	
Katayama, T. Damage to lifeline systems in the city of Sendai caused by the 1978 Miyagiken-Oki earthquake. 12(1)	49
Kato, B. A design criteria of beam-to-column joint panels. 7(1)	14
Kawashima, K. see Iwasaki, T.	
Kean, R.J. see Adams, R.D.	
Kelly, J.M. see Aiken, I.D.	

Kelly, J.M.: Hodder, S.B. Experimental study of lead and elastomeric dampers for base isolation systems in laminated neoprene bearings. 15(2)	53
Kelly, J.M.: Skinner, R.I.: Heine, A.J. Mechanisms of energy absorption in special devices for use in earthquake resistant structures. 5(3)	63
Kelly, J.M.: Tsztoo, D.F. Earthquake simulation testing of a stepping frame with energy-absorbing devices. 10(4)	196
Kelly, T.E. Floor response of yielding structures. 11(4)	255
Some comments on reinforced concrete structures forming column hinge mechanisms. 10(4)	186
Uniaxial dynamic analysis of a six storey reinforced concrete framed structure. 10(1)	37
Kent, D.C.: Park, R. Inelastic behaviour of reinforced concrete members with cyclic loading. 4(1)	108
Kerswill, F.E. Comments on some earthquake damaged buildings in New Zealand. 2(4)	483
Key, D.E. The seismic performance of energy absorbing dampers in building structures. 17(1)	38
Kibblewhite, A.C. Geophysics at the University of Auckland. 2(4)	459
King, M.E. see Miyamoto, A.	
Kivell, B.T.: Moss, P.J.: Carr, A.J. Hysteretic modelling of moment-resisting nailed timber joints. 14(4)	233
Knight, R.L. Managing the New Zealand economy at a time of natural disaster. 23(3)	173
Kolston, D. 1975 Seminar on NZS 4203. Parts and portions of buildings. 9(1)	74
Book review - Reinforced Concrete Structures, by R.Park and T.Paulay. 8(4)	291
Notes on the New Zealand earthquake loading provisions. 8(2)	102
Kolston, D. see Hutchison, D.L.	
Kolston, D.: Buchanan, B.W. NZNSEE discussion group on reinforced concrete walls and diaphragms. Section D: Diaphragms in seismic resistant buildings. 13(2)	162
Krawinkler, H. Seismic code development for steel structures. 20(2)	127

L

Lai Cho Sim: Berrill, J.B. Shaking table tests on a model retaining wall. 12(2)	122
Lanigan, A.G. see Fisher, R.W.	
Lanigan, A.G.: Preston, R.L.: Fisher, R.W.: Stockwell, M.J. NZNSEE discussion group on the seismic design of bridges. Section 8: Structural and non structural details. 13(3)	274
Larkin, T.: Marsh, J. Two dimensional nonlinear site response analyses. 25(3)	222
Latter, J.H. Frequency of eruptions at New Zealand volcanoes. 18(1)	55
Latter, J.H. see Smith, E.G.C.	
Leadbeater, D.B. Refurbishing earthquake risk buildings in U.S.A. 14(2)	43
Lee, D.M.: Medland, I.C. Base isolation - an historical development, and the influence of higher mode responses. 11(4)	219
Estimation of base isolated structure responses. 11(4)	234
Lensen, G.J. Earth deformation and earthquake prediction. 2(4)	443
Earthquake forecasting, public policy and earthquake forecasting. 12(4)	328
Elastic and non-elastic surface deformation in New Zealand. 3(4)	131
Palmdale Bulge and its significance. 11(3)	193

Lensen, G.J. see Falconer, B.H.	
Lensen, G.J. see Grant-Taylor, T.L.	
Lensen, G.J.: Suggate, R.P. Geology (<i>Inangahua earthquake 1968</i>). 2(1)	19
Leslie, P.D. Second International Earthquake Conference April 6-10 1987, Los Angeles, California, USA. 21(2)	105
Leuchars, J.M. The use of sprayed concrete in the strengthening of earthquake risk buildings. 22(3)	167
Leuchars, J.M. see Cathie, M.C.	
Leuchars, J.M.: Scrivener, J.C. Masonry infill panels subjected to cyclic in-plane loading. 9(2)	122
Lewis, K.B. see Smith, E.G.C.	
Li Zhiming: Geng Shujiang. The energy dissipation effects of redundant members in silos under earthquakes. 20(4)	269
Lord, J. Real-time simulated earthquake motion of high rise structures. 3(2)	95
Lord, J.: Hoerner, J.B.: Zayed, M. Inelastic dynamic analysis of steel structures. 8(4)	273
Lord, J.: Zayed, M. Three dimensional elastic dynamic analysis of a 985 foot high free-standing communications tower. 8(3)	222
Lowry, M.A. see Adams, R.D.	

M

Macfarlane, M. see Hodge, W.C.	
Mackenzie, D.S. Maximum yield stress in reinforced concrete frames. 2(3)	267
Maeda, Y. see Ferry Borges, J.	
Mahin, S.A. see Bertero, V.V.	
Makoto Watabe see Yorihiro Ohsaki.	
Mander, J.B.: Priestley, M.J.N.: Park, R. Behaviour of ductile hollow reinforced concrete columns. 16(4)	273
Maragakis, E.A. see Douglas, B.M.	
Marks, P. Observations of the 1989 Loma Prieta earthquake. 23(4)	235
Marriott, E.W.T. Builders' field experiences (<i>Inangahua earthquake 1968</i>). 2(1)	96
Marsh, J. see Larkin, T.	
Marshall, Sir J. The political and legal effects (<i>Earthquake prediction seminar 1977</i>). 11(1)	5
Martin, G.R. Earthquake engineering research at the University of Auckland. 2(4)	474
Martin, G.R. see Taylor, P.W.	
Martin, G.R.: Taylor, P.W. Earthquake resistant design of cohesive earth slopes. 4(1)	51
Martinez-Romero, E. The behaviour, overview of damage and retrofit of steel buildings after the earthquakes of September 1985. 20(1)	30
Massey, W.E. see Hopkins, D.C.	
Matsushima, M. An overview of earthquake insurance in Japan. 22(4)	244
Matsuzaki, J. see Yoshikawa, S.	
Matthewson, C.D.: Davey, R.A. Design of an earthquake resisting building using precast concrete cross-braced panels and incorporating energy-absorbing devices. 12(4)	340
Matthewson, M.B.: Wood, J.H.: Berrill, J.B. NZNSEE discussion group on the seismic design of bridges. Section 9: Earth retaining structures. 13(3)	280
Matuschka, T. see Hopkins, D.C.	
Matuschka, T.: Berryman, K.R.O.: O'Leary, A.J.: McVerry, G.H.: Mulholland, W.M.: Skinner, R.I. New Zealand seismic hazard analysis. 18(4)	313
Mayes, R.L.: Hitchcock, H.C. Earthquake response of high voltage circuit breakers with non-linear force-deflection characteristics. 4(2)	301

- Mayes, R.L.: Mostaghel, N.M.: Clough, R.W.:
Dickey, W.L. Cyclic tests on masonry piers. 7(3) 105
- Mazilu, P. see Ferry Borges, J.
- McConnel, R.E. see Shepherd, R.
- McCue, K. Discussion - The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea, by Jury, R.D., Hollings, J.P. and Fraser, I.A.N. 17(4) 292
- McGuire, J.F.: Fisher, R.W.: Stanford, P.R.: North, P.J. NZNSEE discussion group on the seismic design of bridges. Section 12: Strengthening of bridges for seismic loads. 13(3) 308
- McKay, G.R. NZNSEE study group for the seismic design of steel structures. Section K Materials and workmanship. 18(4) 400
- McKay, G.R. see Campbell, M.D.
- McKay, G.R. see Hopkins, D.C.
- McKenzie, D.J. Behaviour of lifts - the Wellington earthquake November 1, 1968. 2(3) 278
- McKenzie, D.S. Editorial. 6(3) 95
- McKenzie, G.H.F. A critical look at the design of reinforced concrete for ductility. 2(3) 295
- An earthquake code for plumbing? 7(1) 50
- Assessment of earthquake response from modal analysis. 3(2) 89
- Discussion - Real-time simulated earthquake motion of high rise structures, by J. Lord (Vol 3(3), p.195). 3(4) 183
- Discussion - Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators, by M.J.N. Priestley and M.J. Stockwell (Vol 11(2)). 11(3) 195
- McKenzie, G.H.F. Seismic design of high rise buildings. 4(2) 222
- The need for structural registration. 3(1) 36
- The new draft concrete design code. 11(3) 181
- McLarin, M.W. see Priestley, M.J.N.
- McNamee, B. see Tanaka, H.
- McNaughton, D.J. see Sharpe, R.D.
- McVerry, G. see Sritharan, S.
- McVerry, G.H. Comparison of remote site and basement records as excitation of the Vogel Building. 17(1) 3
- Uncertainties in attenuation relations for New Zealand seismic hazard analysis. 19(1) 28
- McVerry, G.H. see Cousins, W.J.
- McVerry, G.H. see Matuschka, T.
- McVerry, G.H. see Skinner, R.I.
- McVerry, G.H. see Van Dissen, R.J.
- McVerry, G.H.: Hefford, R.T. Technical note: strong-motion instrumentation and records in the Wanganui earthquake swarm. 15(4) 216
- Mead, F.H. Eccentric beam to column junctions. 3(1) 24
- Mead, F.H. see Croad, R.N.
- Medland, I.C. see Lee, D.M.
- Megget, L.M. Analysis and design of a base-isolated reinforced concrete frame building. 11(4) 245
- Cyclic behaviour of exterior reinforced concrete beam-column joints. 7(1) 27
- Eighth world conference on earthquake engineering San Francisco, July 1984. 17(3) 215
- Review of the Conference on Large Earthquakes, Napier, 31 January to 3 February 1981. 14(1) 39
- Megget, L.M. see Blakeley, R.W.G.
- Megget, L.M.: Fenwick, R.C. Seismic behaviour of a reinforced concrete portal frame sustaining gravity loads. 22(1) 39
- Melchers, R.R. Discussion, and authors' reply: Vulnerability and seismic risk assessment of buildings following the 1989 Newcastle, Australia earthquake (24(2), p116). 24(4) 341
- Melville-Smith, R.W. see Parton, I.M.
- Menglin, L. The static substructure method for dynamic analysis of structures. 20(4) 264
- Mesley, R.C. see Nicoletti, J.P.
- Mezzi, M. see Parducci, A.
- Milburn, J.R. see Park, R.
- Mileti, D.S. see Haas, J.E.
- Mitchell, R.S. The police role (*Earthquake prediction seminar 1977*). 11(1) 33
- Mitchell, T.N. see Bryant, A.H.
- Miyamoto, A.: King, M.E.: Fujii, M. Non-linear dynamic analysis and design concepts for RC beams under impulsive loads. 22(2) 98
- Moinfar, A.A.: Naderzadeh, A. An immediate and preliminary report on the Manjil, Iran, earthquake of 20 June 1990. 23(4) 254
- Moore, T.E. Civil defence in Inangahua (*Inangahua earthquake 1968*). 2(1) 32
- Moss, P.J. Damage in Christchurch and Canterbury (*Inangahua earthquake 1968*). 2(1) 143
- Review of current earthquake engineering research in New Zealand. 20(2) 91
- The influence of earthquake fault-lines on town planning. 20(2) 84
- Moss, P.J. see Carr, A.J.
- Moss, P.J. see Cooke, N.
- Moss, P.J. see Kivell, B.T.
- Moss, P.J. see Tjondro, J.A.
- Moss, P.J.: Carr, A.J. Aspects of the analysis of frame-panel interaction. 4(1) 126
- The effects of large displacements on the earthquake response of tall concrete frame structures. 13(4) 317
- Moss, P.J.: Carr, A.J.: Buchanan, A.H. Seismic response of low-rise buildings. 19(3) 180
- Moss, P.J.: Carr, A.J.: Cooke, N.: Tan Fun Kwai. The influence of bridge geometry on the seismic behaviour of bridges on isolating bearings. 19(4) 255
- Moss, P.J.: Carr, A.J.: Pardeon, G.C. Inelastic analysis of the Imperial County Services Building. 16(2) 141
- Mostaghel, N.: Ahmadi, G. Construction of site dependent design spectra. 14(4) 244
- Mostaghel, N.M. see Mayes, R.L.
- Mouton, S.: Smits, F. Locating shallow faults and fracture zones using engineering geophysics 22(1) 19
- Mowat, A.F. see Evison, R.D.
- Mugurama, H. see Nishiyama, M.
- Muir, M.G. see Adams, R.D.
- Mulholland, W.M. see Matuschka, T.
- Munro, D.J. Case studies: earthquake risk buildings 3. Strengthening of James Smith Ltd Cuba Street, Wellington. 17(1) 67

N

- Naderzadeh, A. see Moinfar, A.A.
- Nath, B. see Douglas, B.M.
- Navidi, A. see Hutchinson, G.L.
- Nersesov, I. Earthquake prognostication in the Soviet Union. 3(3) 108
- New Zealand Police Department. Police action (law and order) (*Inangahua earthquake 1968*). 2(1) 45

Nicholas, C.J.A. NZNSEE study group for the seismic design of steel structures. Section G Connection design. 18(4)	360
Nicholls, J.S.F. see Gurley, C.R.	
Nicoletti, J.P.; Jhaveri, D.P.; Emkin, L.Z.; Mesley, R.C. Computer-aided structural analysis and design of the 37-storey Los Angeles Bonaventure Hotel. 12(3)	212
Nims, D.K. see Aiken, I.D.	
Nishiyama, M. Seismic design of prestressed concrete buildings. 23(4)	288
Nishiyama, M.; Mugurama, H.; Watanabe, F. Hysteretic restoring force characteristics of unbonded prestressed concrete structure under earthquake loads. 22(2)	112
North, P.J. see Bloxam, M.J.	
North, P.J. see Chapman, H.E.	
North, P.J. see Edmonds, F.D.	
North, P.J. see McGuire, J.F.	
North, P.J. see Park, R.	
North, P.J. see Shephard, R.B.	
Norton, J.A.; Gillies, A.G.; Edmonds, F.D. Recommendations for the seismic design of petrochemical plants. 15(2)	105

O

O'Brien, M.T. The implications of earthquake prediction for the New Zealand Electricity Department. 11(1)	37
O'Dea, Sir P. (<i>Earthquake prediction seminar 1977.</i>) Opening address. 11(1)	1
The roles of central and local government in pre-disaster planning. 11(1)	30
O'Donovan, C.J. 1975 Seminar on NZS 4203. Wind loading. 9(1)	84
O'Leary, A.J. Technical note: Advances in earthquake engineering. 13(3)	310
O'Leary, A.J. see Matuschka, T.	
Oborn, L.E. see Grant-Taylor, T.L.	
Ohi, K. see Takanashi, K.	
Ohkubo, M. An estimation method for seismic effects of reinforced concrete non-structural walls to structural frame members. 22(2)	90
Okamoto, T. see Suzuki, T.	
Otani, S. see Williams, R.L.	

P

Page, G.G. Letter to the editor. 7(2)	90
Page, W.J. see Armstrong, I.C.	
Pam Hoat Joen see Park, R.	
Pappin, J.W. Earthquake engineering in regions of low seismicity. 24(4)	317
Pappin, J.W. see Chandler, A.M.	
Pardeon, G.C. see Moss, P.J.	
Parducci, A.; Mezzi, M. Seismic isolation of bridges in Italy. 25(3)	193
Park, R. Evaluation of ductility of structures and structural assemblages from laboratory testing. 22(3)	155
Review of code developments for earthquake resistant design of concrete structures in New Zealand. 14(4)	177
NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section H Columns subjected to flexure and axial load. 10(2)	95

Theorisation of structural behaviour with a view to defining resistance and ultimate deformability. 6(2)	52
Park, R. see Andriano, T.	
Park, R. see Blakeley, R.W.G.	
Park, R. see Chapman, H.E.	
Park, R. see Cheung, P.C.	
Park, R. see Cormack, L.G.	
Park, R. see Kent, D.C.	
Park, R. see Mander, J.B.	
Park, R. see Priestley, M.J.N.	
Park, R. see Stanford, P.R.	
Park, R. see Tanaka, H.	
Park, R. see Thompson, K.J.	
Park, R. see Zahn, F.A.	
Park, R.; Andrews, A.L. NZNSEE study group for structures of limited ductility: 2. Design of building structures of limited ductility 2.1 Philosophy of design approach. 19(4)	286
Park, R.; Andrews, A.L.; Robinson, L.M.; Priestley, M.J.N.; Spring, K.C.F.; Buchanan, A.H.; Chapman, H.E.; Brunson, D.R.; Shephard, R.B. NZNSEE study group report: Structures of limited ductility. 19(4)	285
Park, R.; Bull, D.K. Behaviour of cast in situ reinforced concrete frames incorporating precast prestressed concrete beam shells subjected to seismic loading. 17(4)	223
Park, R.; Chapman, H.E.; Cormack, L.G.; North, P.J. NZ contributions to the international workshop on the seismic design and retrofitting of reinforced concrete bridges, Bormio, Italy, April 2-5, 1991. 24(2)	139
Park, R.; Dai Ruitong. A comparison of the behaviour of reinforced concrete beam-column joints designed for ductility and limited ductility. 21(4)	255
Park, R.; Gaerty, L.; Stevenson, E.C. Tests on an interior reinforced concrete beam-column joint. 14(2)	81
Park, R.; Hopkins, D.C. United States/New Zealand/ Japan/China collaborative research project on the seismic design of reinforced concrete beam-column-slab joints. 22(2)	122
Park, R.; Milburn, J.R. Comparison of recent New Zealand and United States seismic design provisions for reinforced concrete beam-column joints and test results from four units designed according to the New Zealand code. 16(1)	3
Park, R.; Paulay, T. Ductile reinforced concrete frames - some comments on the special provisions for seismic design of ACI 318-71 and on capacity design. 8(1)	70
Park, R.; Priestley, M.J.N. Code provisions for confining steel in potential plastic hinge regions of columns in seismic design. 13(1)	60
Park, R.; Priestley, M.J.N.; Falconer, T.J.; Pam Hoat Joen. Detailing of prestressed concrete piles for ductility. 17(4)	251
Park, R.; Robinson, L.M. NZNSEE study group for structures of limited ductility: 2. Design of building structures of limited ductility 2.2 Reinforced concrete. 19(4)	298
Park, R.; Thompson, K.J. Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading: Unit 1 test results. 6(4)	158
Progress report on cyclic load tests on prestressed partially prestressed and reinforced concrete interior beam-column assemblies. 8(1)	12

- Some recent research in New Zealand into aspects of seismic resistance of prestressed concrete frames. 9(3) 167
- Park, R.: Yeoh Sik Keong. Tests on structural concrete beam-column joints with intermediate column bars. 12(3) 189
- Park, R.J.T.: Priestley, M.J.N.: Walpole, W.R. The seismic performance of steel encased reinforced concrete bridge piles. 16(2) 123
- Parton, I.M.: Taylor, P.W. Analysis of microtremor records. 6(3) 96
- Parton, I.M.: Melville-Smith, R.W. Effect of soil properties on earthquake response. 4(1) 73
- Parton, I.M.: Taylor, P.W. Application of microtremor measurements to earthquake engineering. 6(4) 170
- Microtremor recording techniques. 6(2) 87
- Paterson, A.W.: Williams, R.L. The Taveuni earthquake Fiji on 17 November 1979. 13(2) 194
- Patton, R.N. NZNSEE study group for the seismic design of steel structures. Section B Analysis and design methods. 18(4) 329
- Paulay, T. A consideration of P-delta effects in ductile reinforced concrete frames. 11(3) 151
- An application of capacity design philosophy to gravity load dominated ductile reinforced concrete frames. 11(1) 50
- Developments in the design of ductile reinforced concrete frames. 12(1) 35
- Discussion: Capacity design of reinforced concrete frames for ductile earthquake performance, by I.C. Armstrong (5(4)). 6(1) 46
- Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames. 9(4) 205
- NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section F Shear strength requirements. 10(2) 80
- Section G Columns - evaluation of actions. 10(2) 85
- Seismic design in reinforced concrete: the state of the art in New Zealand. 21(3) 208
- Some aspects of shear wall design. 5(3) 89
- The shear strength of shear walls. 3(4) 148
- Paulay, T. see Binney, J.R.
- Paulay, T. see Cheung, P.C.
- Paulay, T. see Goodsir, W.J.
- Paulay, T. see Park, R.
- Paulay, T. see Row, D.G.
- Paulay, T. see Smith, W.D.
- Paulay, T.: Carr, A.J.: Tompkins, D.N. Response of ductile reinforced concrete frames located in Zone C. 13(3) 209
- Paulay, T.: Goodsir, W.J. The capacity design of reinforced concrete hybrid structures for multistorey buildings. 19(1) 1
- The ductility of structural walls. 18(3) 250
- Paulay, T.: Scarpas, A. The behaviour of exterior beam-column joints. 14(3) 131
- Paulay, T.: Williams, R.L. NZNSEE discussion group on reinforced concrete walls and diaphragms. Section B: The analysis and design of and the evaluation of design actions for reinforced concrete ductile shear wall structures. 13(2) 108
- Pear, A. McG. The role of Government Departments (*Mangahua earthquake 1968*). 2(1) 113
- Pedersen, I.S. see Rynn, J.M.W.
- Peek, R. see Berrill, J.B.
- Peek, R.: Berrill, J.B.: Davis, R.O. A seismicity model for New Zealand. 13(4) 355
- Pender, M.J. Earthquake-soil structure interaction, spring and dashpot models, and real soil behaviour. 16(4) 320
- Pender, M.J.: Robertson, T.W. Edgcomb earthquake: reconnaissance report. 20(3) 201
- Perrin, N.D. see Darby, D.J.
- Perrin, N.D. see Dellow, G.D.
- Perry, A.K. see Shephard, R.B.
- Pham, L.T. A base-isolation design using spherically-ended rollers and telescopic shock absorbers. 21(2) 135
- Pham, L.T. see Safi, B.F.
- Pollard, J.L. see Hopkins, D.C.
- Poole, R.A. NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section C Analysis for torsion employing provisions of NZS 4203:1974. 10(4) 219
- Poole, R.A.: Clendon, J.E. N.Z. Parliament Buildings seismic protection by base isolation. 25(3) 147
- Popov, E.P. On California structural steel seismic design. 20(1) 7
- Popov, E.P.: Kasai, K.: Engelhardt, M.D. Advances in design of eccentrically braced frames. 20(1) 22
- Porro, B. The role of reinsurance in earthquake risk assessment. 22(4) 219
- Press, F. The role of science and engineering in mitigating natural hazards. 18(2) 115
- Preston, D.S.G. see Eddy, D.C.A.
- Preston, R.L. see Edmonds, F.D.
- Preston, R.L. see Lanigan, A.G.
- Priestley, M.J.N. Discussion: Reinforced masonry shear walls: cyclic load tests in contraflexure, by S.J. Thurston and D.L. Hutchison (Vol 15(1)). 15(2) 97
- Ductility of confined concrete masonry shear walls. 15(1) 22
- Ductility of unconfined masonry shear walls. 14(1) 12
- Letter - Concrete filled tubular structures. 18(3) 285
- NZNSEE study group for structures of limited ductility: 2. Design of building structures of limited ductility 2.3 Masonry. 19(4) 304
- Seismic behaviour of unreinforced masonry walls. 18(2) 191
- Seismic design of masonry buildings - background to the draft masonry design code DZ4210. 13(4) 329
- Seismic design of masonry structures to the new provisional New Zealand Standard NZS 4230P. 18(1) 1
- Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. 10(1) 1
- Structural damage aspects of the April 22, 1991 Costa Rica earthquake. 25(1) 17
- Priestley, M.J.N. see Berrill, J.B.
- Priestley, M.J.N. see Blakeley, R.W.G.
- Priestley, M.J.N. see Brunson, D.R.
- Priestley, M.J.N. see Hunt, B.
- Priestley, M.J.N. see Mander, J.B.
- Priestley, M.J.N. see Park, R.
- Priestley, M.J.N. see Park, R.J.T.
- Priestley, M.J.N. see Wood, J.H.
- Priestley, M.J.N. see Zahn, F.A.
- Priestley, M.J.N.: Crosbie, R.L.: Carr, A.J. Seismic forces in base-isolated masonry structures. 10(2) 55
- Priestley, M.J.N.: Elder, D. McG. Cyclic loading tests of slender concrete masonry shear walls. 15(1) 3
- Priestley, M.J.N.: Evison, R.J.: Carr, A.J. Seismic response of structures free to rock on their foundations. 11(3) 141
- Priestley, M.J.N.: Park, R.: Heng, N.K. Influence of foundation compliance on the seismic response of bridge piers. 12(1) 22

- Priestley, M.J.N.: Seible, F. Performance assessment of damaged bridge bents after the Loma Prieta earthquake. 25(1) 44
- Research into seismic retrofit of reinforced concrete bridge columns. 25(3) 203
- Priestley, M.J.N.: Stanford, P.R.: Carr, A.J. NZNSEE discussion group on the seismic design of bridges. Section 11: Bridges requiring special studies. 13(3) 302
- Priestley, M.J.N.: Stockwell, M.J. Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators. 11(2) 110
- Priestley, M.J.N.: Thorby, P.N.: McLarin, M.W.: Bridgeman, D.O. Dynamic performance of brick masonry veneer panels. 12(4) 314
- Priestley, M.J.N.: Wood, J.H.: Davidson, B.J. Seismic design of storage tanks. 19(4) 272
- Q**
- Quigley, D. The role of the state as an insurer of last resort? (*Conference on information needs of the earthquake insurance industry, 1989.*) 23(3) 180
- Quinn, F. see Anderson, P.D.
- R**
- Randal, P.M. see Beck, J.L.
- Randal, P.M. see Hefford, R.T.
- Randal, P.M. see Hodder, S.B.
- Randel, P.M. see Hefford, R.T.
- Rands, G.F. Letter - Editorial comment on Building Services. 7(1) 49
- Read, S.A.L. see Dellow, G.D.
- Read, S.A.L. see Van Dissen, R.J.
- Reay, A.M.: Shephard, R. Steady state vibration tests of a six storey reinforced concrete building. 4(1) 94
- Reilly, W.I. see Smith, E.G.C.
- Reyners, M. Death of George Eiby. 25(1) 73
- Reyners, M.: Hodder, S. The Motu river earthquake of 8 March 1984. 18(1) 41
- Rhoades, D.A. Earthquake forecasting probability charts. 12(4) 324
- Rhoades, D.A. see Dowrick, D.J.
- Richards, R. see Elms, D.G.
- Rinne, J.E. A welcome to the Society. 1(1) Unpaged
- Discussion - New Zealand National Society for Earthquake Engineering discussion group on the seismic design of bridges, Vol 13(3). 14(2) 97
- Roberts, J.L. Central government and earthquake prediction. 11(1) 43
- Robertson, T.W. see Hopkins, D.C.
- Robertson, T.W. see Pender, M.J.
- Robinson, J.R. see Ferry Borges, J.
- Robinson, L.M. A preliminary analytic evaluation of the seismic response of structural walls failing in a shear mode. 19(3) 167
- Discussion - Seismic behaviour of unreinforced masonry walls, by M.J.N. Priestley, 18(2). 19(1) 65
- NZNSEE discussion group on reinforced concrete walls and diaphragms. Section C: Shear walls of limited ductility. 13(2) 144
- Robinson, L.M. see Park, R.
- Robinson, R. see Smith, E.G.C.
- Robinson, W.H. see Cousins, W.J.
- Robinson, W.H. see Skinner, R.I.
- Robinson, W.H. see Tyler, R.G.
- Robinson, W.H.: Greenbank, L.R. Properties of an extrusion energy absorber. 8(3) 187
- Robinson, W.H.: Tucker, A.G. A lead-rubber shear damper. 10(3) 151
- Test results for lead-rubber bearings for Wm. Clayton Building, Toe Toe bridge and Waiotukupuna bridge. 14(1) 21
- Robson, M. Role of the media in earthquake prediction. 11(1) 22
- Rodriguez, M. Strength and ductility in reinforced concrete frames designed with Mexican codes. 23(3) 184
- Rosenblueth, E. Decisions theory in earthquake engineering. 5(1) 1
- Roth, R.J., Jr. The information needs and obligations of the insurer. (*Conference on information needs of the earthquake insurance industry, 1989.*) 22(4) 199
- Row, D.G.: Paulay, T. Biaxial flexure and axial load interaction in short rectangular reinforced concrete columns. 6(3) 110
- Rutenberg, A. A consideration of the torsional response of building frames. 12(1) 11
- Rutledge, A.L. Earthquake damage at Edgumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake. 21(4) 247
- Errata - earthquake damage at Edgumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake on 2 March 1987, Vol.21 No. 4, December 1988, pp 247-254. 22(1) 60
- Rynn, J.M.W.: Brennan, E.: Hughes, P.R.: Pedersen, I.S.: Stuart, H.J. The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions. 25(2) 77
- S**
- Safi, B.F.: Pham, L.T.: Busby, M.J. High voltage circuit breaker supported on a base isolating tripod for earthquake protection. 22(3) 145
- Sakai, Y. see Takashi, K.
- Salt, P.E. Seismic site response. 7(2) 62
- Sanders, R.L.: Toynbee, G.A. Damage in Nelson and Murchison (*Inangahua earthquake 1968*). 2(1) 122
- Savarensky, F.F. Formidable echo. 3(3) 107
- Scarpas, A. see Paulay, T.
- Scott, B.J. see Smith, E.G.C.
- Scott, D.J. Earthquake insurance. 21(2) 116
- Scrivener, J.C. Reinforced masonry - seismic behaviour and design. 5(4) 143
- Scrivener, J.C. see Leuchars, J.M.
- Scrivener, J.C.: Williams, D. Behaviour of reinforced masonry shear walls under cyclic loading. 4(2) 316
- Seible, F. see Priestley, M.J.N.
- Sharpe, R.D. Support structure design for New Zealand Forest Products Ltd's No. 5 recovery boiler. 20(1) 2
- Sharpe, R.D. see Blakeley, R.W.G.
- Sharpe, R.D.: Binney, J.R.: McNaughton, D.J. The development of the design of the ANZ Head Office building, Lambton Quay, Wellington. 12(3) 204
- Sharpe, R.D.: Carr, A.J. The seismic response of inelastic structures. 8(3) 192
- Sharpe, R.D.: Skinner, R.I. The seismic design of an industrial chimney with rocking base. 16(2) 98
- Shephard, R.B. see Brunson, D.R.
- Shephard, R.B. see Hopkins, D.C.
- Shephard, R.B. see Park, R.
- Shephard, R.B.: Glogau, O.A. Seismic design of public buildings. 2(4) 391

- Shephard, R.B.: Wood, P.R.: Berrill, J.B.: Gillon, N.R.: North, P.J.: Perry, A.K.: Bent, D.P. The Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE Team. 23(1) 1
- Shepherd, R. Book review - Fundamentals of earthquake engineering, by N.M. Newmark and E. Rosenblueth. 5(1) 36
- Discussion - Assessment of earthquake response from modal analysis, by G.H.F. McKenzie. 3(2) 90
- Earthquake engineering research at the University of Canterbury. 2(2) 186
- Fifth World Conference on Earthquake Engineering - Rome, 25 June, 1973. 6(3) 128
- New Zealand earthquake engineering education. 2(3) 200
- Report on the 4th World Conference on Earthquake Engineering. 2(2) 176
- Some limitations of modal analysis in seismic design. 2(3) 284
- The June 28, 1991 Sierra Madre California earthquake. 24(4) 279
- The October 1, 1987 Whittier Narrows earthquake. 20(4) 255
- Shepherd, R. see Blakeley, R.W.G.
- Shepherd, R. see Croad, R.N.
- Shepherd, R. see Gillies, A.G.
- Shepherd, R. see Reay, A.M.
- Shepherd, R. see Walpole, W.R.
- Shepherd, R.: McConnel, R.E. An application of spectral techniques to inelastic seismic response predictions. 3(4) 173
- Shunsuke Otani. Emergency guideline for classification of risk levels of earthquake damaged reinforced concrete buildings. 21(4) 279
- Shunsuke Otani see Daisuke Kato.
- Shunsuke Sugano. Seismic strengthening of existing reinforced concrete buildings in Japan. 14(4) 209
- Sidwell, G.K. NZNSEE study group for the seismic design of steel structures. Section F Eccentrically braced frames. 18(4) 355
- Sidwell, G.K. see Smith, I.C.
- Silvester, D. see Elms, D.G.
- Sinclair, D. Aspects of high earthquake risk government buildings. 7(2) 85
- Sinclair, J.C. see Hopkins, D.C.
- Skinner, R.I. Conference report Base isolation of buildings. 16(1) 80
- Design lessons from recent destructive earthquakes. 4(2) 234
- Dynamic aspects of the Code for the design of earthquake resistant buildings. 9(1) 63
- Romanian earthquake, March 1977. 10(2) 106
- Seventh world conference on earthquake engineering September 8-13, 1980 Istanbul, Turkey. 13(4) 383
- Skinner, R.I. see Blakeley, R.W.G.
- Skinner, R.I. see Dowrick, D.J.
- Skinner, R.I. see Hefford, R.T.
- Skinner, R.I. see Hodder, S.B.
- Skinner, R.I. see Kelly, J.M.
- Skinner, R.I. see Matuschka, T.
- Skinner, R.I. see Sharpe, R.D.
- Skinner, R.I.: McVerry, G.H. Base isolation for increased earthquake resistance of buildings. 8(2) 93
- Skinner, R.I.: Stephenson, W.R.: Hefford, R.T. Strong-motion earthquake recording in New Zealand. 4(1) 31
- Skinner, R.I.: Taylor, R.G.: Heine, A.J.: Robinson, W.H. Hysteretic dampers for the protection of structures from earthquakes. 13(1) 22
- Skinner, R.I.: Tyler, R.G.: Hodder, S.B. Isolation of nuclear power plants from earthquake attack. 9(4) 199
- Small, G.R. see Denham, D.
- Smart, M. Public relations in restoration work (*Inangahua earthquake 1968*). 2(1) 99
- Smith, A.D. Damage between Westport and Greymouth (*Inangahua earthquake 1968*). 2(1) 135
- Smith, E.G.C. see Dowrick, D.J.
- Smith, E.G.C. see Taber, J.J.
- Smith, E.G.C.: Anderson, H.J.: Ansell, J.: Eiby, G.: Fellows, D.: Lewis, K.B.: Reilly, W.I.: Robinson, R.: Webb, T.H.: Wellman, H.W.: Workshop on the deformation of the Wellington Region. 22(1) 2
- Smith, E.G.C.: Scott, B.J.: Latter, J.H. The Waiotapu earthquake of 1983, December 14. 17(4) 272
- Smith, F.R. see Anderson, P.D.
- Smith, I.C. Our old buildings can be safe in earthquake. 12(4) 289
- Smith, I.C.: Sidwell, G.K. NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. Section E Beam flexure and hinge detailing in reinforced concrete ductile frames requiring beam sway mechanisms. 10(2) 72
- Smith, I.C.: Spring, K.C.F.: Sidwell, G.K. The design and construction of the Bank of New Zealand, Wellington, New Zealand. 8(2) 142
- Smith, P.C. see Dowrick, D.J.
- Smith, P.C.: Dowrick, D.J.: Dean, J.A. Horizontal timber diaphragms for wind and earthquake resistance. 19(2) 135
- Smith, W.D. A computer file of New Zealand earthquakes. 9(2) 136
- A tribute to George Eiby. 25(1) 73
- Earthquake hazard in New Zealand: some implications of the Edgecumbe Earthquake, March 1987. 23(3) 211
- How well is the insurance industry in New Zealand served by existing research and technology? 23(2) 134
- New Zealand earthquakes in 1989. 23(2) 97
- Pitfalls in the estimation of seismic hazard. 15(2) 77
- Principal New Zealand earthquakes in 1979. 13(1) 71
- Principal New Zealand earthquakes in 1980. 14(2) 96
- Principal New Zealand earthquakes in 1981. 15(1) 46
- Principal New Zealand earthquakes in 1982. 16(1) 59
- Principal New Zealand earthquakes in 1983. 17(1) 56
- Principal New Zealand earthquakes in 1985. 19(1) 64
- Principal New Zealand earthquakes in 1986. 20(1) 1
- Principal New Zealand earthquakes in 1987. 21(1) 1
- Principal New Zealand earthquakes in 1988. 22(1) 1
- Principal New Zealand earthquakes in 1990. 24(1) 1
- Principal earthquakes in New Zealand 1991. 25(1) 1
- Statistical estimates of the likelihood of earthquake shaking throughout New Zealand. 9(4) 213
- The importance of surface waves in strong ground-motion. 10(4) 170
- Smith, W.D.: Berryman, K.R. Revised estimates of earthquake hazard in New Zealand. 16(4) 259
- Smith, W.D.: Paulay, T. Book review - Basic concepts of seismic codes. Published by IAEE, Vol 1, 1980. 14(3) 173
- Sozen, M.A. Lateral drift of reinforced concrete structures subjected to strong ground motion. 16(2) 107
- Spring, K.C.F. NZNSEE study group for structures of limited ductility: 2. Design of building structures of limited ductility 2.4 Structural steel. 19(4) 305
- Spring, K.C.F. see Butterworth, J.W.
- Spring, K.C.F. see Park, R.
- Spring, K.C.F. see Smith, I.C.

Spring, K.C.F.: Butcher, G.W. NZNSEE study group for the seismic design of steel structures. Section A Introduction and Philosophy. 18(4)	323
Spurr, D.D. An economic solution for stabilising a slender arch roof. 19(2)	93
Spurr, D.D. see Hutchison, D.L.	
Sriharan, S. see Van Dissen, R.J.	
Sriharan, S.: McVerry, G.H. Microzone effects in the Hutt Valley in records from a strong-motion accelerography array. 25(4)	246
Stanford, P.R. see McGuire, J.F.	
Stanford, P.R. see Priestley, M.J.N.	
Stanford, P.R.: Cormack, L.G.: Park, R. NZNSEE discussion group on the seismic design of bridges. Section 1: Design philosophy. 13(3)	229
Steinbrugge, K.V. Earthquake disaster response planning: an engineering overview. 8(2)	114
Loss estimation for insurance purposes: United States practices. 22(4)	193
Steinbrugge, K.V.: Degenkolb, H.J. A note on the earthquake performance of reinforced concrete shear walls. 2(2)	193
Stephenson, W.R. Cellular normal modes of alluvium response. 8(4)	245
Discussion - The importance of surface waves in strong ground motion, by W.D. Smith. Vol 10(4). 11(2)	131
Earthquake induced resonant motion of alluvium. 7(3)	144
Engineering seismology. 2(1)	24
Normal modes of a "cylindrical valley" of alluvium. 22(2)	76
Observation of a directed resonance in soil driven by transverse rock motion. 22(2)	81
Seismic microzoning in New Zealand. 4(1)	43
Strategies for strong motion earthquake recording in New Zealand. 12(3)	269
Stephenson, W.R. see Skinner, R.I.	
Stephenson, W.R. see Van Dissen, R.J.	
Stephenson, W.R.: Barker, P.R. Evaluation of sediment properties in the Lower Hutt and Porirua areas by means of cone and seismic cone penetration tests. 25(4)	265
Steven, L. The Earthquake and War Damage Commission - a look forward (and a look back). 25(1)	52
Stevens, G.R. Historical aspects of the 1855 earthquake. 22(1)	30
Stevenson, E.C. see Park, R.	
Stewart, W.G. see Dean, J.A.	
Stirrat, A.G. The effects of earthquake prediction on the Ministry of Works and Development. 11(1)	35
Stockwell, M.J. see Blakeley, R.W.G.	
Stockwell, M.J. see Fisher, R.W.	
Stockwell, M.J. see Lanigan, A.G.	
Stockwell, M.J. see Priestley, M.J.N.	
Strachan, C.M. Mitigation of danger to property (<i>Earthquake prediction seminar, 1977</i>). 11(1)	26
Stuart, H.J. see Rynn, J.M.W.	
Study Group, NZNSEE. A revision of the Modified Mercalli Seismic Intensity Scale. 25(4)	345
Suggate, R.P. Seismotectonics and earthquake risk macrozoning in New Zealand. 12(1)	3
Suggate, R.P. see Grant-Taylor, T.L.	
Suggate, R.P. see Lensen, G.J.	
Suzuki, T.: Takiguchi, K.: Ichinose, T.: Okamoto, T. Effects of hoop reinforcement in steel and reinforced concrete composite sections. 17(3)	198
Sydenham, P.H. Review of geophysical strain measurement. 4(1)	2

Syun'itiro Omote: Yorihiro Ohsaki: Toshihiro Kakimi: Tokihoko Matsuda. Japanese practice for estimating the expected maximum earthquake force at a nuclear power plant site. 13(1)	37
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----

T

Taber, J.J. see Van Dissen, R.J.	
Taber, J.J.: Smith, E.G.C. Frequency dependent amplification of weak ground motions in Porirua and Lower Hutt, New Zealand. 25(4)	303
Tai, M. see Yoshikawa, S.	
Takanashi, K.: Ohi, K.: Sakai, Y. Shake table tests of an industrial building. 20(1)	53
Takiguchi, K. see Suzuki, T.	
Tan Fun Kwai see Cooke, N.	
Tan Fun Kwai see Moss, P.J.	
Tan Pham. Earthquake reconnaissance report. Damage to the power generation and transmission facilities in the Loma Prieta earthquake of 17 October 1989. 25(1)	3
Tanaka, H.: Park, R. Prediction of the ultimate longitudinal compressive concrete strain at hoop fracture using energy considerations. 20(4)	290
Tanaka, H.: Park, R.: McNamee, B. Anchorage of transverse reinforcement in rectangular reinforced concrete columns in seismic design. 18(2)	165
Tatsuo Nishiki. Present status of the Railway Technical Research Institute and seismic research and designing in the Japanese National Railways. 3(4)	143
Taylor, J.M. Case studies: earthquake risk buildings. 3. Cashfields shopping Centre: Christchurch. 16(2)	172
Taylor, P.W. 1975 Seminar on NZS 4203. Code provisions related to soils and foundations. 9(1)	68
Strong-motion earthquake records. 7(2)	53
Taylor, P.W. see Allardice, N.W.	
Taylor, P.W. see Martin, G.R.	
Taylor, P.W. see Parton, I.M.	
Taylor, P.W.: Martin, G.R. Seminar on geotechnical aspects of earthquake engineering. 3(3)	120
Taylor, P.W.: Williams, R.L. Foundations for capacity designed structures. 12(2)	101
Taylor, R.G. NZNSEE discussion group on reinforced concrete walls and diaphragms. Section A: Introduction to and aims in the design of earthquake resisting shear wall structures. 13(2)	103
Taylor, R.G. see Skinner, R.I.	
Thompson, B.N. see Grant-Taylor, T.L.	
Thompson, G. The economic issues (<i>Earthquake prediction seminar 1977</i>). 11(1)	8
Thompson, K.J. see Park, R.	
Thompson, K.J.: Park, R. Stress-strain model for grade 275 reinforcing steel with cyclic loading. 11(2)	101
Stress-strain model for prestressing steel with cyclic loading. 11(4)	209
Thompson, P. Capital discovery place Te aho a Maui Wellington. 23(2)	159
Thompson, R.M. Building research in the School of Architecture. 2(4)	472
Thorby, P.N. see Priestley, M.J.N.	
Thurston, S.J. Cyclic load testing of three haunched reinforced concrete beam-column assemblies. 15(3)	141
Technical note: Local buckling of universal beam flanges. 15(2)	96
Thurston, S.J. see Bryant, A.H.	
Thurston, S.J.: Charleson, A.W. Cyclic testing of a haunched reinforced concrete beam. 12(1)	67

Thurston, S.J.: Hutchison, D.L. Reinforced masonry shear walls: cyclic load tests in contraflexure. 15(1)	27
Tjondro, J.A.: Moss, P.J.: Carr, A.J. P-delta effects in medium height moment resisting steel frames under seismic loading. 23(4)	305
Tokihoko Matsuda see Syun'itiro Omote.	
Tompkins, D.N. see Paulay, T.	
Toomath, S.W. Architectural detailing for earthquake movement. 1(1)	Unpaged
Toomath, W. Some aspects of the strengthening of earthquake risk buildings. 12(4)	287
Toshihiko Hisada. Structural examination of high rise buildings in Japan. 1(1).	Unpaged
Toshiro Kakimi see Syun'itiro Omote.	
Toynbee, G.A. see Sanders, R.L.	
Tracey, W.J. A simulated earthquake test of a timber house. 2(3)	289
Tsztoo, D.F. see Kelly, J.M.	
Tucker, A.G. see Robinson, W.H.	
Tyler, R.G. A tenacious base isolation system using round steel bars. 11(4)	273
Damping in sliding structures by means of PTFE sliding joints. 10(3)	139
Dynamic tests on laminated rubber bearings. 10(3)	143
Tyler, R.G. Dynamic tests on PTFE sliding layers under earthquake conditions. 10(3)	129
Further notes on a steel energy-absorbing element for braced frameworks. 18(3)	270
Preliminary tests on an energy absorbing element for braced structures under earthquake loading. 16(3)	201
Rubber bearings in base-isolated structures: a summary paper. 24(3)	251
Tapered steel energy dissipators for earthquake resistant structures. 11(4)	282
Test on a brake lining damper for structures. 18(3)	280
Tyler, R.G. see Hefford, R.T.	
Tyler, R.G. see Skinner, R.I.	
Tyler, R.G.: Baguley, D.E. Uses for earthquake detectors. 14(3)	160
Tyler, R.G.: Hefford, R.T. Technical note: A note on the Hutt Valley strong-motion microzone network. 15(3)	160
Tyler, R.G.: Heine, A.J. Tests on an axially loaded steel energy absorber. 17(1)	47
Tyler, R.G.: Robinson, W.H. High-strain tests on lead-rubber bearings for earthquake loadings. 17(2)	90

U

Upritchard, G.J. The seismic restraint of building services - a code of practice. 12(2)	94
---------------------------------------------------------------------------------------------------	----

V

van Brink, D.J. Time for a break - let's have an earthquake. 21(4)	237
Van Disen, R.J. see Dellow, G.D.	
Van Disen, R.J.: Taber, J.J.: Stephenson, W.R.: Sritharan, S.: Read, S.A.L.: McVerry, G.H.: Dellow, G.D.: Barker, P.R. Earthquake ground shaking hazard assessment for the Lower Hutt and Porirua areas, New Zealand. 25(4)	286
Van Geldermalsen, T.J. see Hutchison, D.L.	
Velkov, M. Aseismic design of 24 storey hotel "De Luxe", Skopje. 8(2)	128

Vere-Jones, D. The statistical estimation of earthquake risk. 6(3)	122
What are the main uncertainties in estimating earthquake risk? 16(1)	39
Walcott, R.I. New Zealand earthquakes and plate tectonic theory. 12(2)	87

W

Walpole, W.R. NZNSEE study group for the seismic design of steel structures. Section E Centrally braced frames. 18(4)	351
Section H Beam-column joints. 18(4)	369
Walpole, W.R. see Johnstone, N.D.	
Walpole, W.R. see Park, R.J.T.	
Walpole, W.R.: Butcher, G.W. NZNSEE study group for the seismic design of steel structures. Section C Beam design. 18(4)	337
Walpole, W.R.: Shepherd, R. Post-elastic seismic response of a reinforced concrete frame. 1(2)	102
Watanabe, F. see Nishiyama, M.	
Webb, T.H. see Smith, E.G.C.	
Webster, J. Seismic considerations in the design of cryogenic pressure vessels. 16(4)	306
Wellman, H.W. see Smith, E.G.C.	
Whitman, R.V. Liquefaction - the state of knowledge. 20(3)	145
Wilby, G.K. Case studies: earthquake risk buildings. 2. Redevelopment of the Normal School Cranmer Square, Christchurch. 16(2)	165
Williams, D. Discussion - Seismic resistance of brick masonry walls, by M.J.N. Priestley and D.O. Bridgeman. 8(3)	238
Williams, D. see Scrivener, J.C.	
Williams, D.: Godden, W.G. Multidirectional seismic response of a curved highway bridge model. 9(2)	97
Williams, J.E. A builder's observations and views at Greymouth (<i>Inangahua earthquake 1968</i>). 2(1)	148
Williams, R. Seismic design of timber structures study group review, March 1986. 19(1)	40
Williams, R.L. A procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height. 8(4)	260
Discussion - Design of Shear walls for seismic resistance, by I.C. Armstrong (Vol10(1)). 10(3)	159
Discussion - Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames, by T. Paulay (Vol 9(4)). 10(3)	160
Williams, R.L. see Allardice, N.W.	
Williams, R.L. see Campbell, M.D.	
Williams, R.L. see Paulay, T.	
Williams, R.L. see Taylor, P.W.	
Williams, R.L.: Otani, S. Discussion - A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures, by Goodsir, W.J., Paulay, T. and Carr, A.J. 16(4)	345
Williamson, K.E. Codes for seismic design of prestressed concrete. 2(3)	277
Prestressed concrete seismic design. 2(3)	251
Williamson, K.E.: Andrews, A.L. Design loads - readers' views. 3(3)	126
Wilson, J.B. Notes on bridges and earthquakes. 1(2)	92
Winthrop, D.A.: Hitchcock, H.C. Earthquake design of structures with brittle members and heavy artificial damping by the method of direct integration. 4(2)	294
Wood, B.J. see Boardman, P.J.	
Wood, J.H. Earthquake-induced pressures on a rigid wall structure. 8(3)	175

- Wood, J.H. see Blakeley, R.W.G.
 Wood, J.H. see Edmonds, F.D.
 Wood, J.H. see Matthewson, M.B.
 Wood, J.H. see Priestley, M.J.N.
 Wood, J.H.: Blakeley, R.W.G.: Priestley, M.J.N.
 NZNSEE discussion group on the seismic design of
 bridges. Section 10: Dynamic analysis. 13(3) 294
 Wood, J.H.: Jennings, P.C. Damage to freeway
 structures in the San Fernando earthquake. 4(3) 347
 Wood, P.R. Finding Wellington's faults. 22(1) 36
 Wood, P.R. see Shephard, R.B.

Y

- Yeatman, H.W. Survey and approach to restoration
 of damaged buildings. 2(1) 85
 Yeatman, H.W. see Hamblett, S.G.
 Yeoh Sik Keong see Park, R.
 Yong, P.M.F. see Hutchison, D.L.
 Yorihiro Ohsaki see Syun'itiro Omote.
 Yorihiro Ohsaki: Makoto Watabe: Yutaka Matsushima.
 Experimental study on five-story full size apartment
 house of reinforced concrete walled frames. 4(3) 377
 Yoshikawa, S.: Iwasaki, Y.T.: Tai, M.: Matsuzaki, J.
 Ground motion near causative fault of Kita-Tango
 earthquake of 1927. 13(1) 49
 Yoshikazu Kitagawa: Yutaka Matsushima. Evaluation
 of dynamic ground characteristics and seismic
 microzoning. 17(1) 15
 Yuji Ishiyama. Motions of rigid bodies and criteria
 for overturning by earthquake excitations. 17(1) 24
 Yutaka Matsushima see Yorihiro Ohsaki.
 Yutaka Matsushima see Yoshikazu Kitagawa.
 Yutaka Nakamura: Hidehiko Abe. Estimation of
 seismic motion and damage to structures
 for new bullet trains. 17(2) 121

Z

- Zahn, F.A.: Chapman, H.E.: Park, R.:
 Priestley, M.J.N. Development of design
 procedures for the flexural strength and
 ductility of reinforced concrete bridge
 columns. 19(3) 200
 Zahn, F.A.: Park, R.: Priestley, M.J.N. The use
 of Grade 380 steel for transverse confirming
 reinforcement in columns. 20(2) 99
 Zayed, M. see Lord, J.

SUBJECT INDEX

AUSTRALIA/NEW ZEALAND STANDARDS *see* Standards

BASE ISOLATION *see* Earthquake Engineering

BOOK REVIEWS

5(1)	36
7(3)	147
8(4)	291
14(3)	173
21(2)	154
21(4)	288
24(4)	344
25(4)	362

BRIDGES

Damage to freeway structures in the San Fernando earthquake. Wood, J.H.: Jennings, P.C. 4(3)	347
Design of a curved 414m long continuous concrete railway bridge to resist earthquake motions. Jury, R.D.: Hollings, J.P.: Catley, T.J. 22(1)	50
Development of design procedures for the flexural strength and ductility of reinforced concrete bridge columns. Zahn, F.A.: Chapman, H.E.: Park, R.: Priestley, M.J.N. 19(3)	200
Discussion - Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators, by M.J.N. Priestley and M.J. Stockwell (Vol 11(2)). McKenzie, G.H.F. 11(3)	195
Dynamic tests on PTFE sliding layers under earthquake conditions. Tyler, R.G. 10(3)	129
Earthquake damage to roads and bridges, Madang, T.P.N.G. - November 1970. Ellison, B.K. 4(2)	243
Earthquake damage to three railway bridges 1968 Inangahua earthquake. Hollings, J.P.: Fraser, I.A.N. 1(2)	22
Earthquake simulation testing of a stepping frame with energy-absorbing devices. Kelly, J.M.: Tsztsoo, D.F. 10(4)	196
Further comments on seismic design loads for bridges. Berrill, J.B.: Priestley, M.J.N.: Peek, R. 14(1)	3
Hysteretic dampers for the protection of structures from earthquakes. Skinner, R.I.: Taylor, R.G.: Heine, A.J.: Robinson, W.H. 13(1)	22
Inangahua earthquake 1968 damage to state highways. Douglas, J.S. 2(1)	47
Influence of foundation compliance on the seismic response of bridge piers. Priestley, M.J.N.: Park, R.: Heng, N.K. 12(1)	22
Multidirectional seismic response of a curved highway bridge model. Williams, D.: Godden, W.G. 9(2)	97
Notes on bridges and earthquakes. Wilson, J.B. 1(2)	92
NZ contributions to the international workshop on the seismic design and retrofitting of reinforced concrete bridges, Bormio, Italy, April 2-5, 1991. Park, R.: Chapman, H.E.: Cormack, L.G.: North, P.J. 24(2)	139
NZNSSEE discussion group on the seismic design of bridges: <i>see</i> NZNSSEE.	
NZNSSEE study group for structures of limited ductility	

- report (and <i>see</i> NZNSSEE). Park, R.: Andrews, A.L.: Robinson, L.M.: Priestley, M.J.N.: Spring, K.C.F.: Buchanan, A.H.: Chapman, H.E.: Brunson, D.R.: Shephard, R.B.: Soesianawati, M.T. 19(4)	285
NZNSSEE study group for structures of limited ductility (and <i>see</i> NZNSSEE): 3. Design of bridge substructures of limited ductility. Chapman, H.E. 19(4)	319
NZNSSEE study group for the seismic design of steel structures (and <i>see</i> NZNSSEE): Section A Introduction and Philosophy. Spring, K.C.F.: Butcher, G.W. 18(4)	323
Section B Analysis and design methods. Patton, R.N. 18(4)	329
Section C Beam design. Walpole, W.R.: Butcher, G.W. 18(4)	337
Research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(3)	154
Seismic analysis of a highway bridge considering soil-structure interaction effects. Iwasaki, T.: Kawashima, K. 12(4)	305
Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators. Priestley, M.J.N.: Stockwell, M.J. 11(2)	110
Seismic hazard analysis and design loads. Berrill, J.B. 18(2)	139
Seismic isolation of bridges in Italy. Parducci, A.: Mezzi, M. 25(3)	193
Structural damage aspects of the April 22, 1991 Costa Rica earthquake. Priestley, M.J.N. 25(1)	17
Tauranga Harbour crossing, Stella Passage bridge - seismic design. Bloxam, M.J.: North, P.J. 23(3)	220
Technical Note: Priorities for research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(4)	220
The influence of bridge geometry on the seismic behaviour of bridges on isolating bearings. Moss, P.J.: Carr, A.J.: Cooke, N.: Tan Fun Kwai. 19(4)	255
The influence of non-geometric factors on the seismic behaviour of bridges on isolating bearings. Cooke, N.: Carr, A.J.: Moss, P.J.: Tan Fun Kwai. 19(4)	263
The new draft concrete design code. McKenzie, G.H.F. 11(3)	181
The seismic performance of steel encased reinforced concrete bridge piles. Park, R.J.T.: Priestley, M.J.N.: Walpole, W.R. 16(2)	123

BUILDING CONSTRUCTION

3rd US-Japan workshop on the improvement of building structural design and construction practices, July 29-August 1 1988 Tokyo, Japan. Billings, I.J. 22(2)	73
Architectural elements in earthquake, a review of design and construction practice in New Zealand. Hopkins, D.C.: Massey, W.E.: Pollard, J.L. 18(1)	21
Design of seismic resistant prestressed concrete structures. Andrews, A.L. 9(3)	175
Editorial. McKenzie, D.S. 6(3)	95
Full-strength butt welds of reinforcing bars by the pressure-gas process. Armstrong, I.C. 4(2)	270
Seismic hazard estimates for the Auckland area, and their design and construction implications. Dowrick, D.J. 25(3)	211

- The design and construction of the Bank of New Zealand, Wellington, New Zealand. Smith, I.C.:
Spring, K.C.F.: Sidwell, G.K. 8(2) 142

BUILDINGS (includes public buildings, high-rise buildings, multistorey buildings)

- 1975 Seminar on NZS 4203 (and *see* Standards).
Dynamic aspects of the Code for the design of earthquake resistant buildings Skinner, R.I. 9(1) 63
Parts and portions of buildings. Kolston, D. 9(1) 74
Seismic torsional effects on buildings.
Elms, D.G. 9(1) 79
Wind loading. O'Donovan, C.J. 9(1) 84
3rd US-Japan workshop on the improvement of building structural design and construction practices, July 29-August 1 1988 Tokyo, Japan. Billings, I.J. 22(2) 73
A method for the evaluation of the seismic capacity of existing reinforced concrete buildings in Japan. Hiroyuki Aoyama. 14(3) 105
A procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height (and *see* Errata). Williams, R.L. 8(4) 260
A reinforced concrete building in Wellington. Hollings, J.P. 2(4) 420
Aspects of high earthquake risk government buildings. Sinclair, D. 7(2) 85
Assessment of seismic performance characteristics of reinforced concrete buildings constructed between 1936 and 1975. Brunson, D.R.: Priestley, M.J.N. 17(3) 163
Book review - Seismic design of reinforced concrete and masonry buildings.
Hopkins, D.C. 25(4) 362
Building configuration: the architecture of seismic design. Arnold, C. 17(2) 83
Buildings: research and development needs.
Hutchison, D.L. 15(2) 93
Conservation of historic buildings in a seismic zone: a New Zealand perspective. Bowman, I. 21(2) 128
Damage *see* Earthquake Damage
Discussion - Conservation of historic buildings in a seismic zone: a New Zealand perspective, by I. Bowman. Hopkins, D.C.: Bowman, I. 22(1) 57
Discussion - Real time simulated earthquake motion of high rise structures, by J. Lord (Vol. 3(3), p. 195). McKenzie, G.H.F. 3(4) 183
Discussion - Seismic design of public buildings, by R.B. Shephard and O.A. Glogau. Vol 2(4).
Edwards, W.P. 3(2) 91
Discussion - Seismic response of low-rise buildings, by Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3). Clifton, G.C. 20(1) 66
Earthquake risk buildings *see* Earthquake Risk Buildings
Earthquakes and tall buildings. Jennings, P.C. 3(2) 51
NZNSEE study group for structures of limited ductility: *see* NZNSEE.
NZNSEE study group for the seismic design of steel structures: *see* NZNSEE.
Our old buildings can be safe in earthquake.
Smith, I.C. 12(4) 289
Real-time simulated earthquake motion of high rise structures. Lord, J. 3(2) 95
Second Conference on Tall Buildings in Seismic Regions. May 16 and 17, 1991, Los Angeles, California, U.S.A. Brunson, D.R. 24(3) 207
Seismic design of high rise buildings.
McKenzie, G.H.F. 4(2) 222

- Seismic design of masonry buildings - background to the draft masonry design code DZ4210.
Priestley, M.J.N. 13(4) 329
Seismic design of prestressed concrete buildings.
Nishiyama, M. 23(4) 288
Seismic design of public buildings. Shephard, R.B.:
Glogau, O.A. 2(4) 391
Seismic response of low-rise buildings. Moss, P.J.:
Carr, A.J.: Buchanan, A.H. 19(3) 180
Structural examination of high rise buildings in Japan. Toshihiko Hisada. 1(1) Unpaged
The capacity design of reinforced concrete hybrid structures for multistorey buildings. Paulay, T.:
Goodsir, W.J. 19(1) 1
The centre of earthquake loading on tall buildings.
Irvine, H.M. 9(4) 195
The December 28, 1989 Newcastle, Australia Earthquake. Brunson, D.R. 23(2) 102
The design of public buildings. Glogau, O.A. 5(4) 128
The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea.
Jury, R.D.: Hollings, J.P.: Fraser, I.A.N. 15(3) 123
The development of the design of the ANZ Head Office building, Lambton Quay, Wellington.
Sharpe, R.D.: Binney, J.R.: McNaughton, D.J. 12(3) 204
The structural check of high rise building design.
Edwards, W.P. 5(2) 52

BUILDING CONTENTS (includes building services, non-structural elements)

- A review of the new code provisions for separation of elements and buildings. Blakeley, R.W.G. 7(3) 130
An earthquake code for plumbing?
McKenzie, G.H.F. 7(1) 50
Architectural detailing for earthquake movement.
Toomath, S.W. 1(1) Unpaged
Architectural elements in earthquake, a review of design and construction practice in New Zealand. Hopkins, D.C.: Massey, W.E.:
Pollard, J.L. 18(1) 21
Behaviour of lifts - the Wellington earthquake
November 1, 1968. McKenzie, D.J. 2(3) 278
Editorial. McKenzie, D.S. 6(3) 95
Earthquake insurance. Scott, D.J. 21(2) 116
Letter - Editorial comment on Building Services.
Rands, G.F. 7(1) 49
Letter - Editorial comment on Building Services.
Blackwell, F.M. 7(1) 50
Separation of non-structural components in buildings. Glogau, O.A. 9(3) 141
Suspended ceilings: the seismic hazard and damage problem and some practical solutions.
Clarke, W.D.: Glogau, O.A. 12(4) 292
The seismic restraint of building services - a code of practice. Upritchard, G.J. 12(2) 94
The seismic response of nonstructural elements in buildings. Arnold, C. 24(4) 306

CIVIL DEFENCE

- A history of anti-seismic measures in New Zealand. Eiby, G.A. 8(4) 255
Three papers on Civil Defence in the Northern Region:
Civil defence at No. 1 sub-region level, Auckland Regional Authority. Blenkinsopp, J.G. 2(4) 357
Civil defence at the local body level.
Armstrong, F.N. 2(4) 371
Ministry of Civil Defence - Northern Region.
Bourke, L.P. 2(4) 347

Emergency guideline for classification of risk levels of earthquake damaged reinforced concrete buildings. Shunsuke Otani. 21(4)	279
<i>Inangahua earthquake 1968</i> (and <i>see</i> Earthquakes in New Zealand):	
Civil defence in Inangahua. Moore, T.E. 2(1)	32
Damage to civil engineering works and resulting civil defence problems. Evans, G.L. 2(1)	39
Police action (law and order). New Zealand Police Department. 2(1)	45
The role of Government Departments. Peart, A.McG. 2(1)	113
Seminar on the social and economic effects of earthquake prediction (and <i>see</i> Earthquake Prediction): Civil defence aspects. Holloway, R.H.F. 11(1)	12

CODES *see* Standards

CONFERENCES AND SEMINARS

1975 seminar on NZS 4203 <i>see</i> Standards	
1979 South Pacific Regional conference on earthquake engineering - closing address. Glogau, O.A. 12(2)	174
- conference report. Andrews, A.L. 12(2)	175
3rd US-Japan workshop on the improvement of building structural design and construction practices, July 29-August 1 1988 Tokyo, Japan. Billings, I.J. 22(2)	73
Information needs of the earthquake insurance industry (and <i>see</i> Insurance). Workshop reports. 23(4)	284
Conference report Base isolation of buildings. Skinner, R.I. 16(1)	80
Discussion of papers presented at the New Zealand national conference on earthquake engineering held at Wellington on 18th, 19th and 20th May 1971 and published in the Bulletin. 5(1)	14
Earthquake symposium; Melbourne Australia 1969. Hitchcock, H.C. 2(4)	490
Fifth world conference on earthquake engineering - Rome, 25-29 June, 1973. Shepherd, R. 6(3)	128
Eighth world conference on earthquake engineering San Francisco, July 1984. Meggett, L.M. 17(3)	215
International Association for Earthquake Engineering. 21(4)	290
Masonry construction for earthquakes. (Report on the International Conference on Masonry Structural Systems, 1967.) Holmes, I.L. 1(1)	Unpaged
Papers presented at the 7th European Conference on Earthquake Engineering, Athens, Sept. 20-25, 1982. 15(4)	222
Report on the 4th World Conference on Earthquake Engineering. Shepherd, R. 2(2)	176
Report on the 7th European Conference on Earthquake Engineering. Hollings, J.P. 15(3)	168
Report on the second (1978) microzonation conference. Bentley, R.J. 12(1)	72
Review of the Conference on Large Earthquakes, Napier, 31 January to 3 February 1981. Megget, L.M. 14(1)	39
Second Conference on Tall Buildings in Seismic Regions. May 16 and 17, 1991, Los Angeles, California, U.S.A. Brunson, D.R. 24(3)	207
Second International Earthquake Conference April 6-10 1987, Los Angeles, California, USA. Leslie, P.D. 21(2)	105
Seminar on the social and economic effects of earthquake prediction (<i>see</i> Earthquake Prediction). 11(1)	1

Seminar on geotechnical aspects of earthquake engineering. Taylor, P.W.: Martin, G.R. 3(3)	120
Seventh world conference on earthquake engineering September 8-13, 1980 Istanbul, Turkey. Skinner, R.I. 13(4)	383
South Pacific Regional Conference on Earthquake Engineering 13-15 May, 1975. Blakeley, R.W.G. 8(2)	170
Symposium on the Inangahua earthquake (and <i>see</i> Earthquakes in New Zealand). 2(2)	154

DISASTER RELIEF (includes disaster assistance)

Civil defence in Inangahua. Moore, T.E. 2(1)	32
Earthquake disaster response planning: an engineering overview. Steinbrugge, K.V. 8(2)	114
Federal disaster assistance in the United States of America. 3(1)	27
Hurricane Camille: a month of federal action. 3(1)	38
Managing the New Zealand economy at a time of natural disaster. Knight, R.L. 23(3)	173

DISCUSSION

Discussion - A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures, by Goodsir, W.J., Paulay, T. and Carr, A.J. Williams, R.L.: Otani, S. 16(4)	345
Discussion - Assessment of earthquake response from modal analysis, by G.H.F. McKenzie. Shepherd, R. 3(2)	90
Discussion - Classification of high earthquake risk buildings Draft Code of Practice, 2 March 1972. Bluck, B.C. 5(3)	108
Discussion - Conservation of historic buildings in a seismic zone: a New Zealand perspective, by I. Bowman. Hopkins, D.C.: Bowman, I. 22(1)	57
Discussion - NZNSEE discussion group on the seismic design of bridges, Vol 13(3). Rinne, J.E. 14(2)	97
Discussion - Real-time simulated earthquake motion of high rise structures, by J. Lord (Vol 3(3), p.195). McKenzie, G.H.F. 3(4)	183
Discussion - Seismic behaviour of unreinforced masonry walls, by M.J.N. Priestley, 18(2). Robinson, L.M. 19(1)	65
Discussion - Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators, by M.J.N. Priestley and M.J. Stockwell (Vol 11(2)). McKenzie, G.H.F. 11(3)	195
Discussion - Seismic resistance of brick masonry walls, by M.J.N. Priestley and D.O. Bridgeman. Williams, D. 8(3)	238
Discussion - Seismic resistance of reinforced concrete masonry shear walls with high steel percentages, by M.J.N. Priestley (Vol 10(1)). Glogau, O.A. 11(1)	70
Discussion - Seismic response of low-rise buildings, by Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3) Clifton, G.C. 20(1)	66
Discussion - Slenderness effects in earthquake resisting frames, by A.L. Andrews, Vol 10(3). Irvine, H.M.: Elms, D.G.: Buchanan, B.W. 11(1)	71
Discussion - Some aspects of shear wall design, by T. Paulay. Glogau, O.A. 5(4)	156
Discussion - The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea, by Jury, R.D., Hollings, J.P. and Fraser, I.A.N. McCue, K. 17(4)	292

Discussion - The importance of surface waves in strong ground motion, by W.D. Smith. Vol 10(4). Stephenson, W.R. 11(2)	131
Discussion - the Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE reconnaissance team. (23(1), 1-78) Gates, J.H. 23(4)	322
Discussion and authors' reply: P-delta effects in medium height moment resisting steel frames under seismic loading. (23(4) p.305) Fenwick, R.C. 25(1)	70
Discussion of paper 'Comparison of recent New Zealand United States seismic design provisions for reinforced concrete beam-column joints and test results for four units designed according to the New Zealand Code', by R Park & J R Milburn. Fenwick, R.C.: Hopkins, D.C. 17(1)	69
Discussion of papers presented at the New Zealand national conference on earthquake engineering held at Wellington on 18th, 19th and 20th May 1971 and published in the Bulletin. 5(1)	14
Discussion: Capacity design of reinforced concrete frames for ductile earthquake performance, by I.C. Armstrong (5(4)). Paulay, T. 6(1)	46
Letter - Lateral flexibility and seismic deflection estimates How good is good enough? by A.L. Andrews (Vol 1(1)). Crookes, S.I. 1(2)	21
Letter - Microtremor recording. Evans, G.L. 7(1)	49
Standards Association of New Zealand Comments on chapter 8 of NZSS 1900. Garden, R.J.P. 5(2)	51
 EARTHQUAKE DAMAGE (includes restoration, reconstruction): also see Reconnaissance Reports	
Agadir, Morocco, reconstruction work six years after the earthquake of February 1960. Falconer, B.H. 1(2)	72
An earthquake catastrophe damage assessment model with particular reference to central New Zealand. Dowrick, D.J. 16(3)	213
Aspects of the FIP recommendations for design of aseismic prestressed concrete structures. Inomata, S. 9(3)	159
Comments on some earthquake damaged buildings in New Zealand. Kerswill, F.E. 2(4)	483
<i>Damage caused by the Inangahua earthquake 1968 see Earthquakes in New Zealand.</i>	
Damage ratios for domestic buildings in the 1987 Edgecumbe earthquake. Dowrick, D.J.: Rhoades, D.A. 23(2)	137
Damage to civil engineering structures due to the near Izu-Oshima earthquake of January 14, 1978. Iwasaki, T.: Kawashima, K. 12(2)	127
Damage to freeway structures in the San Fernando earthquake. Wood, J.H.: Jennings, P.C. 4(3)	347
Damage to lifeline systems in the city of Sendai caused by the 1978 Miyagiken-Oki earthquake. Katayama, T. 12(1)	49
Design lessons from recent destructive earthquakes. Skinner, R.I. 4(2)	234
Earthquake damage at Edgecumbe and Kwarau Electricorp substations in the Bay of Plenty earthquake (and see Errata). Rutledge, A.L. 21(4)	247
Earthquake damage at Sendai, June, 1978. 11(2)	129
Earthquake damage to roads and bridges, Madang, T.P.N.G. - November 1970. Ellison, B.K. 4(2)	243
Earthquake disaster response planning: an engineering overview. Steinbrugge, K.V. 8(2)	114
Earthquake hazard in New Zealand: some implications of the Edgecumbe Earthquake, March 1987. Smith, W.D. 23(3)	211
Earthquake reconnaissance report. Damage to the power generation and transmission facilities in the Loma Prieta earthquake of 17 October 1989. Tan Pham. 25(1)	3
Earthquakes and tall buildings. Jennings, P.C. 3(2)	51
Edgecumbe earthquake: reconnaissance report. Pender, M.J.: Robertson, T.W. 20(3)	201
Effect of the Edgecumbe earthquake on mechanical and process equipment at the Tasman Mill. Hodge, W.C.: Macfarlane, M. 21(3)	161
Emergency guideline for classification of risk levels of earthquake damaged reinforced concrete buildings. Shunsuke Otani. 21(4)	279
Engineering features of the San Fernando earthquake. Earthquake Engineering Research Laboratory, California Institute of Technology. 6(1)	22
Epoxy injection for crack repair. Evans, W.V. 3(4)	179
Errata - earthquake damage at Edgecumbe and Kwarau Electricorp substations in the Bay of Plenty earthquake on 2 March 1987, Vol.21 No. 4, December 1988, pp 247-254. Rutledge, A.L. 22(1)	60
Estimation of seismic motion and damage to structures for new bullet trains. Yutaka Nakamura: Hidehiko Abe. 17(2)	121
Federal disaster assistance in the United States of America. 3(1)	27
Methodology for the assessment of the damage cost resulting from a large earthquake in the vicinity of Wellington. Birss, G.R. 18(3)	215
NZNSEE discussion group on reinforced concrete walls and diaphragms (and see NZNSEE): Section G: Low rise reinforced concrete buildings of limited ductility. Glogau, O.A. 13(2)	182
Performance assessment of damaged bridge bents after the Loma Prieta earthquake. Priestley, M.J.N.: Seible, F. 25(1)	44
Photographs of building damage at Sendai, Japan in the Miyagiken-Oki earthquake of June 12, 1978. 12(1)	59
Preliminary field observations of the Chilean earthquake of 3 March 1985. Dowrick, D.J. 18(2)	119
Response of a reinforced concrete shear wall structure during the 1972 Managua earthquake. Bertero, V.V.: Mahin, S.A.: Hollings, J. 7(3)	95
Romanian earthquake, March 1977. Skinner, R.I. 10(2)	106
Separation of non-structural components in buildings. Glogau, O.A. 9(3)	141
Structural damage aspects of the April 22, 1991 Costa Rica earthquake. Priestley, M.J.N. 25(1)	17
Suspended ceilings: the seismic hazard and damage problem and some practical solutions. Clarke, W.D.: Glogau, O.A. 12(4)	292
Te Aroha earthquake, 9 January 1972 Adams, R.D.: Muir, M.G.: Kean, R.J. 5(2)	54
The behaviour, overview of damage and retrofit of steel buildings after the earthquakes of September 1985. Martinez-Romero, E. 20(1)	30
The December 28, 1989 Newcastle, Australia Earthquake. Brunson, D.R. 23(2)	102
The Dunedin earthquake, 9 April 1974, Part 1: seismological studies. Adams, R.D.: Kean, R.J. 7(3)	115
Part 2: local effects. Bishop, D.G. 7(3)	123
The economics of earthquake engineering. Hollings, J.P. 4(2)	205
The June 28, 1991 Sierra Madre California earthquake. Shepherd, R. 24(4)	279

The Lake Coleridge earthquakes of 1946. Eiby, G. 23(2)	150
The Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE Team. Shephard, R.B.: Wood, P.R.: Berrill, J.B.: Gillon, N.R.: North, P.J.: Perry, A.K.: Bent, D.P. 23(1)	1
The Peruvian earthquake disaster. 3(2)	84
The September 1985 Mexico Earthquake: Preliminary report of the New Zealand reconnaissance team. 18(4)	291
The September 1985 Mexico earthquakes: final report of the New Zealand reconnaissance team 1988. 21(1)	3
The statistical estimation of earthquake risk. Vere-Jones, D. 6(3)	122
The Taveuni earthquake Fiji on 17 November 1979. Paterson, A.W.: Williams, R.L. 13(2)	194
The Tonga earthquake of 23 June, 1977 - some initial observations. Campbell, M.D.: McKay, G.R.: Williams, R.L. 10(4)	208
The Veracruz earthquake of 28 August, 1973. Irvine, H.M. 7(1)	2

EARTHQUAKE ENGINEERING

1979 South Pacific Regional Conference on earthquake engineering - conference report. Andrews, A.L. 12(2)	175
A base-isolation design using spherically-ended rollers and telescopic shock absorbers. Pham, L.T. 21(2)	135
A consideration of the torsional response of building frames. Rutenberg, A. 12(1)	11
A general introduction to the seismic design problem. Garden, R.J.P. 2(3)	202
A history of anti-seismic measures in New Zealand. Eiby, G.A. 8(4)	255
A lead-rubber shear damper. Robinson, W.H.: Tucker, A.G. 10(3)	151
A simplified earthquake resistant design method for base isolated multistorey structures. Andriono, T.: Carr, A.J. 24(3)	238
A study of the earthquake resistance of domestic break pressure tanks. Blackwell, F.N. 12(2)	168
A tenacious base isolation system using round steel bars. Tyler, R.G. 11(4)	273
Advances in design of eccentrically braced frames. Popov, E.P.: Kasai, K.: Engelhardt, M.D. 20(1)	22
Analysis and design of a base-isolated reinforced concrete frame building. Megget, L.M. 11(4)	245
Application of microtremor measurements to earthquake engineering. Parton, I.M.: Taylor, P.W. 6(4)	170
Base isolation - an historical development, and the influence of higher mode responses. Lee, D.M.: Medland, I.C. 11(4)	219
Base isolation for increased earthquake resistance of buildings. Skinner, R.I.: McVerry, G.H. 8(2)	93
Book review - Earthquake engineering, by R.L. Wiegel. 3(4)	182
Book review - Fundamentals of earthquake engineering, by N.M. Newmark and E Rosenblueth. Shepherd, R. 5(1)	36
Brief review of modern earthquake engineering. Ferry Borges, J.: Despeyroux, J.: Maeda, Y.: Mazilu, P.: Robinson, J.R. 4(3)	397
Buildings: research and development needs. Hutchison, D.L. 15(2)	93
Case studies: <i>see</i> Earthquake Risk Buildings	
Column strength requirements in multi-storey seismic frames. Blaikie, E.L. 22(3)	135
Comparative study of four passive energy dissipation systems. Aiken, I.D.: Nims, D.K.: Kelly, J.M. 25(3)	175
Conference report Base isolation of buildings. Skinner, R.I. 16(1)	80
Correspondence on base isolated structures. 12(4)	362
Cyclic load testing of two refined reinforced concrete beam-column joints. Blakeley, R.W.G.: Edmonds, F.D.: Megget, L.M.: Wood, J.H. 12(3)	238
Cyclic testing of a haunched reinforced concrete beam. Thurston, S.J.: Charleson, A.W. 12(1)	67
Decisions theory in earthquake engineering. Rosenblueth, E. 5(1)	1
Design of a curved 414m long continuous concrete railway bridge to resist earthquake motions. Jury, R.D.: Hollings, J.P.: Catley, T.J. 22(1)	50
Design of an earthquake resisting building using precast concrete cross-braced panels and incorporating energy-absorbing devices. Matthewson, C.D.: Davey, R.A. 12(4)	340
Developments in the design of ductile reinforced concrete frames. Paulay, T. 12(1)	35
Diagonal beam reinforcing for ductile frames. Buchanan, A.H. 12(4)	346
Discussion - Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators, by M.J.N. Priestley and M.J. Stockwell (Vol 11(2)). McKenzie, G.H.F. 11(3)	195
Discussion of papers presented at the New Zealand national conference on earthquake engineering held at Wellington on 18th, 19th and 20th May 1971 and published in the Bulletin. 5(1)	14
Dynamic tests on laminated rubber bearings. Tyler, R.G. 10(3)	143
Earthquake engineering in regions of low seismicity. Pappin, J.W. 24(4)	317
Earthquake engineering research and practice in Mexico after the 1985 earthquakes. Esteva, L. 20(3)	159
Earthquake engineering research at the Papua and New Guinea Institute of Higher Technical Education. Boyce, W.H. 2(4)	482
Earthquake engineering research at the University of Auckland. Martin, G.R. 2(4)	474
Earthquake engineering research at the University of Canterbury. Shepherd, R. 2(2)	186
Earthquake isolation technology for industrial facilities - research, development and applications. Fujita, T. 18(3)	224
Earthquake resistance of the "SCT" large panel building system. Fischinger, M.: Fajfar, P.: Capuder, F. 20(4)	281
Earthquake simulation testing of a stepping frame with energy-absorbing devices. Kelly, J.M.: Tsztoo, D.F. 10(4)	196
Earthquakes and earthquake engineering in China. Fu Yuan. 20(4)	275
Editorial - Macro zoning for earthquake engineering. Andrews, A.L. 5(3)	ii
Eighth world conference on earthquake engineering San Francisco, July 1984 Meggett, L.M. 17(3)	215
Elastic soil-structure interaction. Carr, A.J.: Moss, P.J. 4(2)	258
Engineering features of the San Fernando earthquake. Earthquake Engineering Research Laboratory, California Institute of Technology. 6(1)	22
Estimation of base isolated structure responses. Lee, D.M.: Medland, I.C. 11(4)	234

- Experimental study of lead and elastomeric dampers for base isolation systems in laminated neoprene bearings. Kelly, J.M.: Hodder, S.B. 15(2) 53
- Fifth World Conference on Earthquake Engineering - Rome, 25-29 June, 1973.
Shepherd, R. 6(3) 128
- Foundations for capacity designed structures.
Taylor, P.W.: Williams, R.L. 12(2) 101
- Further notes on a steel energy-absorbing element for braced frameworks. Tyler, R.G. 18(3) 270
- High voltage circuit breaker supported on a base isolating tripod for earthquake protection.
Safi, B.F.: Pham, L.T.: Busby, M.J. 22(3) 145
- High-strain tests on lead-rubber bearings for earthquake loadings. Tyler, R.G.:
Robinson, W.H. 17(2) 90
- Hysteretic dampers for the protection of structures from earthquakes. Skinner, R.I.: Taylor, R.G.:
Heine, A.J.: Robinson, W.H. 13(1) 22
- Influence of foundation compliance on the seismic response of bridge piers. Priestley, M.J.N.:
Park, R.: Heng, N.K. 12(1) 22
- Isolation of nuclear power plants from earthquake attack. Skinner, R.I.: Tyler, R.G.:
Hodder, S.B. 9(4) 199
- Lateral drift of reinforced concrete structures subjected to strong ground motion.
Sozen, M.A. 16(2) 107
- Mechanical strain gauge measurements at Te Marau. Darby, D.J.: Perrin, N.D. 19(2) 104
- Mechanisms of energy absorption in special devices for use in earthquake resistant structures. Kelly, J.M.: Skinner, R.I.:
Heine, A.J. 5(3) 63
- N.Z. Parliament Buildings seismic protection by base isolation. Poole, R.A.: Clendon, J.E. 25(3) 147
- New Zealand earthquake engineering education.
Shepherd, R. 2(3) 200
- NZNSSE discussion group on the seismic design of bridges (and *see* NZNSSE). Section 6: Mechanical energy dissipating devices. Blakeley, R.W.G.:
Cormack, L.G.: Stockwell, M.J. 13(3) 264
- On California structural steel seismic design.
Popov, E.P. 20(1) 7
- Preliminary tests on an energy absorbing element for braced structures under earthquake loading.
Tyler, R.G. 16(3) 201
- Properties of an extrusion energy absorber.
Robinson, W.H.: Greenbank, L.R. 8(3) 187
- Recent developments in devices for seismic isolation. Cousins, W.J.: Robinson, W.H.:
McVerry, G.H. 25(3) 167
- Recommendations for the design and construction of base isolated structures. Blakeley, R.W.G.:
Charleson, A.W.: Hitchcock, H.C.: Megget, L.M.:
Priestley, M.J.N.: Sharpe, R.D.: Skinner, R.I. 12(2) 136
- Reconnaissance field investigation of the Landers earthquake (Ms 7.5) of June 28, 1992, San Bernardino County, California, USA.
Berryman, K. 25(3) 230
- Reduction and distribution of lateral seismic inertia forces on base isolated multistorey structures. Andriono, T.: Carr, A.J. 24(3) 225
- Reinforced concrete beam-column joints for seismic loading. Fenwick, R.C.: Irvine, H.M. 10(4) 174
- Report on the 4th World Conference on Earthquake Engineering. Shepherd, R. 2(2) 176
- Report on the 7th European Conference on Earthquake Engineering. Hollings, J.P. 15(3) 168
- Research into seismic retrofit of reinforced concrete bridge columns. Priestley, M.J.N.:
Seible, F. 25(3) 203
- Review of current earthquake engineering research in New Zealand. Moss, P.J. 20(2) 91
- Rubber bearings in base-isolated structures: a summary paper. Tyler, R.G. 24(3) 251
- Seismic design of gravity retaining walls.
Elms, D.G.: Richards, R. 12(2) 114
- Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators.
Priestley, M.J.N.: Stockwell, M.J. 11(2) 110
- Seismic forces in base-isolated masonry structures.
Priestley, M.J.N.: Crosbie, R.L.: Carr, A.J. 10(2) 55
- Seismic hazard estimates for the Auckland area, and their design and construction implications.
Dowrick, D.J. 25(3) 211
- Seismic isolation of a printing press in Wellington, New Zealand. Dowrick, D.J.: Babor, J.:
Cousins, W.J.: Skinner, R.I. 25(3) 161
- Seismic isolation of bridges in Italy.
Parducci, A.: Mezzi, M. 25(3) 193
- Seminar on geotechnical aspects of earthquake engineering. Taylor, P.W.: Martin, G.R. 3(3) 120
- Seventh world conference on earthquake engineering September 8-13, 1980 Istanbul, Turkey. Skinner, R.I. 13(4) 383
- South Pacific Regional Conference on Earthquake Engineering 13-15 May, 1975. Blakeley, R.W.G. 8(2) 170
- Tapered steel energy dissipators for earthquake resistant structures. Tyler, R.G. 11(4) 282
- Technical note: Advances in earthquake engineering. O'Leary, A.J. 13(3) 310
- Technical note: Local buckling of universal beam flanges. Thurston, S.J. 15(2) 96
- Test on a brake lining damper for structures.
Tyler, R.G. 18(3) 280
- Test results for lead-rubber bearings for Wm. Clayton Building, Toe Toe bridge and Waitokupuna bridge. Robinson, W.H.:
Tucker, A.G. 14(1) 21
- Tests on an axially loaded steel energy absorber.
Tyler, R.G.: Heine, A.J. 17(1) 47
- Tests on structural concrete beam-column joints with intermediate column bars. Park, R.:
Yeoh Sik Keong. 12(3) 189
- The behaviour of exterior beam-column joints.
Paulay, T.: Scarpas, A. 14(3) 131
- The economics of earthquake engineering.
Hollings, J.P. 4(2) 205
- The energy dissipation effects of redundant members in silos under earthquakes. Li Zhiming:
Geng Shujiang. 20(4) 269
- The influence of bridge geometry on the seismic behaviour of bridges on isolating bearings.
Moss, P.J.: Carr, A.J.: Cooke, N.:
Tan Fun Kwai. 19(4) 255
- The influence of non-geometric factors on the seismic behaviour of bridges on isolating bearings.
Cooke, N.: Carr, A.J.: Moss, P.J.:
Tan Fun Kwai. 19(4) 263
- The performance of a ductile moment resisting connection between a precast concrete column and a timber beam. Dean, J.A. 19(2) 111
- The role of science and engineering in mitigating natural hazards. Press, F. 18(2) 115
- The role of the International Association for Earthquake Engineering. Glogau, O.A. 3(1) 1
- The seismic performance of energy absorbing dampers in building structures. Key, D.E. 17(1) 38

- The specification of earthquake resistance for electricity system equipment. Hitchcock, H.C. 6(4) 178
- Union House - a cross braced structure with energy dissipators. Boardman, P.R.: Wood, B.J.: Carr, A.J. 16(2) 83

EARTHQUAKES GENERAL

- Accelerograph recordings of the Musa earthquake 16 September, 1972. Gaull, B. 9(2) 115
- Agadir, Morocco, reconstruction work six years after the earthquake of February 1960. Falconer, B.H. 1(2) 72
- An immediate and preliminary report on the Manjil, Iran, earthquake of 20 June 1990. Moinfar, A.A.: Naderzadeh, A. 23(4) 254
- An immediate field survey of the San Fernando, Los Angeles earthquake, February 9, 1971. Adams, R.D. 4(3) 335
- Damage to civil engineering structures due to the near Izu-Oshima earthquake of January 14, 1978. Iwasaki, T.: Kawashima, K. 12(2) 127
- Damage to lifeline systems in the city of Sendai caused by the 1978 Miyagiken-Oki earthquake. Katayama, T. 12(1) 49
- Design lessons from recent destructive earthquakes. Skinner, R.I. 4(2) 234
- Discussion - the Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE reconnaissance team. (23(1), 1-78) Gates, J.H. 23(4) 322
- Discussion, and authors' reply: Vulnerability and seismic risk assessment of buildings following the 1989 Newcastle, Australia earthquake (24(2), p116). Melchers, R.R. 24(4) 341
- Earthquake damage at Sendai, June, 1978. 11(2) 129
- Earthquake engineering reseach and practice in Mexico after the 1985 earthquakes. Esteva, L. 20(3) 159
- Earthquake reconnaissance report. Damage to the power generation and transmission facilities in the Loma Prieta earthquake of 17 October 1989. Tan Pham. 25(1) 3
- Engineering features of the San Fernando earthquake. Earthquake Engineering Research Laboratory, California Institute of Technology. 6(1) 22
- Ghaenat (Iran) earthquake of November 14, 1979. Hojjat Adeli. 14(1) 34
- Ground motion near causative fault of Kita-Tango earthquake of 1927. Yoshikawa, S.: Iwasaki, Y.T.: Tai, M.: Matsuzaki, J. 13(1) 49
- Observations of the 1989 Loma Prieta earthquake. Marks, P. 23(4) 235
- Palmdale Bulge and its significance. Lensen, G.J. 11(3) 193
- Performance assessment of damaged bridge bents after the Loma Prieta earthquake. Priestley, M.J.N.: Seible, F. 25(1) 44
- Photographs of building damage at Sendai, Japan in the Miyagiken-Oki earthquake of June 12, 1978. 12(1) 59
- Preliminary field observations of the Chilean earthquake of 3 March 1985 Dowrick, D.J. 18(2) 119
- Response of a reinforced concrete shear wall structure during the 1972 Managua earthquake. Bertero, V.V.: Mahin, S.A.: Hollings, J. 7(3) 95
- Romanian earthquake, March 1977. Skinner, R.I. 10(2) 106
- Society, prediction and warning: current assumptions on the implications of earthquake forecasting. Britton, N.R. 13(4) 365
- Structural damage aspects of the April 22, 1991 Costa Rica earthquake. Priestley, M.J.N. 25(1) 17
- Technical note - A note on the 1976, Gazli accelerogram. Berrill, J.B. 10(4) 238
- The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions. Rynn, J.M.W.: Brennan, E.: Hughes, P.R.: Pedersen, I.S.: Stuart, H.J. 25(2) 77
- The behaviour, overview of damage and retrofit of steel buildings after the earthquakes of September 1985. Martinez-Romero, E. 20(1) 30
- The December 28, 1989 Newcastle, Australia Earthquake. Brunson, D.R. 23(2) 102
- The Haicheng, China, earthquake of February, 1975: the first successfully predicted major earthquake. Adams, R.D. 9(1) 32
- The June 28, 1991 Sierra Madre California earthquake. Shepherd, R. 24(4) 279
- The Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE team. Shephard, R.B.: Wood, P.R.: Berrill, J.B.: Gillon, N.R.: North, P.J.: Perry, A.K.: Bent, D.P. 23(1) 1
- The October 1, 1987 Whittier Narrows earthquake. Shepherd, R. 20(4) 255
- The Peruvian earthquake disaster. 3(2) 84
- The Philippines earthquake of July 16, 1990 Report on field visit by the NZNSEE reconnaissance team. Hopkins, D.C.: Clark, W.D.: Matuschka, T.: Sinclair, J.C. 24(1) 3
- The San Antonio, Chile, earthquake of 3 March 1985. Connor, I.N. 18(2) 128
- The September 1985 Mexico Earthquake: Preliminary report of the New Zealand reconnaissance team. 18(4) 291
- The September 1985 Mexico earthquakes: final report of the New Zealand reconnaissance team. 21(1) 3
- The Taveuni earthquake Fiji on 17 November 1979. Paterson, A.W.: Williams, R.L. 13(2) 194
- The Tonga earthquake of 23 June, 1977 - some initial observations. Campbell, M.D.: McKay, G.R.: Williams, R.L. 10(4) 208
- The Veracruz earthquake of 28 August, 1973. Irvine, H.M. 7(1) 2
- Vulnerability and seismic risk assessment of buildings following the 1989 Newcastle, Australia, earthquake. Chandler, A.M.: Pappin, J.W.: Coburn, A.W. 24(2) 116

EARTHQUAKES IN NEW ZEALAND

- A computer file of New Zealand earthquakes. Smith, W.D. 9(2) 136
- A seismicity model for New Zealand. Peek, R.: Berrill, J.B.: Davis, R.O. 13(4) 355
- Bay of Plenty earthquake: an outline of the Earthquake and War Damage Commission's role. Allwood, M.J.R. 21(2) 113
- Behaviour of lifts - the Wellington earthquake November 1, 1968. McKenzie, D.J. 2(3) 278
- Comparison of remote site and basement records as excitation of the Vogel Building. McVerry, G.H. 17(1) 3
- Earthquake damage at Edgecumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake (and *see* Errata). Rutledge, A.L. 21(4) 247
- Earthquake hazard in New Zealand: some implications of the Edgecumbe Earthquake, March 1987 Smith, W.D. 23(3) 211
- Edgecumbe earthquake - some notes on its source, ground motions, and damage in relation to safety. Dowrick, D.J. 21(3) 198
- Edgecumbe earthquake: reconnaissance report. Pender, M.J.: Robertson, T.W. 20(3) 201

Effect of the Edgecumbe earthquake on mechanical and process equipment at the Tasman Mill. Hodge, W.C.: Macfarlane, M. 21(3)	161	Liquefaction in the Buller region in the 1929 and 1968 earthquakes. Berrill, J.B.: Bienvenu, V.C.: Callaghan, M.W. 21(3)	174
Errata - earthquake damage at Edgecumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake on 2 March 1987, Vol.21 No. 4, December 1988, pp 247-254. Rutledge, A.L. 22(1)	60	New Zealand earthquakes in 1989. Smith, W.D. 23(2)	97
Historical aspects of the 1855 earthquake. Stevens, G.R. 22(1)	30	Prediction of seismic wave amplitudes using the phase-front parabolic approximation. Haines, A.J. 17(2)	145
<i>Inangahua earthquake 1968:</i> A builder's observations and views at Greymouth. Williams, J.E. 2(1)	148	Principal New Zealand earthquakes during the year 1972. Adams, R.D. 6(1)	48
Builders' field experiences. Marriott, E.W.T. 2(1)	96	Principal New Zealand earthquakes during the year 1973. Adams, R.D. 7(1)	48
Building damage in the Reefton area. Bird, D.I.D.: Gentry, S.C.: Hollings, J.P. 2(1)	130	Principal earthquakes in New Zealand during the year 1975. 9(2)	135
Building damage in Westport. Andrews, A.L. 2(1)	126	Principal earthquakes during the year 1976. Adams, R.D. 10(1)	52
Damage between Westport and Greymouth. Smith, A.D. 2(1)	135	Principal earthquakes during the year 1977. Adams, R.D. 11(1)	62
Damage from Greymouth to Hokitika. Anderson, P.D.: Osborne, T.W.J. 2(1)	147	Principal New Zealand earthquakes in 1978. Eiby, G.A. 12(1)	66
Damage in Christchurch and Canterbury. Moss, P.J. 2(1)	143	Principal New Zealand earthquakes in 1979. Smith, W.D. 13(1)	71
Damage in Nelson and Murchison. Sanders, R.L.: Toynbee, G.A. 2(1)	122	Principal New Zealand earthquakes in 1980. Smith, W.D. 14(2)	96
Damage in the Greymouth area. Anderson, P.D.: Smith, F.R.: Quinn, F. 2(1)	139	Principal New Zealand earthquakes in 1981. Smith, W.D. 15(1)	46
Damage in the Westport area. Chandler, T.M.: Bennett, J.R. 2(1)	128	Principal New Zealand earthquakes in 1982. Smith, W.D. 16(1)	59
Damage to civil engineering works and resulting civil defence problems. Evans, G.L. 2(1)	39	Principal New Zealand earthquakes in 1983. Smith, W.D. 17(1)	56
Damage to railway track. Duckworth, W.J.H. 2(1)	59	Principal New Zealand earthquakes in 1985. Smith, W.D. 19(1)	64
Damage, operation and reinstatement of Post Office communications services. Eddy, D.C.A.: Hands, B.B.: Preston, D.S.G. 2(1)	73	Principal New Zealand earthquakes in 1986. Smith, W.D. 20(1)	1
Earthquake damage to three railway bridges 1968 Inangahua earthquake. Hollings, J.P.: Fraser, I.A.N. 1(2)	22	Principal New Zealand earthquakes in 1987. Smith, W.D. 21(1)	1
Earthquake insurance. Gill, J.L. 2(1)	116	Principal New Zealand earthquakes in 1988. Smith, W.D. 22(1)	1
Immediate field damage reconnaissance. Falconer, B.H.: Lensen, G.J. 2(1)	27	Principal New Zealand earthquakes in 1990. Smith, W.D. 24(1)	1
Inangahua earthquake 1968 damage to State Highways. Douglas, J.S. 1(2)	49	Principal earthquakes in New Zealand 1991. Smith, W.D. 25(1)	1
Inangahua earthquake 1968 damage to State Highways. Douglas, J.S. 2(1)	47	Pukaki earthquake of 17 December 1978. Calhaem, I.M. 12(1)	7
Inangahua earthquake damage on railways. Duckworth, W.J.H. 1(2)	12	Strong motion records of the Milford Sound earthquake 1976 May 4. Hodder, S.B.: Skinner, R.I.: Hefford, R.T.: Randal, P.M. 11(3)	184
Initial appraisal of building damage in Inangahua. Falconer, B.H. 2(1)	77	Strong-motion earthquake recording in New Zealand. Skinner, R.I.: Stephenson, W.R.: Hefford, R.T. 4(1)	31
Insurance assessments in Inangahua. Bird, D.I.D. 2(1)	111	Surface wave magnitudes of some New Zealand earthquakes 1901-1988. Dowrick, D.J.: Smith, E.G.C. 23(3)	198
May 24, 1968 at Inangahua Junction. Hogue, T. 2(1)	37	Te Aroha earthquake, 9 January 1972. Adams, R.D.: Muir, M.G.: Kean, R.J. 5(2)	54
Preliminary comment on damage to buildings in the Inangahua earthquake. Falconer, B.H. 1(2)	61	Technical note: Computer analyses of New Zealand earthquake accelerograms - Volume 1. Beck, J.L.: Randal, P.M.: Hefford, R.T. 15(1)	46
Public relations in restoration work. Smart, M. 2(1)	99	Technical note: Strong motion record from Turangi, 5 March 1984. Hodder, S.B. 17(2)	154
Restoration in the Inangahua area. Hamblett, S.G.: Yeatman, H.W. 2(1)	92	The Dunedin earthquake, 9 April 1974, Part 1: seismological studies. Adams, R.D.: Kean, R.J. 7(3)	115
Rights and duties of owners and mortgagees. Craig, W.T. 2(1)	119	Part 2: local effects. Bishop, D.G. 7(3)	123
Survey and approach to restoration of damaged buildings. Yeatman, H.W. 2(1)	85	The Lake Coleridge earthquakes of 1946. Eiby, G. 23(2)	150
Symposium on the Inangahua earthquake. 2(2)	154	The Milford Sound earthquake of 1976 May 4. Eiby, G.A. 11(3)	191
The 1968 Inangahua earthquake and electricity services. Hitchcock, H.C. 1(2)	4	The Motu river earthquake of 8 March 1984. Reyners, M.: Hodder, S. 18(1)	41
The 1968 Inangahua earthquake and electricity services. Hitchcock, H.C. 2(1)	65	The Waitapu earthquake of 1983, December 14. Smith, E.G.C.: Scott, B.J.: Latter, J.H. 17(4)	272
The role of Government Departments. Peart, A.McG. 2(1)	113	Time for a break - let's have an earthquake. van Brink, D.J. 21(4)	237
Liquefaction during historic earthquakes in New Zealand. Fairless, G.J. Berrill, J.B. 17(4)	280		

Timing of the last large earthquake on the Wellington fault from the Tararua ranges to Woodville. Beanland, S. 22(1)	4
Who says earthquakes don't happen here? Adams, R.D. 7(2)	52

EARTHQUAKE MITIGATION

Consequences of earthquake prediction on other adjustments to earthquakes. Haas, J.E.: Mileti, D.S. 9(4)	187
Mitigation of danger to property. Strachan, C.M. 11(1)	26
The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions. Rynn, J.M.W.: Brennan, E.: Hughes, P.R.: Pedersen, I.S.: Stuart, H.J. 25(2)	77
The role of science and engineering in mitigating natural hazards. Press, F. 18(2)	115

EARTHQUAKE PREDICTION (includes earthquake warning systems)

Editorial - How beneficial is earthquake prediction? Adams, R.D. 5(4)	ii
<i>Seminar on the social and economic effects of earthquake prediction, 1977.</i>	
Central government and earthquake prediction. Roberts, J.L. 11(1)	43
Civil defence aspects. Holloway, R.H.F. 11(1)	12
Earthquake prediction. Evison, F.F. 11(1)	2
Mitigation of danger to property. Strachan, C.M. 11(1)	26
Opening address. O'Dea, Sir P. 11(1)	1
Role of the media in earthquake prediction. Robson, M. 11(1)	22
Summary of evening discussion. 11(1)	48
The economic issues. Thompson, G. 11(1)	8
The effect of earthquake prediction on earthquake insurance in New Zealand. Hellberg, M. 11(1)	19
The effects of earthquake prediction on the Ministry of Works and Development. Stirrat, A.G. 11(1)	35
The implications of earthquake prediction for the New Zealand Electricity Department. O'Brien, M.T. 11(1)	37
The police role. Mitchell, R.S. 11(1)	33
The political and legal effects. Marshall, Sir J. 11(1)	5
The role of local bodies. Fowler, M. 11(1)	40
The roles of central and local government in pre-disaster planning. O'Dea, Sir P. 11(1)	30
The social implications of earthquake predictions and warnings on and for organisations. Britton, N.R. 11(1)	15
Society, prediction and warning: current assumptions on the implications of earthquake forecasting. Britton, N.R. 13(4)	365

EARTHQUAKE RESISTANT STRUCTURES and see Seismic Design

1975 Seminar on NZS 4203 (and see Standards). Dynamic aspects of the Code for the design of earthquake resistant buildings. Skinner, R.I. 9(1)	63
A method for the evaluation of the seismic capacity of existing reinforced concrete buildings in Japan. Hiroyuki Aoyama. 14(3)	105
A modified approach to earthquake resistant design of torsionally coupled buildings. Chandler, A.M.: Hutchison, G.L. 21(2)	140
A preliminary analytic evaluation of the seismic response of structural walls failing in a shear mode. Robinson, L.M. 19(3)	167

A simplified earthquake resistant design method for base isolated multistorey structures. Andriano, T.: Carr, A.J. 24(3)	238
A study of the earthquake resistance of domestic break pressure tanks. Blackwell, F.N. 12(2)	168
Anchorage of transverse reinforcement in rectangular reinforced concrete columns in seismic design. Tanaka, H.: Park, R.: McNamee, B. 18(2)	165
Base isolation for increased earthquake resistance of buildings. Skinner, R.I.: McVerry, G.H. 8(2)	93
Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading: Unit 1 test results. Park, R.: Thompson, K.J. 6(4)	158
Comparative study of four passive energy dissipation systems. Aiken, I.D.: Nims, D.K.: Kelly, J.M. 25(3)	175
Design lessons from recent destructive earthquakes. Skinner, R.I. 4(2)	234
Design of an earthquake resisting building using precast concrete cross-braced panels and incorporating energy-absorbing devices. Mathewson, C.D.: Davey, R.A. 12(4)	340
Design of seismic resistant prestressed concrete structures. Andrews, A.L. 9(3)	175
Design of shear walls for seismic resistance. Armstrong, I.C. 10(1)	17
Developments in design of wood structures for earthquake resistance. Buchanan, A.H. 16(2)	156
Discussion - Design of Shear walls for seismic resistance, by I.C. Armstrong (Vol10(1)). Williams, R.L. 10(3)	159
Discussion - Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames, by T. Paulay (Vol 9(4)). Williams, R.L. 10(3)	160
Discussion - Seismic resistance of brick masonry walls, by M.J.N. Priestley and D.O. Bridgeman. Williams, D. 8(3)	238
Discussion - The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea, by Jury, R.D., Hollings, J.P. and Fraser, I.A.N. McCue, K. 17(4)	292
Dynamic tests on laminated rubber bearings. Tyler, R.G. 10(3)	143
Earthquake isolation technology for industrial facilities - research, development and applications. Fujita, T. 18(3)	224
Earthquakes and earthquake engineering in China. Fu Yuan. 20(4)	275
Effect of wall base rotation on behaviour of reinforced concrete frame-wall building. Daisuke Kato: Shunsuke Otani: Hideo Katsumata: Hiroyuki Aoyama. 17(2)	106
Identification of research needs for improving the aseismic design of building structures. Bertero, V.V. 9(1)	1
Japanese practice for estimating the expected maximum earthquake force at a nuclear power plant site. Syun'itiro Omote: Yorihiro Ohsaki: Toshihiro Kakimi: Tokihoko Matsuda. 13(1)	37
Mechanisms of energy absorption in special devices for use in earthquake resistant structures. Kelly, J.M.: Skinner, R.I.: Heine, A.J. 5(3)	63
Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames. Paulay, T. 9(4)	205
N.Z. Parliament Buildings seismic protection by base isolation. Poole, R.A.: Clendon, J.E. 25(3)	147
NZNSSE discussion group on reinforced concrete walls and diaphragms see NZNSSE.	

P-delta actions in seismic resistant structures. Fenwick, R.C.: Davidson, B.J.: Chung, B.T. 25(1)	56
Progress report on cyclic load tests on prestressed partially prestressed and reinforced concrete interior beam-column assemblies. Park, R.: Thompson, K.J. 8(1)	12
Reduction and distribution of lateral seismic inertia forces on base isolated multistorey structures. Andriono, T.: Carr, A.J. 24(3)	225
Research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(3)	154
Rubber bearings in base-isolated structures: a summary paper Tyler, R.G. 24(3)	251
Seismic design of high rise buildings. McKenzie, G.H.F. 4(2)	222
Seismic isolation of bridges in Italy. Parducci, A.: Mezzi, M. 25(3)	193
Seismic performance of two full-size reinforced concrete beam-column joint units. Blakeley, R.W.G.: Megget, L.M.: Priestley, M.J.N. 8(1)	38
Seismic resistant joints for reinforced concrete structures. Fenwick, R.C. 14(3)	145
Seismic response of low-rise buildings. Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3)	180
Seismic strengthening of existing reinforced concrete buildings in Japan. Shunsuke Sugano. 14(4)	209
Shear modulus Gs. Hughes, D.K. 20(1)	63
Slenderness effects in earthquake resisting frames. Andrews, A.L. 10(3)	154
Some recent research in New Zealand into aspects of seismic resistance of prestressed concrete frames. Park, R.: Thompson, K.J. 9(3)	167
Support structure design for New Zealand Forest Products Ltd's No. 5 recovery boiler. Sharpe, R.D. 20(1)	2
Tapered steel energy dissipators for earthquake resistant structures. Tyler, R.G. 11(4)	282
Technical Note: Priorities for research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(4)	220
The design of public buildings. Glogau, O.A. 5(4)	128
The New Zealand Loadings Code and its application to the design of seismic resistant prestressed concrete structures. Butcher, G.W. 9(3)	162
The structural performance of houses in earthquakes. Cooney, R.C. 12(3)	223
The task of earthquake resistance design - a divergent problem. Garden, R.J.P. 4(2)	331
Use of yield ratio response spectra to design yielding members for improving earthquake resistance of brittle structure. Gilmour, R.M.: Hitchcock, H.C. 4(2)	285

EARTHQUAKE RISK BUILDINGS and see Refurbishment and Retrofitting

A philosophy for improving old buildings to resist earthquakes. Hollings, J.P. 7(2)	78
Aspects of high earthquake risk government buildings. Sinclair, D. 7(2)	85
Case studies: earthquake risk buildings 1. The upgrading of Middle School, cnr Jed and Don streets, Invercargill. Buxton, F.N. 16(1)	60
2. Anglican parish of Blenheim: strengthening to the Church of the Nativity. Davidson, C.C. 16(1)	64
3. Hastings Boys' High School administration buildings, Hastings, Hawkes Bay, New Zealand. Garrett, I.J. 16(1)	69
4. Restoration of old Auckland Customhouse. Boardman, P.R. 16(1)	73

Case studies: earthquake risk buildings 1. Strengthening of State Trinity Centre, Christchurch. Evans, D.S. 16(2)	162
2. Redevelopment of the Normal School Cranmer Square, Christchurch. Wilby, G.K. 16(2)	165
3. Cashfields shopping centre: Christchurch. Taylor, J.M. 16(2)	172
4. State Opera House - upgrading. Christianson, J. 16(2)	175
Case studies: earthquake risk buildings 1. New Plymouth Girls' High School structural strengthening and upgrading of the 1926 block. Hutchison, D.L.: Gill, W.D. 17(1)	57
2. Upgrading of AMP Society branch office corner Customhouse Quay and Hunter Street, Wellington. Cathie, M.C.: Leuchars, J.M. 17(1)	65
3. Strengthening of James Smith Ltd Cuba Street, Wellington. Munro, D.J. 17(1)	67
Classification of high earthquake risk buildings Draft Code of Practice 2 March 1972. 5(2)	37
Comments on some earthquake damaged buildings in New Zealand. Kerswill, F.E. 2(4)	483
Discussion - Classification of high earthquake risk buildings Draft Code of Practice, 2 March 1972. Bluck, B.C. 5(3)	108
Earthquake risk buildings - how they stand up in court. Hopkins, D.C.: McKay, G.R.: Shephard, R.B. 24(2)	107
Earthquake risk buildings - lessons from experience. Hopkins, D.C.: Robertson, T.W. 14(2)	54
Earthquake risk buildings in Wellington. Bentley, R.J. 11(3)	200
Leading article. Crookes, S.I. 1(2)	2
NZNSSE study group for structures of limited ductility (and see NZNSSE): 4. The evaluation of existing structures. Brunson, D.R.: Shephard, R.B. 19(4)	325
Our old buildings can be safe in earthquake. Smith, I.C. 12(4)	289
Refurbishing earthquake risk buildings in U.S.A. Leadbeater, D.B. 14(2)	43
Some aspects of the strengthening of earthquake risk buildings. Toomath, W. 12(4)	287
The June 28, 1991 Sierra Madre California earthquake. Shepherd, R. 24(4)	279
The local authority engineer and high earthquake risk buildings. Grigg, A.N. 7(2)	81
The need for a strengthening code. Bluck, B.C. 7(2)	88
The use of sprayed concrete in the strengthening of earthquake risk buildings. Leuchars, J.M. 22(3)	167

ECONOMICS

A philosophy of seismic zoning Eiby, G.A. 4(1)	171
Builders' field experiences. (<i>Inangahua earthquake</i> 1968.) Marriott, E.W.T. 2(1)	96
Consequences of earthquake prediction on other adjustments to earthquakes. Haas, J.E.: Mileti, D.S. 9(4)	187
Cost effectiveness of code base shear requirements for reinforced concrete frame structures. Elms, D.G.: Silvester, D. 11(2)	85
Managing the New Zealand economy at a time of natural disaster. Knight, R.L. 23(3)	173
The economic issues (<i>Earthquake prediction seminar</i> , 1977). Thompson, G. 11(1)	8
The economics of earthquake engineering. Hollings, J.P. 4(2)	205

EDITORIALS AND LEADING ARTICLES

Editorial. McKenzie, D.S. 6(3)	95
How beneficial is earthquake prediction? Adams, R.D. 5(4)	ii
Macro zoning for earthquake engineering. Andrews, A.L. 5(3)	ii
Leading article. Crookes, S.I. 1(2)	2
New Zealand earthquake engineering education. Shepherd, R. 2(3)	200
The role of the International Association for Earthquake Engineering. Glogau, O.A. 3(1)	1
Who says earthquakes don't happen here? Adams, R.D. 7(2)	52

ELECTRIC POWER (includes generating plants, power transmission)

Earthquake damage at Edgecumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake (and <i>see</i> Errata). Rutledge, A.L. 21(4)	247
Earthquake design of structures with brittle members and heavy artificial damping by the method of direct integration. Winthrop, D.A.: Hitchcock, H.C. 4(2)	294
Earthquake reconnaissance report. Damage to the power generation and transmission facilities in the Loma Prieta earthquake of 17 October 1989. Tan Pham. 25(1)	3
Earthquake response of high voltage circuit breakers with non-linear force-deflection characteristics. Mayes, R.L.: Hitchcock, H.C. 4(2)	301
Errata - earthquake damage at Edgecumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake on 2 March 1987, Vol.21 No. 4, December 1988, pp 247-254. Rutledge, A.L. 22(1)	60
Isolation of nuclear power plants from earthquake attack. Skinner, R.I.: Tyler, R.G.: Hodder, S.B. 9(4)	199
The 1968 Inangahua earthquake and electricity services. Hitchcock, H.C. 1(2)	4
Seismic effects on nuclear installations introduction, summary and recommendations. (<i>See</i> Industrial Plants.) 11(3)	161
The 1968 Inangahua earthquake and electricity services. Hitchcock, H.C. 2(1)	65
The implications of earthquake prediction for the New Zealand Electricity Department. O'Brien, M.T. 11(1)	37
The specification of earthquake resistance for electricity system equipment. Hitchcock, H.C. 6(4)	178
Time for a break - let's have an earthquake. van Brink, D.J. 21(4)	237
Use of yield ratio response spectra to design yielding members for improving earthquake resistance of brittle structure. Gilmour, R.M.: Hitchcock, H.C. 4(2)	285

ENERGY-ABSORBING DEVICES *see* Earthquake Engineering

ENGINEERING EDUCATION (includes engineering qualification, registration)

Geophysics at the University of Auckland. Kibblewhite, A.C. 2(4)	459
Geophysics at the Victoria University of Wellington. Evison, F.F. 2(4)	470
New Zealand earthquake engineering education. Shepherd, R. 2(3)	200
The need for structural registration. McKenzie, G.H.F. 3(1)	36

ERRATA

Errata - amendments to Procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height, by R.L. Williams. Vol 8. No.4 9(1)	88
Errata - earthquake damage at Edgecumbe and Kawarau Electricorp substations in the Bay of Plenty earthquake on 2 March 1987, Vol.21 No. 4, December 1988, pp 247-254. Rutledge, A.L. 22(1)	60
Errata - Sliding-vibrating response of elastic structures, Vol 21 No. 3 September 1988 pp 190-197. Fu Yu-An. 22(1)	59

GENERAL

Capital discovery place Te aho a Maui Wellington. Thompson, P. 23(2)	15
-----------------------------------------------------------------------------------	----

GEOLOGY (includes geophysics)

1975 Seminar on NZS 4203 (and <i>see</i> Standards). Code provisions related to soils and foundations. Taylor, P.W. 9(1)	68
Accelerograph recordings of the Musa earthquake 16 September, 1972. Gaull, B. 9(2)	115
Active earth deformation. Grant-Taylor, T.L.: Hancox, G.T.: Lensen, G.J.: Oborn, L.E.: Thompson, B.N.: Suggate, R.P. 12(4)	334
An earthquake catastrophe damage assessment model with particular reference to central New Zealand. Dowrick, D.J. 16(3)	213
Distribution of geological materials in Lower Hutt and Porirua, New Zealand: a component of a ground shaking hazard assessment. Dellow, G.D.: Read, S.A.L.: Begg, J.G.: Van Dissen, R.J.: Perrin, N.D. 25(4)	332
Earthquake hazard in New Zealand: some implications of the Edgecumbe Earthquake, March 1987. Smith, W.D. 23(3)	211
Earthquake resistant design of cohesive earth slopes. Martin, G.R.: Taylor, P.W. 4(1)	51
Elastic and non-elastic surface deformation in New Zealand. Lensen, G.J. 3(4)	131
Finding Wellington's faults. Wood, P.R. 22(1)	36
Foundations for capacity designed structures. Taylor, P.W.: Williams, R.L. 12(2)	101
Frequency of eruptions at New Zealand volcanoes. Latter, J.H. 18(1)	55
Geodetic observations in the Wellington Region. Blick, G.H. 22(1)	6
Geophysics at the University of Auckland. Kibblewhite, A.C. 2(4)	459
Geophysics at the Victoria University of Wellington. Evison, F.F. 2(4)	470
Influence of foundation compliance on the seismic response of bridge piers. Priestley, M.J.N.: Park, R.: Heng, N.K. 12(1)	22
Is strain concentrating about the Wellington fault? Darby, D.J. 22(1)	9
Kaiwharawhara reclamation. Bentley, R.J. 13(2)	203
Locating shallow faults and fracture zones using engineering geophysics. Mouton, S.: Smits, F. 22(1)	19
New Zealand earthquakes and plate tectonic theory. Walcott, R.I. 12(2)	87
Rate of movement and geometry of the southern segment of the Wellington Fault. Berryman, K.R. 22(1)	4

Reconnaissance field investigation of the Landers earthquake (Ms 7.5) of June 28, 1992, San Bernadino County, California, USA. Berryman, K. 25(3)	230
Review of current earthquake engineering research in New Zealand. Moss, P.J. 20(2)	91
Review of geophysical strain measurement. Sydenham, P.H. 4(1)	2
Seismotectonics and earthquake risk macrozoning in New Zealand. Suggate, R.P. 12(1)	3
Seminar on geotechnical aspects of earthquake engineering. Taylor, P.W.: Martin, G.R. 3(3)	120
The Dunedin earthquake, 9 April, 1974 Part 2: local effects (and <i>see</i> Earthquakes in New Zealand). Bishop, D.G. 7(3)	123
The Inangahua Earthquake 1968 (and <i>see</i> Earthquakes in New Zealand). Geology. Lensen, G.J.: Suggate, R.P. 2(1)	19
Two dimensional nonlinear site response analyses. Larkin, T.: Marsh, J. 25(3)	222
What are the main uncertainties in estimating earthquake risk? Vere-Jones, D. 16(1)	39
Workshop on the deformation of the Wellington Region. Smith, E.G.C.: Anderson, H.J.: Ansell, J.: Eiby, G.: Fellows, D.: Lewis, K.B.: Reilly, W.I.: Robinson, R.: Webb, T.H.: Wellman, H.W. 22(1)	2

GEOMECHANICS

Earthquake resistant design of cohesive earth slopes. Martin, G.R.: Taylor, P.W. 4(1)	51
Earthquake-soil structure interaction, spring and dashpot models, and real soil behaviour. Pender, M.J. 16(4)	320
Effect of soil properties on earthquake response. Parton, I.M.: Melville-Smith, R.W. 4(1)	73
Elastic soil-structure interaction. Carr, A.J.: Moss, P.J. 4(2)	258
Foundations for capacity designed structures. Taylor, P.W.: Williams, R.L. 12(2)	101
NZNSSE discussion group on the seismic design of bridges (and <i>see</i> NZNSSE). Section 9: Earth retaining structures. Matthewson, M.B.: Wood, J.H.: Berrill, J.B. 13(3)	280
Seismic analysis of a highway bridge considering soil-structure interaction effects. Iwasaki, T.: Kawashima, K. 12(4)	305
Seismic design of gravity retaining walls. Elms, D.G.: Richards, R. 12(2)	114
Seismic stability of reinforced earth retaining walls. Bracegirdle, A. 13(4)	347
Seminar on geotechnical aspects of earthquake engineering. Taylor, P.W.: Martin, G.R. 3(3)	120
Shaking table tests on a model retaining wall. Lai Cho Sim: Berrill, J.B. 12(2)	122

GROUND RESPONSE (includes ground shaking, soil testing, liquefaction)

1975 Seminar on NZS 4203 (and <i>see</i> Standards). Code provisions related to soils and foundations. Taylor, P.W. 9(1)	68
Seismic torsional effects on buildings. Elms, D.G. 9(1)	79
A field test for dynamic soil properties. Evans, G.L. 4(2)	176
Accelerograph recordings of the Musa earthquake 16 September, 1972. Gaull, B. 9(2)	115
Anomalous intensities due to the Korakonui earthquake, 5 December, 1976. Eiby, G.A. 10(4)	167

Cellular normal modes of alluvium response. Stephenson, W.R. 8(4)	245
Considerations for a "design" earthquake. Evans, G.L. 5(2)	47
Construction of site dependent design spectra. Mostaghel, N.: Ahmadi, G. 14(4)	244
Earthquake ground shaking hazard assessment for the Lower Hutt and Porirua areas, New Zealand. Van Dissen, R.J.: Taber, J.J.: Stephenson, W.R.: Sritharan, S.: Read, S.A.L.: McVerry, G.H.: Dellow, G.D.: Barker, P.R. 25(4)	286
Earthquake induced resonant motion of alluvium. Stephenson, W.R. 7(3)	144
Earthquake-soil structure interaction, spring and dashpot models, and real soil behaviour. Pender, M.J. 16(4)	320
Earthquakes, landslides, and large dams in New Zealand. Adams, J. 14(2)	93
Edgecumbe earthquake - some notes on its source, ground motions, and damage in relation to safety. Dowrick, D.J. 21(3)	198
Effect of soil properties on earthquake response. Parton, I.M.: Melville-Smith, R.W. 4(1)	73
Estimation of seismic motion and damage to structures for new bullet trains. Yutaka Nakamura: Hidehiko Abe. 17(2)	121
Evaluation of dynamic ground characteristics and seismic microzoning. Yoshikazu Kitagana: Yutaka Matsushima. 17(1)	15
Formidable echo. Savarensky, F.F. 3(3)	107
Ground motion near causative fault of Kita-Tango earthquake of 1927. Yoshikawa, S.: Iwasaki, Y.T.: Tai, M.: Matsuzaki, J. 13(1)	49
Japanese practice for estimating the expected maximum earthquake force at a nuclear power plant site. Syun'itiro Omote: Yorihiko Ohsaki: Toshihiro Kakimi: Tokihoko Matsuda. 13(1)	37
Lateral drift of reinforced concrete structures subjected to strong ground motion. Sozen, M.A. 16(2)	107
Liquefaction - the state of knowledge. Whitman, R.V. 20(3)	145
Liquefaction during historic earthquakes in New Zealand. Fairless, G.J. Berrill, J.B. 17(4)	280
Liquefaction in the Buller region in the 1929 and 1968 earthquakes. Berrill, J.B.: Bienvenu, V.C.: Callaghan, M.W. 21(3)	174
Normal modes of a "cylindrical valley" of alluvium. Stephenson, W.R. 22(2)	76
Observation of a directed resonance in soil driven by transverse rock motion. Stephenson, W.R. 22(2)	81
On the observation, characterisation and predictive GIS mapping of strong ground shaking for seismic zonation (a case study in the San Francisco Bay region, California). Borchardt, R.D. 24(4)	287
Palmdale Bulge and its significance. Lensen, G.J. 11(3)	193
Prediction of post-elastic seismic response of structures by a mode superposition technique. Gillies, A.G.: Shepherd, R. 16(3)	222
Seismic risk and design criteria. Hatrick, A.V. 13(1)	14
Seismic site response. Salt, P.E. 7(2)	62
Seismotectonics and earthquake risk macrozoning in New Zealand. Suggate, R.P. 12(1)	3
Strong motion records of the Milford Sound earthquake 1976 May 4. Hodder, S.B.: Skinner, R.I.: Hefford, R.T.: Randal, P.M. 11(3)	184
Technical note: Intensity of shaking generated by large shallow New Zealand earthquakes. Andrews, A.L.: Butcher, G.W. 25(4)	358

Technical note: Computer analyses of New Zealand earthquake accelerograms - Volume 1. Beck, J.L.: Randal, P.M.: Hefford, R.T. 15(1)	46
The Dunedin earthquake, 9 April 1974, Part 1: seismological studies. Adams, R.D.: Kean, R.J. 7(3)	115
Part 2: local effects. Bishop, D.G. 7(3)	123
The effects of large displacements on the earthquake response of tall concrete frame structures. Moss, P.J.: Carr, A.J. 13(4)	317
The importance of surface waves in strong ground-motion. Smith, W.D. 10(4)	170
The MO2A strong-motion accelerograph. Hefford, R.T.: Tyler, R.G.: Skinner, R.I. 13(4)	374
The task of earthquake resistance design - a divergent problem. Garden, R.J.P. 4(2)	331
Three dimensional elastic dynamic analysis of a 985 foot high free-standing communications tower. Lord, J.: Zayed, M. 8(3)	222
Two dimensional nonlinear site response analyses. Larkin, T.: Marsh, J. 25(3)	222

INDUSTRIAL PLANTS

Isolation of nuclear power plants from earthquake attack. Skinner, R.I.: Tyler, R.G.: Hodder, S.B. 9(4)	199
Planning for disaster. Hodge, W.C. 22(4)	239
Recommendations for the seismic design of petrochemical plants. Norton, J.A.: Gillies, A.G.: Edmonds, F.D. 15(2)	105
Seismic considerations in the design of cryogenic pressure vessels. Webster, J. 16(4)	306
Seismic design of storage tanks. Priestley, M.J.N.: Wood, J.H.: Davidson, B.J. 19(4)	272
Seismic effects on nuclear installations introduction, summary and recommendations (<i>excerpts from the submission of the Working Group on Seismic Effects on Nuclear Installations to the 1977 Royal Commission on Nuclear Power</i>). 11(3)	161
Shake table tests of an industrial building. Takashi, K.: Ohi, K.: Sakai, Y. 20(1)	53
Shear modulus Gs. Hughes, D.K. 20(1)	63
Support structure design for New Zealand Forest Products Ltd's No. 5 recovery boiler. Sharpe, R.D. 20(1)	2
The seismic design of an industrial chimney with rocking base. Sharpe, R.D.: Skinner, R.I. 16(2)	98

INSURANCE

Bay of Plenty earthquake: an outline of the Earthquake and War Damage Commission's role. Allwood, M.J.R. 21(2)	113
<i>Conference on Information needs of the Earthquake Insurance Industry, 1989:</i>	
A new building control system - its nature and some implications. Hall, C.W. 23(3)	168
An overview of earthquake insurance in Japan. Matsushima, M. 22(4)	244
Earthquake and business interruption: a policy for survival? Jacob, P. 22(4)	232
How well is the insurance industry in New Zealand served by existing research and technology? Smith, W.D. 23(2)	134
Loss estimation for insurance purposes: United States practices. Steinbrugge, K.V. 22(4)	193
Managing the New Zealand economy at a time of natural disaster. Knight, R.L. 23(3)	173
Progress in earth science research of benefit to the earthquake insurance industry. Berryman, K.R.: Darby, D.J. 23(2)	130
Research reduces risks. Hopkins, D.C. 23(2)	121

Techniques and parameters for earthquake risk assessment. Algermissen, S.T. 22(4)	202
The information needs and obligations of the insurer. Roth, R.J., Jr. 22(4)	199
The insurance industry's role in town planning. Fowler, M. 23(3)	165
The role of reinsurance in earthquake risk assessment. Porro, B. 22(4)	219
<i>Conference on Information needs of the Earthquake Insurance Industry, 1989 (contd):</i>	
The role of the international reinsurance broker. Greig, J.S. 22(4)	227
The role of the state as an insurer of last resort? Quigley, D. 23(3)	180
Workshop reports - Conference on the information needs of the earthquake insurance industry in New Zealand. 23(4)	284
Consequences of earthquake prediction on other adjustments to earthquakes. Haas, J.E.: Mileti, D.S. 9(4)	187
Earthquake insurance. Scott, D.J. 21(2)	116
<i>Inangahua earthquake 1968:</i>	
Builders' field experiences. Marriott, E.W.T. 2(1)	96
Earthquake insurance. Gill, J.L. 2(1)	116
Initial appraisal of building damage in Inangahua. Falconer, B.H. 2(1)	77
Insurance assessments in Inangahua. Bird, D.I.D. 2(1)	111
Public relations in restoration work. Smart, M. 2(1)	99
Restoration in the Inangahua area. Hamblett, S.G.: Yeatman, H.W. 2(1)	92
Rights and duties of owners and mortgagees. Craig, W.T. 2(1)	119
Methodology for the assessment of the damage cost resulting from a large earthquake in the vicinity of Wellington. Birss, G.R. 18(3)	215
Notes on earthquake insurance in California and New Zealand. 19(4)	251
The Earthquake and War Damage Commission - a look forward (and a look back). Steven, L. 25(1)	52
The effect of earthquake prediction on earthquake insurance in New Zealand. Hellberg, M. 11(1)	19
The June 28, 1991 Sierra Madre California earthquake. Shepherd, R. 24(4)	279
The statistical estimation of earthquake risk. Vere-Jones, D. 6(3)	122

LAW (including law and order, policing)

1975 Seminar on NZS 4203 (and <i>see</i> Standards). Wind loading. O'Donovan, C.J. 9(1)	84
A new building control system - its nature and some implications. Hall, C.W. 23(3)	168
Earthquake risk buildings - how they stand up in court. Hopkins, D.C.: McKay, G.R.: Shepherd, R.B. 24(2)	107
Ministry of Civil Defence - Northern Region. Bourke, L.P. 2(4)	347
Police action (law and order). New Zealand Police Department. (<i>Inangahua earthquake 1968.</i>) 2(1)	45
The local authority engineer and high earthquake risk buildings. Grigg, A.N. 7(2)	81
The political and legal effects (and <i>see</i> Earthquake Prediction). Marshall, Sir J. 11(1)	5

LETTERS

Editorial comment on Building Services. Rands, G.F. 7(1)	49
Editorial comment on Building Services. Blackwell, F.M. 7(1)	50
Microtremor recording. Evans, G.L. 7(1)	49

The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions (25(2) pp 77-144).	
Brunsdon, D.R. 25(4)	361
Tsunami risk. Garden, R.J.P. 1(2)	97
Vol 15 (3) Structural steel test photographs.	
Clifton, G.C. 16(4)	345

LIFE MEMBERS

Life member Dr. Kiyushi Muto. 8(3)	241
----------------------------------------------	-----

LIFELINES

Damage to lifeline systems in the city of Sendai caused by the 1978 Miyagiken-Oki earthquake.	
Katayama, T. 12(1)	49
Earthquake disaster response planning: an engineering overview. Steinbrugge, K.V. 8(2)	114
Seismic risks to linear structures. Eiby, G.A. 11(3)	203
The Philippines earthquake of July 16, 1990 Report on field visit by the NZNSEE Reconnaissance Team.	
Hopkins, D.C.: Clark, W.D.: Matuschka, T.: Sinclair, J.C. 24(1)	3

MASONRY

Behaviour of reinforced masonry shear walls under cyclic loading. Scrivener, J.C.: Williams, D. 4(2)	316
Book review - Seismic design of reinforced concrete and masonry buildings. Hopkins, D.C. 25(4)	362
Case studies: earthquake risk buildings (and <i>see</i> Earthquake Risk Buildings) 1. The upgrading of Middle School, cnr Jed and Don streets, Invercargill. Buxton, F.N. 16(1)	60
3. Hastings Boys' High School administration buildings, Hastings, Hawkes Bay, New Zealand. Garrett, I.J. 16(1)	69
4. Restoration of old Auckland Customhouse. Boardman, P.R. 16(1)	73
4. State Opera House - upgrading. Christianson, J. 16(2)	175
Cyclic loading tests of slender concrete masonry shear walls. Priestley, M.J.N.: Elder, D. McG. 15(1)	3
Cyclic tests on masonry piers. Mayes, R.L.: Mostaghel, N.M.: Clough, R.W.: Dickey, W.L. 7(3)	105
Discussion - Seismic behaviour of unreinforced masonry walls, by M.J.N. Priestley, 18(2).	
Robinson, L.M. 19(1)	65
Discussion - Seismic resistance of brick masonry walls, by M.J.N. Priestley and D.O. Bridgeman. Williams, D. 8(3)	238
Discussion - Seismic resistance of reinforced concrete masonry shear walls with high steel percentages, by M.J.N. Priestley (Vol 10(1)). Glogau, O.A. 11(1)	70
Discussion: Reinforced masonry shear walls: cyclic load tests in contraflexure, by S.J. Thurston and D.L. Hutchison (Vol 15(1)). Priestley, M.J.N. 15(2)	97
Ductility of confined concrete masonry shear walls. Priestley, M.J.N. 15(1)	22
Ductility of unconfined masonry shear walls. Priestley, M.J.N. 14(1)	12
Dynamic performance of brick masonry veneer panels. Priestley, M.J.N.: Thorby, P.N.: McLarin, M.W.: Bridgeman, D.O. 12(4)	314
Earthquake strengthening of old masonry with reference to the Auckland Ferry Building. Gurley, C.R.: Nicholls, J.S.F. 15(4)	199

Masonry construction for earthquakes. (Report of International Conference on Masonry Structural Systems, 1967.) Holmes, I.L. 1(1)	Unpaged
Masonry infill panels subjected to cyclic in-plane loading. Leuchars, J.M.: Scrivener, J.C. 9(2)	122
NZNSEE study group for structures of limited ductility (and <i>see</i> NZNSEE). 2. Design of building structures of limited ductility 2.3 Masonry.	
Priestley, M.J.N. 19(4)	304
Reinforced masonry - seismic behaviour and design. Scrivener, J.C. 5(4)	143
Reinforced masonry shear walls: cyclic load tests in contraflexure. Thurston, S.J.: Hutchison, D.L. 15(1)	27
Seismic behaviour of unreinforced masonry walls. Priestley, M.J.N. 18(2)	191
Seismic design of masonry buildings - background to the draft masonry design code DZ4210. Priestley, M.J.N. 13(4)	329
Seismic design of masonry structures to the new provisional New Zealand Standard NZS 4230P. Priestley, M.J.N. 18(1)	1
Seismic forces in base-isolated masonry structures. Priestley, M.J.N.: Crosbie, R.L.: Carr, A.J. 10(2)	55
Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. Priestley, M.J.N. 10(1)	1

MODIFIED MERCALLI SCALE (and *see* Seismology)

A revision of the Modified Mercalli Seismic Intensity Scale. Study Group, NZNSEE. 25(4)	345
Intensities: a strictly subjective view. Eiby, G.A. 9(3)	181

NZNSEE - NEW ZEALAND NATIONAL SOCIETY FOR EARTHQUAKE ENGINEERING (and *see* Reconnaissance reports and Life Members)

A revision of the Modified Mercalli Seismic Intensity Scale. Study Group, NZNSEE. 25(4)	345
A welcome to the Society. Rinne, J.E. 1(1)	Unpaged
NZNSEE discussion group on reinforced concrete walls and diaphragms.	
Section A: Introduction to and aims in the design of earthquake resisting shear wall structures. Taylor, R.G. 13(2)	103
Section B: The analysis and design of and the evaluation of design actions for reinforced concrete ductile shear wall structures. Paulay, T.: Williams, R.L. 13(2)	108
Section C: Shear walls of limited ductility. Robinson, L.M. 13(2)	144
Section D: Diaphragms in seismic resistant buildings. Kolston, D.: Buchanan, B.W. 13(2)	162
No Section E published.	
Section F: Foundations for shear wall structures. Binney, J.R.: Paulay, T. 13(2)	171
Section G: Low rise reinforced concrete buildings of limited ductility. Glogau, O.A. 13(2)	182
NZNSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames.	
Section A Introduction and philosophy. Burns, R.J. 10(2)	69
No Section B published.	
Section C Analysis for torsion employing provisions of NZS 4203:1974. Poole, R.A. 10(4)	219
Section D Foundations for ductile frames. Allardice, N.W.: Fenwick, R.C.: Taylor, P.W.: Williams, R.L. 11(2)	122

Section E Beam flexure and hinge detailing in reinforced concrete ductile frames requiring beam sway mechanisms. Smith, I.C.: Sidwell, G.K. 10(2)	72
Section F Shear strength requirements. Paulay, T. 10(2)	80
Section G Columns - evaluation of actions. Paulay, T. 10(2)	85
Section H Columns subjected to flexure and axial load. Park, R. 10(2)	95
No Section I published.	
Section J Design of beam-column joints. Blakeley, R.W.G. 10(4)	226
Section K Parts, portions and secondary elements. Allardice, N.W. 10(2)	102
Conclusion. Burns, R.J. 11(2)	121
NZNSSE discussion group on the seismic design of bridges. Introduction. Huizing, J.B.S. 13(3)	226
Section 1: Design philosophy. Stanford, P.R.: Cormack, L.G.: Park, R. 13(3)	229
Section 2: Design earthquake loading and ductility demand. Berrill, J.B.: Priestley, M.J.N.: Chapman, H.E. 13(3)	232
Section 3: Capacity design principles and practice. Chapman, H.E.: North, P.J.: Park, R. 13(3)	242
Section 4: Bridge foundations. Edmonds, F.D.: Carr, A.J.: Goldsmith, P.R.: North, P.J.: Wood, J.H.: Preston, R.L. 13(3)	248
Section 5: Detailing for ductility and ductility capacity. Cormack, L.G.: Park, R.: Chapman, H.E. 13(3)	262
Section 6: Mechanical energy dissipating devices. Blakeley, R.W.G.: Cormack, L.G.: Stockwell, M.J. 13(3)	264
Section 7: Small bridges. Fisher, R.W.: Lanigan, A.G.: Stockwell, M.J. 13(3)	269
Section 8: Structural and non structural details. Lanigan, A.G.: Preston, R.L.: Fisher, R.W.: Stockwell, M.J. 13(3)	274
Section 9: Earth retaining structures. Matthewson, M.B.: Wood, J.H.: Berrill, J.B. 13(3)	280
Section 10: Dynamic analysis. Wood, J.H.: Blakeley, R.W.G.: Priestley, M.J.N. 13(3)	294
Section 11: Bridges requiring special studies. Priestley, M.J.N.: Stanford, P.R.: Carr, A.J. 13(3)	302
Section 12: Strengthening of bridges for seismic loads. McGuire, J.F.: Fisher, R.W.: Stanford, P.R.: North, P.J. 13(3)	308
Discussion - NZNSSE discussion group on the seismic design of bridges, 13(3). Rinne, J.E. 14(2)	97
NZNSSE study group for structures of limited ductility: 1. Introduction. 19(4)	285
2. Design of building structures of limited ductility 2.1 Philosophy of design approach. Park, R.: Andrews, A.L. 19(4)	286
2.2 Reinforced concrete. Park, R.: Robinson, L.M. 19(4)	298
2.3 Masonry. Priestley, M.J.N. 19(4)	304
2.4 Structural steel. Spring, K.C.F. 19(4)	305
2.5 Timber. Buchanan, A.H. 19(4)	313
3. Design of bridge substructures of limited ductility. Chapman, H.E. 19(4)	319
4. The evaluation of existing structures. Brunsdon, D.R.: Shephard, R.B. 19(4)	325
Recommendations for the design and construction of base isolated structures. Blakeley, R.W.G.: Charleson, A.W.: Hitchcock, H.C.: Megget, L.M.: Priestley, M.J.N.: Sharpe, R.D.: Skinner, R.I. 12(2)	136
Seismic design committee. 11(1)	64
The structural check of high rise building design. Edwards, W.P. (High rise building committee.) 5(2)	52

OBITUARIES

A tribute to George Eiby. Smith, W.D. 25(1)	73
Death of George Eiby. Reyners, M. 25(1)	73
J.R.G. Hanlon. 8(2)	174
Professor Kiyushi Muto. Aoyama, H. 22(2)	132
Time and place - a reminiscence (R.C. Hayes). Eiby, G. 21(3)	204

PLANNING

Earthquake disaster response planning: an engineering overview. Steinbrugge, K.V. 8(2)	114
Earthquake fault movement and town planning. Hopkins, D.C. 20(2)	79
Planning for disaster. Hodge, W.C. 22(4)	239
The influence of earthquake fault-lines on town planning. Moss, P.J. 20(2)	84
The insurance industry's role in town planning. Fowler, M. 23(3)	165
The roles of central and local government in pre-disaster planning. O'Dea, Sir P. 11(1)	30
The social implications of earthquake predictions and warnings on and for organisations. Britton, N.R. 11(1)	15

POLICING *see* Law

PRESTRESSED CONCRETE

A review of the seismic resistance of prestressed concrete. Blakeley, R.W.G.: Park, R.: Shepherd, R. 3(1)	3
Aspects of the FIP recommendations for design of aseismic prestressed concrete structures. Inomata, S. 9(3)	159
Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading: Unit 1 test results. Park, R.: Thompson, K.J. 6(4)	158
Behaviour of cast in situ reinforced concrete frames incorporating precast prestressed concrete beam shells subjected to seismic loading. Park, R.: Bull, D.K. 17(4)	223
Codes for seismic design of prestressed concrete. Williamson, K.E. 2(3)	277
Design of seismic resistant prestressed concrete structures. Andrews, A.L. 9(3)	175
Detailing of prestressed concrete piles for ductility. Park, R.: Priestley, M.J.N.: Falconer, T.J.: Pam Hoat Joen. 17(4)	251
Ductility of prestressed concrete members. Blakeley, R.W.G.: Park, R. 4(1)	145
Epoxy injection for crack repair. Evans, W.V. 3(4)	179
Hysteretic restoring force characteristics of unbonded prestressed concrete structure under earthquake loads. Nishiyama, M.: Mugurama, H.: Watanabe, F. 22(2)	112
Prestressed concrete seismic design. Williamson, K.E. 2(3)	251
Prestressed concrete seismic design. Blakeley, R.W.G. 6(1)	2
Progress report on cyclic load tests on prestressed partially prestressed and reinforced concrete interior beam-column assemblies. Park, R.: Thompson, K.J. 8(1)	12
Recommendations for the design and detailing of ductile prestressed concrete frames for seismic loading prepared by the Seismic Committee of the N.Z. Prestressed Concrete Institute. 9(2)	89
Seismic design of prestressed concrete buildings. Nishiyama, M. 23(4)	288

Some recent research in New Zealand into aspects of seismic resistance of prestressed concrete frames. Park, R.: Thompson, K.J. 9(3)	167
Stress-strain model for prestressing steel with cyclic loading. Thompson, K.J.: Park, R. 11(4)	209
Tauranga Harbour crossing, Stella Passage bridge - seismic design. Bloxam, M.J.: North, P.J. 23(3)	220
Tests on structural concrete beam-column joints with intermediate column bars. Park, R.: Yeoh Sik Keong. 12(3)	189
The New Zealand Loadings Code and its application to the design of seismic resistant prestressed concrete structures. Butcher, G.W. 9(3)	162
Theorisation of structural behaviour with a view to defining resistance and ultimate deformability. Park, R. 6(2)	52

RAILWAYS

Damage to railway track. (<i>Inangahua earthquake, 1968.</i>) Duckworth, W.J.H. 2(1)	59
Estimation of seismic motion and damage to structures for new bullet trains. Yutaka Nakamura: Hidehiko Abe. 17(2)	121
Inangahua earthquake damage on railways. (<i>Inangahua earthquake, 1968.</i>) Duckworth, W.J.H. 1(2)	12
Present status of the Railway Technical Research Institute and seismic research and designing in the Japanese National Railways. Tatsuo Nishiki. 3(4)	143

RECONNAISSANCE REPORTS

Discussion - the Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE reconnaissance team. (23(1), 1-78) Gates, J.H. 23(4)	322
Earthquake of 7 December 1988, Spitak, Armenia: Report of the NZNSEE team visit of 1989. Wood, P.R.: Berrill, J.B.: Gillon, N.R.: North, P.J. 26(3)	253
Earthquake reconnaissance report. Damage to the power generation and transmission facilities in the Loma Prieta earthquake of 17 October 1989. Tan Pham. 25(1)	3
Edgecumbe earthquake: reconnaissance report. Pender, M.J.: Robertson, T.W. 20(3)	201
NZNSEE reconnaissance teams. 9(2)	132
NZNSEE Engineering reconnaissance manual. 15(3)	164
Observations of the 1989 Loma Prieta earthquake. Marks, P. 23(4)	235
Reconnaissance field investigation of the Landers earthquake (Ms 7.5) of June 28, 1992, San Bernadino County, California, USA. Berryman, K. 25(3)	230
Reconnaissance report on the Weber earthquake - 13 May 1990. Johnstone, P.G.: Potangaroa, R. 26(2)	222
The Loma Prieta, California, earthquake of October 17, 1989: report of the NZNSEE team. Shephard, R.B.: Wood, P.R.: Berrill, J.B.: Gillon, N.R.: North, P.J.: Perry, A.K.: Bent, D.P. 23(1)	1
The Philippines earthquake of July 16, 1990 Report on field visit by the NZNSEE Reconnaissance Team. Hopkins, D.C.: Clark, W.D.: Matuschka, T.: Sinclair, J.C. 24(1)	3
The San Antonio, Chile, earthquake of 3 March 1985. Connor, I.N. 18(2)	128
The September 1985 Mexico Earthquake: Preliminary report of the New Zealand reconnaissance team. 18(4)	291

The September 1985 Mexico earthquakes: final report of the New Zealand reconnaissance team. 21(1)	3
-------------------------------------------------------------------------------------------------------------	---

RECONSTRUCTION *see* Earthquake Damage

REFURBISHMENT AND RETROFITTING (and *see* Earthquake Risk Buildings)

A philosophy for improving old buildings to resist earthquakes. Hollings, J.P. 7(2)	78
Aspects of high earthquake risk government buildings. Sinclair, D. 7(2)	85
Case studies: earthquake risk buildings. <i>See</i> Earthquake Risk Buildings.	
Comparative study of four passive energy dissipation systems. Aiken, I.D.: Nims, D.K.: Kelly, J.M. 25(3)	175
Earthquake risk buildings in Wellington. Bentley, R.J. 11(3)	200
Earthquake strengthening of old masonry with reference to the Auckland Ferry Building. Gurley, C.R.: Nicholls, J.S.F. 15(4)	199
Estimation of seismic motion and damage to structures for new bullet trains. Yutaka Nakamura: Hidehiko Abe. 17(2)	121
NZ contributions to the international workshop on the seismic design and retrofitting of reinforced concrete bridges, Bormio, Italy, April 2-5, 1991. Park, R.: Chapman, H.E.: Cormack, L.G.: North, P.J. 24(2)	139
NZNSEE discussion group on the seismic design of bridges. Section 12: Strengthening of bridges for seismic loads. McGuire, J.F.: Fisher, R.W.: Stanford, P.R.: North, P.J. 13(3)	308
Our old buildings can be safe in earthquake. Smith, I.C. 12(4)	289
Performance assessment of damaged bridge bents after the Loma Prieta earthquake. Priestley, M.J.N.: Seible, F. 25(1)	44
Refurbishing earthquake risk buildings in U.S.A. Leadbeater, D.B. 14(2)	43
Research into seismic retrofit of reinforced concrete bridge columns. Priestley, M.J.N.: Seible, F. 25(3)	203
Seismic strengthening of existing reinforced concrete buildings in Japan. Shunsuke Sugano. 14(4)	209
Some aspects of the strengthening of earthquake risk buildings. Toomath, W. 12(4)	287
The behaviour, overview of damage and retrofit of steel buildings after the earthquakes of September 1985. Martinez-Romero, E. 20(1)	30
The local authority engineer and high earthquake risk buildings. Grigg, A.N. 7(2)	81
The need for a strengthening code. Bluck, B.C. 7(2)	88

REINFORCED CONCRETE (includes high strength concrete)

A comparison of the behaviour of reinforced concrete beam-column joints designed for ductility and limited ductility. Park, R.: Dai Ruitong. 21(4)	255
A consideration of P-delta effects in ductile reinforced concrete frames. Paulay, T. 11(3)	151
A critical look at the design of reinforced concrete for ductility. McKenzie, G.H.F. 2(3)	295
A method for the evaluation of the seismic capacity of existing reinforced concrete buildings in Japan. Hiroyuki Aoyama. 14(3)	105

- A note on the earthquake performance of reinforced concrete shear walls. Steinbrugge, K.V.: Degenkolb, H.J. 2(2) 193
- A procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height (and *see* Errata). Williams, R.L. 8(4) 260
- A reinforced concrete building in Wellington. Hollings, J.P. 2(4) 420
- A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures. Goodsir, W.J.: Paulay, T.: Carr, A.J. 16(3) . . . 185
- An application of capacity design philosophy to gravity load dominated ductile reinforced concrete frames. Paulay, T. 11(1) 50
- An application of spectral techniques to inelastic seismic response predictions. Shepherd, R.: McConnel, R.E. 3(4) 173
- An estimation method for seismic effects of reinforced concrete non-structural walls to structural frame members. Ohkubo, M. 22(2) 90
- Analysis and design of a base-isolated reinforced concrete frame building. Megget, L.M. 11(4) 245
- Anchorage of transverse reinforcement in rectangular reinforced concrete columns in seismic design. Tanaka, H.: Park, R.: McNamee, B. 18(2) 165
- Aseismic design of 24 storey hotel "De Luxe", Skopje. Velkov, M. 8(2) 128
- Assessment of seismic performance characteristics of reinforced concrete buildings constructed between 1936 and 1975. Brunson, D.R.: Priestley, M.J.N. 17(3) 163
- Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading: Unit 1 test results. Park, R.: Thompson, K.J. 6(4) 158
- Behaviour of cast in situ reinforced concrete frames incorporating precast prestressed concrete beam shells subjected to seismic loading. Park, R.: Bull, D.K. 17(4) 223
- Behaviour of ductile hollow reinforced concrete columns. Mander, J.B.: Priestley, M.J.N.: Park, R. 16(4) 273
- Biaxial flexure and axial load interaction in short rectangular reinforced concrete columns. Row, D.G.: Paulay, T. 6(3) 110
- Book review - Reinforced Concrete Structures, by R.Park and T.Paulay. Kolston, D. 8(4) 291
- Book review - Seismic design of reinforced concrete and masonry buildings. Hopkins, D.C. 25(4) 362
- Capacity design of reinforced concrete frames for ductile earthquake performance. Armstrong, I.C. 5(4) . . . 133
- Code provisions for confining steel in potential plastic hinge regions of columns in seismic design. Park, R.: Priestley, M.J.N. 13(1) 60
- Comparison of recent New Zealand and United States seismic design provisions for reinforced concrete beam-column joints and test results from four units designed according to the New Zealand code. Park, R.: Milburn, J.R. 16(1) 3
- Cost effectiveness of code base shear requirements for reinforced concrete frame structures. Elms, D.G.: Silvester, D. 11(2) 85
- Cyclic behaviour of exterior reinforced concrete beam-column joints. Megget, L.M. 7(1) 27
- Cyclic load testing of three haunched reinforced concrete beam-column assemblies. Thurston, S.J. 15(3) 141
- Cyclic load testing of two refined reinforced concrete beam-column joints. Blakeley, R.W.G.: Edmonds, F.D.: Megget, L.M.: Wood, J.H. 12(3) 238
- Cyclic testing of a haunched reinforced concrete beam. Thurston, S.J.: Charleson, A.W. 12(1) 67
- Damage to freeway structures in the San Fernando earthquake. Wood, J.H.: Jennings, P.C. 4(3) 347
- Design of a curved 414m long continuous concrete railway bridge to resist earthquake motions. Jury, R.D.: Hollings, J.P.: Catley, T.J. 22(1) 50
- Developments in the design of ductile reinforced concrete frames. Paulay, T. 12(1) 35
- Diagonal beam reinforcing for ductile frames. Buchanan, A.H. 12(4) 346
- Discussion - A consideration of P-delta effects in ductile reinforced concrete frames, by T. Paulay (Vol 11(3)). Andrews, A.L. 11(3) 196
- Discussion - A consideration of P-Delta effects in ductile reinforced concrete frames, by T. Paulay (Vol 11, No. 3) Andrews, A.L. 12(4) 357
- Discussion - A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures, by Goodsir, W.J., Paulay, T. and Carr, A.J. Williams, R.L.: Otani, S. 16(4) 345
- Discussion - Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames, by T. Paulay (Vol 9(4)). Williams, R.L. 10(3) 160
- Discussion - Seismic resistance of reinforced concrete masonry shear walls with high steel percentages, by M.J.N. Priestley (Vol 10(1)). Glogau, O.A. 11(1) 70
- Discussion of paper 'Comparison of recent New Zealand United States seismic design provisions for reinforced concrete beam-column joints and test results for four units designed according to the New Zealand Code', by R Park & J R Milburn. Fenwick, R.C.: Hopkins, D.C. 17(1) 69
- Discussion: Capacity design of reinforced concrete frames for ductile earthquake performance, by I.C. Armstrong (5(4)). Paulay, T. 6(1) 46
- Ductile reinforced concrete frames - some comments on the special provisions for seismic design of ACI 318-71 and on capacity design. Park, R.: Paulay, T. 8(1) 70
- Editorial. McKenzie, D.S. 6(3) 95
- Effect of wall base rotation on behaviour of reinforced concrete frame-wall building. Daisuke Kato: Shunsuke Otani: Hideo Katsumata: Hiroyuki Aoyama. 17(2) 106
- Effects of hoop reinforcement in steel and reinforced concrete composite sections. Suzuki, T.: Takiguchi, K.: Ichinose, T.: Okamoto, T. 17(3) 198
- Emergency guideline for classification of risk levels of earthquake damaged reinforced concrete buildings. Shunsuke Otani. 21(4) 279
- Epoxy injection for crack repair. Evans, W.V. 3(4) 179
- Errata - amendments to Procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height, by R.L.Williams. Vol 8. No.4 9(1) 88
- Evaluation of shear and flexural deformations of flexural type shear walls. Hisahiro Hiraishi. 17(2) 135
- Experimental study on five-story full size apartment house of reinforced concrete walled frames. Yorihiro Ohsaki: Makoto Watabe: Yutaka Magsushima. 4(3) 377
- Full-strength butt welds of reinforcing bars by the pressure-gas process. Armstrong, I.C. 4(2) 270

Inelastic analysis of the Imperial County Services Building. Moss, P.J.: Carr, A.J.: Pardoen, G.C. 16(2) . . .	141
Inelastic behaviour of reinforced concrete members with cyclic loading. Kent, D.C.: Park, R. 4(1)	108
Lateral drift of reinforced concrete structures subjected to strong ground motion. Sozen, M.A. 16(2) . . .	107
Letter - Concrete filled tubular structures. Priestley, M.J.N. 18(3)	285
Letter - Editorial comment on Building Services. Rands, G.F. 7(1)	49
Letter - Editorial comment on Building Services. Blackwell, F.M. 7(1)	50
Masonry infill panels subjected to cyclic in-plane loading. Leuchars, J.M.: Scrivener, J.C. 9(2)	122
Maximum yield stress in reinforced concrete frames. Mackenzie, D.S. 2(3)	267
Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames. Paulay, T. 9(4)	205
Multidirectional seismic response of a curved highway bridge model. Williams, D.: Godden, W.G. 9(2)	97
Non-linear dynamic analysis and design concepts for RC beams under impulsive loads. Miyamoto, A.: King, M.E.: Fujii, M. 22(2)	98
NZNSSEE study group for structures of limited ductility. <i>See</i> NZNSSEE.	
NZ contributions to the international workshop on the seismic design and retrofitting of reinforced concrete bridges, Bormio, Italy, April 2-5, 1991. Park, R.: Chapman, H.E.: Cormack, L.G.: North, P.J. 24(2)	139
NZNSSEE discussion group on reinforced concrete walls and diaphragms. <i>See</i> NZNSSEE.	
NZNSSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. <i>See</i> NZNSSEE.	
Optimum design of reinforced concrete shear walls. Hutchison, D.L.: Van Geldermalsen, T.J. 17(3)	185
Post-elastic seismic response of a reinforced concrete frame. Walpole, W.R.: Shepherd, R. 1(2)	102
Prediction of the ultimate longitudinal compressive concrete strain at hoop fracture using energy considerations. Tanaka, H.: Park, R. 20(4)	290
Pressure-gas butt welding of reinforcing bars. Armstrong, I.C.: Page, W.J. 2(3)	329
Progress report on cyclic load tests on prestressed partially prestressed and reinforced concrete interior beam-column assemblies. Park, R.: Thompson, K.J. 8(1)	12
Recent developments in seismic design of reinforced concrete buildings in Japan. Aoyama, H. 24(4)	333
Reinforced concrete beam-column joints for seismic loading. Fenwick, R.C.: Irvine, H.M. 10(3)	121
Reinforced concrete beam-column joints for seismic loading. Fenwick, R.C.: Irvine, H.M. 10(4)	174
Reinforced concrete seismic design. Hollings, J.P. 2(3)	217
Research into seismic retrofit of reinforced concrete bridge columns. Priestley, M.J.N.: Seible, F. 25(3)	203
Response of a reinforced concrete shear wall structure during the 1972 Managua earthquake. Bertero, V.V.: Mahin, S.A.: Hollings, J. 7(3)	95
Response of ductile reinforced concrete frames located in Zone C. Paulay, T.: Carr, A.J.: Tompkins, D.N. 13(3)	209
Review of code developments for earthquake resistant design of concrete structures in New Zealand. Park, R. 14(4)	177
Seismic behaviour of a reinforced concrete portal frame sustaining gravity loads. Megget, L.M.: Fenwick, R.C. 22(1)	39
Seismic design in reinforced concrete: the state of the art in New Zealand. Paulay, T. 21(3)	208
Seismic design of public buildings. Shephard, R.B.: Glogau, O.A. 2(4)	391
Seismic performance of two full-size reinforced concrete beam-column joint units. Blakeley, R.W.G.: Megget, L.M.: Priestley, M.J.N. 8(1)	38
Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. Priestley, M.J.N. 10(1)	1
Seismic resistant joints for reinforced concrete structures. Fenwick, R.C. 14(3)	145
Seismic strengthening of existing reinforced concrete buildings in Japan. Shunsuke Sugano. 14(4)	209
Shear reinforcement of reinforced concrete inelastic interior beam-column joints. Ichinose, T. 20(2)	116
Some comments on reinforced concrete structures forming column hinge mechanisms. Kelly, T.E. 10(4)	186
Steady state vibration tests of a six storey reinforced concrete building. Reay, A.M.: Shepherd, R. 4(1)	94
Strength and ductility in reinforced concrete frames designed with Mexican codes. Rodriguez, M. 23(3)	184
Strength degradation of concrete beams under cyclic loading. Fenwick, R.C. 16(1)	25
Tests on an interior reinforced concrete beam-column joint. Park, R.: Gaerty, L.: Stevenson, E.C. 14(2)	81
The behaviour of exterior beam-column joints. Paulay, T.: Scarpas, A. 14(3)	131
The behaviour of reinforced concrete beams under cyclic loading. Fenwick, R.C.: Fong, A. 12(2)	158
The capacity design of reinforced concrete hybrid structures for multistorey buildings. Paulay, T.: Goodsir, W.J. 19(1)	1
The development of the design of the ANZ Head Office building, Lambton Quay, Wellington. Sharpe, R.D.: Binney, J.R.: McNaughton, D.J. 12(3)	204
The effects of large displacements on the earthquake response of tall concrete frame structures. Moss, P.J.: Carr, A.J. 13(4)	317
The energy dissipation effects of redundant members in silos under earthquakes. Li Zhiming: Geng Shujiang. 20(4)	269
The seismic performance of steel encased reinforced concrete bridge piles. Park, R.J.T.: Priestley, M.J.N.: Walpole, W.R. 16(2)	123
The seismic response of inelastic structures. Sharpe, R.D.: Carr, A.J. 8(3)	192
The shear strength of shear walls. Paulay, T. 3(4)	148
The use of Grade 380 steel for transverse confirming reinforcement in columns. Zahn, F.A.: Park, R.: Priestley, M.J.N. 20(2)	99
Theorisation of structural behaviour with a view to defining resistance and ultimate deformability. Park, R. 6(2)	52
Uniaxial dynamic analysis of a six storey reinforced concrete framed structure. Kelly, T.E. 10(1)	37
United States/New Zealand/Japan/China collaborative research project on the seismic design of reinforced concrete beam-column-slab joints. Park, R.: Hopkins, D.C. 22(2)	122

RESEARCH (includes testing)

A comparison of the behaviour of reinforced concrete beam-column joints designed for ductility and limited ductility. Park, R.: Dai Ruitong. 21(4)	255
--------------------------------------------------------------------------------------------------------------------------------------------------------------	-----

- A review of the seismic resistance of prestressed concrete. Blakeley, R.W.G.: Park, R.: Shepherd, R. 3(1) 3
- A simulated earthquake test of a timber house. Tracey, W.J. 2(3) 289
- American Geological Institute bibliographic data bank. 3(1) 26
- Anchorage of transverse reinforcement in rectangular reinforced concrete columns in seismic design. Tanaka, H.: Park, R.: McNamee, B. 18(2) 165
- Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading: Unit 1 test results. Park, R.: Thompson, K.J. 6(4) 158
- Behaviour of cast in situ reinforced concrete frames incorporating precast prestressed concrete beam shells subjected to seismic loading. Park, R.: Bull, D.K. 17(4) 223
- Behaviour of ductile hollow reinforced concrete columns. Mander, J.B.: Priestley, M.J.N.: Park, R. 16(4) 273
- Behaviour of steel beam-column connections, made using bolted end plates. Johnstone, N.D.: Walpole, W.R. 15(2) 82
- Brief review of modern earthquake engineering. Ferry Borges, J.: Despeyroux, J.: Maeda, Y.: Mazilu, P.: Robinson, J.R. 4(3) 397
- Building research in the School of Architecture. Thompson, R.M. 2(4) 472
- Buildings: research and development needs. Hutchison, D.L. 15(2) 93
- Calculating static deformations from quick-release accelerograms. Douglas, B.M.: Maragakis, E.A.: Nath, B. 23(4) 239
- Code provisions for confining steel in potential plastic hinge regions of columns in seismic design. Park, R.: Priestley, M.J.N. 13(1) 60
- Comparative analyses of a multi-storey frame and wall using the current and draft loading codes. Fenwick, R.C.: Davidson, B.J. 22(4) 181
- Cyclic behaviour of exterior reinforced concrete beam-column joints. Megget, L.M. 7(1) 27
- Cyclic load testing of three haunched reinforced concrete beam-column assemblies. Thurston, S.J. 15(3) 141
- Cyclic load testing of two refined reinforced concrete beam-column joints. Blakeley, R.W.G.: Edmonds, F.D.: Megget, L.M.: Wood, J.H. 12(3) 238
- Cyclic loading tests of slender concrete masonry shear walls. Priestley, M.J.N.: Elder, D. McG. 15(1) 3
- Cyclic loading tests on steel portal frame knee joints. Beamish, M.J. 20(1) 42
- Cyclic testing of a brick wall strengthened with a plaster coating of glass reinforced cement. Hutchison, D.L.: Yong, P.M.F. 15(4) 185
- Cyclic testing of a haunched reinforced concrete beam. Thurston, S.J.: Charleson, A.W. 12(1) 67
- Cyclic tests on masonry piers. Mayes, R.L.: Mostaghel, N.M.: Clough, R.W.: Dickey, W.L. 7(3) 105
- D.S.I.R. microzoning programme. Adams, R.D. 2(3) 282
- Detailing of prestressed concrete piles for ductility. Park, R.: Priestley, M.J.N.: Falconer, T.J.: Pam Hoat Joen. 17(4) 251
- Ductility of confined concrete masonry shear walls. Priestley, M.J.N. 15(1) 22
- Ductility of unconfined masonry shear walls. Priestley, M.J.N. 14(1) 12
- Dynamic performance of brick masonry veneer panels. Priestley, M.J.N.: Thorby, P.N.: McLarin, M.W.: Bridgeman, D.O. 12(4) 314
- Dynamic tests on PTFE sliding layers under earthquake conditions. Tyler, R.G. 10(3) 129
- Earthquake engineering research and practice in Mexico after the 1985 earthquakes. Esteva, L. 20(3) 159
- Earthquake engineering research at the Papua and New Guinea Institute of Higher Technical Education. Boyce, W.H. 2(4) 482
- Earthquake engineering research at the University of Auckland. Martin, G.R. 2(4) 474
- Earthquake engineering research at the University of Canterbury. Shepherd, R. 2(2) 186
- Earthquake-soil structure interaction, spring and dashpot models, and real soil behaviour. Pender, M.J. 16(4) 320
- Effects of hoop reinforcement in steel and reinforced concrete composite sections. Suzuki, T.: Takiguchi, K.: Ichinose, T.: Okamoto, T. 17(3) 198
- Errata - Sliding-vibrating response of elastic structures, Vol 21 No. 3 September 1988 pp 190-197. Fu Yu-An. 22(1) 59
- Evaluation of ductility of structures and structural assemblages from laboratory testing. Park, R. 22(3) 155
- Evaluation of sediment properties in the Lower Hutt and Porirua areas by means of cone and seismic cone penetration tests. Stephenson, W.R.: Barker, P.R. 25(4) 265
- Evaluation of shear and flexural deformations of flexural type shear walls. Hisahiro Hiraishi. 17(2) 135
- Experimental study of lead and elastomeric dampers for base isolation systems in laminated neoprene bearings. Kelly, J.M.: Hodder, S.B. 15(2) 53
- Experimental study on five-storey full size apartment house of reinforced concrete walled frames. Yorihiro Ohsaki: Makoto Watabe: Yutaka Magsushima. 4(3) 377
- Further notes on a steel energy-absorbing element for braced frameworks. Tyler, R.G. 18(3) 270
- Geophysics at the University of Auckland. Kibblewhite, A.C. 2(4) 459
- Geophysics at the Victoria University of Wellington. Evison, F.F. 2(4) 470
- Identification of research needs for improving the aseismic design of building structures. Bertero, V.V. 9(1) 1
- Inelastic behaviour of reinforced concrete members with cyclic loading. Kent, D.C.: Park, R. 4(1) 108
- Motions of rigid bodies and criteria for overturning by earthquake excitations. Yuji Ishiyama. 17(1) 24
- Prediction of the ultimate longitudinal compressive concrete strain at hoop fracture using energy considerations. Tanaka, H.: Park, R. 20(4) 290
- Present status of the Railway Technical Research Institute and seismic research and designing in the Japanese National Railways. Tatsuo Nishiki. 3(4) 143
- Progress in earth science research of benefit to the earthquake insurance industry. Berryman, K.R.: Darby, D.J. 23(2) 130
- Progress report on cyclic load tests on prestressed partially prestressed and reinforced concrete interior beam-column assemblies. Park, R.: Thompson, K.J. 8(1) 12
- Recent developments in devices for seismic isolation. Cousins, W.J.: Robinson, W.H.: McVerry, G.H. 25(3) 167
- Research reduces risks. Hopkins, D.C. 23(2) 121
- Research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(3) 154
- Review of current earthquake engineering research in New Zealand. Moss, P.J. 20(2) 91
- Rocking motion of a slender elastic body on rigid floor. Ichinose, T. 19(1) 18

Seismic behaviour of a reinforced concrete portal frame sustaining gravity loads. Megget, L.M.: Fenwick, R.C. 22(1)	39
Seismic code development for steel structures. Krawinkler, H. 20(2)	127
Seismic hazard analysis and design loads. Berrill, J.B. 18(2)	139
Seismic performance of two full-size reinforced concrete beam-column joint units. Blakeley, R.W.G.: Megget, L.M.: Priestley, M.J.N. 8(1)	38
Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. Priestley, M.J.N. 10(1)	1
Seismic resistant joints for reinforced concrete structures. Fenwick, R.C. 14(3)	145
Seismic response of structures free to rock on their foundations. Priestley, M.J.N.: Evison, R.J.: Carr, A.J. 11(3)	141
Shake table tests of an industrial building. Takanashi, K.: Ohi, K.: Sakai, Y. 20(1)	53
Sliding-vibrating responses of elastic structures (and <i>see</i> Errata). Fu Yu-An. 21(3)	190
Some limitations of modal analysis in seismic design. Shepherd, R. 2(3)	284
Some recent research in New Zealand into aspects of seismic resistance of prestressed concrete frames. Park, R.: Thompson, K.J. 9(3)	167
Steady state vibration tests of a six storey reinforced concrete building. Reay, A.M.: Shepherd, R. 4(1)	94
Stress-strain model for grade 275 reinforcing steel with cyclic loading. Thompson, K.J.: Park, R. 11(2)	101
Technical Note: Priorities for research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(4)	220
Tests on an interior reinforced concrete beam-column joint. Park, R.: Gaerty, L.: Stevenson, E.C. 14(2)	81
Tests on structural concrete beam-column joints with intermediate column bars. Park, R.: Yeoh Sik Keong. 12(3)	189
The behaviour of exterior beam-column joints. Paulay, T.: Scarpas, A. 14(3)	131
The behaviour of reinforced concrete beams under cyclic loading. Fenwick, R.C.: Fong, A. 12(2)	158
The cyclic yield response of a steel star plate cruciform joint. Croad, R.N.: Mead, F.H.: Shepherd, R. 8(3)	204
The ductility of structural walls. Paulay, T.: Goodsir, W.J. 18(3)	250
The performance of a ductile moment resisting connection between a precast concrete column and a timber beam. Dean, J.A. 19(2)	111
The shear strength of shear walls. Paulay, T. 3(4)	148
United States/New Zealand/Japan/China collaborative research project on the seismic design of reinforced concrete beam-column-slab joints. Park, R.: Hopkins, D.C. 22(2)	122

RETROFITTING *see* Refurbishment

ROADING

Damage to freeway structures in the San Fernando earthquake. Wood, J.H.: Jennings, P.C. 4(3)	347
Earthquake damage to roads and bridges, Madang, T.P.N.G. - November 1970. Ellison, B.K. 4(2)	243
Inangahua earthquake 1968 damage to State Highways. Douglas, J.S. 1(2)	49
Inangahua earthquake 1968 damage to state highways. Douglas, J.S. 2(1)	47

Structural damage aspects of the April 22, 1991 Costa Rica earthquake. Priestley, M.J.N. 25(1)	17
----------------------------------------------------------------------------------------------------------	----

SEISMIC ANALYSIS AND RESPONSE

A note on the earthquake performance of reinforced concrete shear walls. Steinbrugge, K.V.: Degenkolb, H.J. 2(2)	193
A preliminary analytic evaluation of the seismic response of structural walls failing in a shear mode. Robinson, L.M. 19(3)	167
A procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height (and <i>see</i> Errata). Williams, R.L. 8(4)	260
A reinforced concrete building in Wellington. Hollings, J.P. 2(4)	420
A simulated earthquake test of a timber house. Tracey, W.J. 2(3)	289
A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures. Goodsir, W.J.: Paulay, T.: Carr, A.J. 16(3)	185
An application of spectral techniques to inelastic seismic response predictions. Shepherd, R.: McConnel, R.E. 3(4)	173
Analysis and design of a base-isolated reinforced concrete frame building. Megget, L.M. 11(4)	245
Aspects of the analysis of frame-panel interaction. Moss, P.J.: Carr, A.J. 4(1)	126
Assessment of earthquake response from modal analysis. McKenzie, G.H.F. 3(2)	89
Behaviour of ductile hollow reinforced concrete columns. Mander, J.B.: Priestley, M.J.N.: Park, R. 16(4)	273
Behaviour of reinforced masonry shear walls under cyclic loading. Scrivener, J.C.: Williams, D. 4(2)	316
Biaxial flexure and axial load interaction in short rectangular reinforced concrete columns. Row, D.G.: Paulay, T. 6(3)	110
Comparison of remote site and basement records as excitation of the Vogel Building. McVerry, G.H. 17(1)	3
Discussion - Assessment of earthquake response from modal analysis, by G.H.F. McKenzie. Shepherd, R. 3(2)	90
Discussion - Seismic response of low-rise buildings, by Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3). Clifton, G.C. 20(1)	66
Ductility of prestressed concrete members. Blakeley, R.W.G.: Park, R. 4(1)	145
Earthquake induced resonant motion of alluvium. Stephenson, W.R. 7(3)	144
Earthquake response of high voltage circuit breakers with non-linear force-deflection characteristics. Mayes, R.L.: Hitchcock, H.C. 4(2)	301
Errata - amendments to Procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height, by R.L. Williams. Vol 8. No.4 9(1)	88
Estimation of base isolated structure responses. Lee, D.M.: Medland, I.C. 11(4)	234
Evaluation of earthquake response of low-rise structures using design codes and local specifications. Hutchinson, G.L.: Navidi, A. 16(4)	331
Evaluation of shear and flexural deformations of flexural type shear walls. Hisahiro Hiraishi. 17(2)	135
Floor response of yielding structures. Kelly, T.E. 11(4)	255
Inelastic analysis of the Imperial County Services Building. Moss, P.J.: Carr, A.J.: Pardeon, G.C. 16(2)	141
Inelastic dynamic analysis of steel structures. Lord, J.: Hoerner, J.B.: Zayed, M. 8(4)	273

Influence of foundation compliance on the seismic response of bridge piers. Priestley, M.J.N.: Park, R.: Heng, N.K. 12(1)	22
Japanese practice for estimating the expected maximum earthquake force at a nuclear power plant site. Syun'itiro Omote: Yorihiro Ohsaki: Toshihiro Kakimi: Tokihoko Matsuda. 13(1)	37
Motions of rigid bodies and criteria for overturning by earthquake excitations. Yuji Ishiyama. 17(1)	24
Multidirectional seismic response of a curved highway bridge model. Williams, D.: Godden, W.G. 9(2)	97
New Zealand seismic hazard analysis. Matuschka, T.: Berryman, K.R.O: O'Leary, A.J.: McVerry, G.H.: Mulholland, W.M.: Skinner, R.I. 18(4)	313
Non-linear dynamic analysis and design concepts for RC beams under impulsive loads. Miyamoto, A.: King, M.E.: Fujii, M. 22(2)	98
Normal modes of a "cylindrical valley" of alluvium. Stephenson, W.R. 22(2)	76
NZNSSE discussion group on seismic design of ductile moment resisting reinforced concrete frames (and <i>see</i> NZNSSE). Section G Columns - evaluation of actions. Paulay, T. 10(2)	85
NZNSSE study group for the seismic design of steel structures (and <i>see</i> NZNSSE). Section B Analysis and design methods. Patton, R.N. 18(4)	329
Post-elastic seismic response of a reinforced concrete frame. Walpole, W.R.: Shepherd, R. 1(2)	102
Prediction of post-elastic seismic response of structures by a mode superposition technique. Gillies, A.G.: Shepherd, R. 16(3)	222
Preliminary tests on an energy absorbing element for braced structures under earthquake loading. Tyler, R.G. 16(3)	201
Report on the second (1978) microzonation conference. Bentley, R.J. 12(1)	72
Seismic analysis of a highway bridge considering soil-structure interaction effects. Iwasaki, T.: Kawashima, K. 12(4)	305
Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators. Priestley, M.J.N.: Stockwell, M.J. 11(2)	110
Seismic forces in base-isolated masonry structures. Priestley, M.J.N.: Crosbie, R.L.: Carr, A.J. 10(2)	55
Seismic hazard analysis and design loads. Berrill, J.B. 18(2)	139
Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. Priestley, M.J.N. 10(1)	1
Seismic response of elevated water reservoirs. Hunt, B.: Priestley, M.J.N. 15(2)	68
Seismic response of low-rise buildings. Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3)	180
Seismic response of structures free to rock on their foundations. Priestley, M.J.N.: Evison, R.J.: Carr, A.J. 11(3)	141
Seismic shear loading at flexural capacity in cantilever wall structures. Blakeley, R.W.G.: Cooney, R.C.: Megget, L.M. 8(4)	278
Some comments on reinforced concrete structures forming column hinge mechanisms. Kelly, T.E. 10(4)	186
Structural examination of high rise buildings in Japan. Toshihiko Hisada. 1(1)	Unpaged
The effects of large displacements on the earthquake response of tall concrete frame structures. Moss, P.J.: Carr, A.J. 13(4)	317
The influence of bridge geometry on the seismic behaviour of bridges on isolating bearings. Moss, P.J.: Carr, A.J.: Cooke, N.: Tan Fun Kwai. 19(4)	255

The influence of non-geometric factors on the seismic behaviour of bridges on isolating bearings. Cooke, N.: Carr, A.J.: Moss, P.J.: Tan Fun Kwai. 19(4)	263
The seismic behaviour of plywood sheathed shearwalls. Dean, J.A.: Stewart W.G.: Carr, A.J. 19(1)	48
The seismic design of an industrial chimney with rocking base. Sharpe, R.D.: Skinner, R.I. 16(2)	98
The seismic response of inelastic structures. Sharpe, R.D.: Carr, A.J. 8(3)	192
The seismic response of nonstructural elements in buildings. Arnold, C. 24(4)	306
The static substructure method for dynamic analysis of structures. Menglin, L. 20(4)	264
Theorisation of structural behaviour with a view to defining resistance and ultimate deformability. Park, R. 6(2)	52
Three dimensional elastic dynamic analysis of a 985 foot high free-standing communications tower. Lord, J.: Zayed, M. 8(3)	222
Two dimensional nonlinear site response analyses. Larkin, T.: Marsh, J. 25(3)	222
Uniaxial dynamic analysis of a six storey reinforced concrete framed structure. Kelly, T.E. 10(1)	37
Union House - a cross braced structure with energy dissipators. Boardman, P.R.: Wood, B.J.: Carr, A.J. 16(2)	83

SEISMIC DESIGN and *see* Earthquake Resistant Structures

1975 Seminar on NZS 4203. <i>See</i> Standards.	
A base-isolation design using spherically-ended rollers and telescopic shock absorbers. Pham, L.T. 21(2)	135
A comparison of the behaviour of reinforced concrete beam-column joints designed for ductility and limited ductility. Park, R.: Dai Ruitong. 21(4)	255
A consideration of P-delta effects in ductile reinforced concrete frames. Paulay, T. 11(3)	151
A critical look at the design of reinforced concrete for ductility. McKenzie, G.H.F. 2(3)	295
A design criteria of beam-to-column joint panels. Kato, B. 7(1)	14
A general introduction to the seismic design problem. Garden, R.J.P. 2(3)	202
A method for the evaluation of the seismic capacity of existing reinforced concrete buildings in Japan. Hiroyuki Aoyama. 14(3)	105
A modified approach to earthquake resistant design of torsionally coupled buildings. Chandler, A.M.: Hutchison, G.L. 21(2)	140
A new draft code for seismic design of buildings in Indonesia. Fraser, I.A.N. 16(3)	247
A note about base shear. Andrews, A.L. 2(2)	171
A note on the earthquake performance of reinforced concrete shear walls. Steinbrugge, K.V.: Degenkolb, H.J. 2(2)	193
A preliminary analytic evaluation of the seismic response of structural walls failing in a shear mode. Robinson, L.M. 19(3)	167
A procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height (and <i>see</i> Errata). Williams, R.L. 8(4)	260
A reinforced concrete building in Wellington. Hollings, J.P. 2(4)	420
A review of the new code provisions for separation of elements and buildings. Blakeley, R.W.G. 7(3)	130
A review of the seismic resistance of prestressed concrete. Blakeley, R.W.G.: Park, R.: Shepherd, R. 3(1)	3

A simplified earthquake resistant design method for base isolated multistorey structures. Andriano, T.: Carr, A.J. 24(3)	238	Codes for seismic design of prestressed concrete. Williamson, K.E. 2(3)	277
A simulated earthquake test of a timber house. Tracey, W.J. 2(3)	289	Column strength requirements in multi-storey seismic frames. Blaikie, E.L. 22(3)	135
A study of the inelastic seismic response of reinforced concrete coupled frame-shear wall structures. Goodsir, W.J.: Paulay, T.: Carr, A.J. 16(3)	185	Comparative analyses of a multi-storey frame and wall using the current and draft loading codes. Fenwick, R.C.: Davidson, B.J. 22(4)	181
Advances in design of eccentrically braced frames. Popov, E.P.: Kasai, K.: Engelhardt, M.D. 20(1)	22	Comparative study of four passive energy dissipation systems. Aiken, I.D.: Nims, D.K.: Kelly, J.M. 25(3)	175
An application of capacity design philosophy to gravity load dominated ductile reinforced concrete frames. Paulay, T. 11(1)	50	Comparison of recent New Zealand and United States seismic design provisions for reinforced concrete beam-column joints and test results from four units designed according to the New Zealand code. Park, R.: Milburn, J.R. 16(1)	3
An application of spectral techniques to inelastic seismic response predictions. Shepherd, R.: McConnel, R.E. 3(4)	173	Comparison of remote site and basement records as excitation of the Vogel Building. McVerry, G.H. 17(1)	3
An economic solution for stabilising a slender arch roof. Spurr, D.D. 19(2)	93	Computer-aided structural analysis and design of the 37-storey Los Angeles Bonaventure Hotel. Nicoletti, J.P.: Jhaveri, D.P.: Emkin, L.Z.: Mesley, R.C. 12(3)	212
An estimation method for seismic effects of reinforced concrete non-structural walls to structural frame members. Ohkubo, M. 22(2)	90	Considerations for a "design" earthquake. Evans, G.L. 5(2)	47
Analysis and design of a base-isolated reinforced concrete frame building. Megget, L.M. 11(4)	245	Correspondence on base isolated structures. 12(4)	362
Anchorage of transverse reinforcement in rectangular reinforced concrete columns in seismic design. Tanaka, H.: Park, R.: McNamee, B. 18(2)	165	Cost effectiveness of code base shear requirements for reinforced concrete frame structures. Elms, D.G.: Silvester, D. 11(2)	85
Architectural detailing for earthquake movement. Toomath, S.W. 1(1)	Unpaged	Cyclic behaviour of exterior reinforced concrete beam-column joints. Megget, L.M. 7(1)	27
Architectural elements in earthquake, a review of design and construction practice in New Zealand. Hopkins, D.C.: Massey, W.E.: Pollard, J.L. 18(1)	21	Cyclic loading tests on steel portal frame knee joints. Beamish, M.J. 20(1)	42
Aseismic design of 24 storey hotel "De Luxe", Skopje. Velkov, M. 8(2)	128	Cyclic testing of a brick wall strengthened with a plaster coating of glass reinforced cement. Hutchison, D.L.: Yong, P.M.F. 15(4)	185
Aspects of the analysis of frame-panel interaction. Moss, P.J.: Carr, A.J. 4(1)	126	Damping in sliding structures by means of PTFE sliding joints. Tyler, R.G. 10(3)	139
Aspects of the FIP recommendations for design of aseismic prestressed concrete structures. Inomata, S. 9(3)	159	Dams and earthquakes in New Zealand. Hatrick, A.V. 11(2)	94
Assessment of earthquake response from modal analysis. McKenzie, G.H.F. 3(2)	89	Decisions theory in earthquake engineering. Rosenblueth, E. 5(1)	1
Assessment of seismic performance characteristics of reinforced concrete buildings constructed between 1936 and 1975. Brunson, D.R.: Priestley, M.J.N. 17(3)	163	Design lessons from recent destructive earthquakes. Skinner, R.I. 4(2)	234
Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading: Unit 1 test results. Park, R.: Thompson, K.J. 6(4)	158	Design of a curved 414m long continuous concrete railway bridge to resist earthquake motions. Jury, R.D.: Hollings, J.P.: Catley, T.J. 22(1)	50
Behaviour of cast in situ reinforced concrete frames incorporating precast prestressed concrete beam shells subjected to seismic loading. Park, R.: Bull, D.K. 17(4)	223	Design of an earthquake resisting building using precast concrete cross-braced panels and incorporating energy-absorbing devices. Matthewson, C.D.: Davey, R.A. 12(4)	340
Behaviour of ductile hollow reinforced concrete columns. Mander, J.B.: Priestley, M.J.N.: Park, R. 16(4)	273	Design of seismic resistant prestressed concrete structures. Andrews, A.L. 9(3)	175
Behaviour of lifts - the Wellington earthquake November 1, 1968. McKenzie, D.J. 2(3)	278	Design of shear walls for seismic resistance. Armstrong, I.C. 10(1)	17
Behaviour of reinforced masonry shear walls under cyclic loading. Scrivener, J.C.: Williams, D. 4(2)	316	Development of design procedures for the flexural strength and ductility of reinforced concrete bridge columns. Zahn, F.A.: Chapman, H.E.: Park, R.: Priestley, M.J.N. 19(3)	200
Behaviour of steel beam-column connections, made using bolted end plates. Johnstone, N.D.: Walpole, W.R. 15(2)	82	Developments in design of wood structures for earthquake resistance. Buchanan, A.H. 16(2)	156
Biaxial flexure and axial load interaction in short rectangular reinforced concrete columns. Row, D.G.: Paulay, T. 6(3)	110	Developments in the design of ductile reinforced concrete frames. Paulay, T. 12(1)	35
Book review - Seismic design of reinforced concrete and masonry buildings. Hopkins, D.C. 25(4)	362	Discussion - A consideration of P-delta effects in ductile reinforced concrete frames, by T. Paulay (Vol 11(3)). Andrews, A.L. 11(3)	196
Book review: Aseismic design analysis of buildings, by Kiyoshi Muto. Burns, R.J. 7(3)	147	Discussion - A consideration of P-Delta effects in ductile reinforced concrete frames, by T. Paulay (Vol 11, No. 3) Andrews, A.L. 12(4)	357
Building configuration: the architecture of seismic design. Arnold, C. 17(2)	83	Discussion - Assessment of earthquake response from modal analysis, by G.H.F. McKenzie. Shepherd, R. 3(2)	90
Capacity design of reinforced concrete frames for ductile earthquake performance. Armstrong, I.C. 5(4)	133		

Discussion - Design of Shear walls for seismic resistance, by I.C. Armstrong (Vol10(1)). Williams, R.L. 10(3)	159
Discussion - Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames, by T. Paulay (Vol 9(4)). Williams, R.L. 10(3)	160
Discussion - NZNSEE discussion group on the seismic design of bridges, Bulletin Vol 13(3). Rinne, J.E. 14(2)	97
Discussion - Real-time simulated earthquake motion of high rise structures, by J. Lord (Vol 3(3), p.195). McKenzie, G.H.F. 3(4)	183
Discussion - Seismic behaviour of unreinforced masonry walls, by M.J.N. Priestley, 18(2). Robinson, L.M. 19(1)	65
Discussion - Seismic design of public buildings, by R.B. Shephard and O.A. Glogau. Vol 2(4). Edwards, W.P. 3(2)	91
Discussion - Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators, by M.J.N. Priestley and M.J. Stockwell (Vol 11(2)). McKenzie, G.H.F. 11(3)	195
Discussion - Seismic resistance of brick masonry walls, by M.J.N. Priestley and D.O. Bridgeman. Williams, D. 8(3)	238
Discussion - Seismic resistance of reinforced concrete masonry shear walls with high steel percentages, by M.J.N. Priestley (Vol 10(1)). Glogau, O.A. 11(1)	70
Discussion - Seismic response of low-rise buildings, by Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3). Clifton, G.C. 20(1)	66
Discussion - Slenderness effects in earthquake resisting frames, by A.L. Andrews, Vol 10(3). Irvine, H.M.: Elms, D.G.: Buchanan, B.W. 11(1)	71
Discussion - Some aspects of shear wall design, by T. Paulay. Glogau, O.A. 5(4)	156
Discussion - The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea, by Jury, R.D., Hollings, J.P. and Fraser, I.A.N. McCue, K. 17(4)	292
Discussion of paper 'Comparison of recent New Zealand United States seismic design provisions for reinforced concrete beam-column joints and test results for four units designed according to the New Zealand Code', by R Park & J R Milburn. Fenwick, R.C.: Hopkins, D.C. 17(1)	69
Discussion: Capacity design of reinforced concrete frames for ductile earthquake performance, by I.C. Armstrong (5(4)). Paulay, T. 6(1)	46
Discussion: Reinforced masonry shear walls: cyclic load tests in contraflexure, by S.J. Thurston and D.L. Hutchison (Vol 15(1)). Priestley, M.J.N. 15(2)	97
Draft revision of NZS 4203:1984: seismic provisions. Hutchison, D.L.: Andrews, A.L.: Butcher, G.W.: Kolston, D. 19(3)	158
Ductile reinforced concrete frames - some comments on the special provisions for seismic design of ACI 318-71 and on capacity design. Park, R.: Paulay, T. 8(1)	70
Ductility of prestressed concrete members. Blakeley, R.W.G.: Park, R. 4(1)	145
Ductility of unconfined masonry shear walls. Priestley, M.J.N. 14(1)	12
Dynamic tests on PTFE sliding layers under earthquake conditions. Tyler, R.G. 10(3)	129
Earthquake damage at Edgecumbe and Kwarau Electricorp substations in the Bay of Plenty earthquake (and <i>see</i> Errata). Rutledge, A.L. 21(4)	247
Earthquake design of structures with brittle members and heavy artificial damping by the method of direct integration. Winthrop, D.A.: Hitchcock, H.C. 4(2)	294
Earthquake engineering research and practice in Mexico after the 1985 earthquakes. Esteva, L. 20(3)	159
Earthquake induced resonant motion of alluvium. Stephenson, W.R. 7(3)	144
Earthquake resistance of the "SCT" large panel building system. Fischinger, M.: Fajfar, P.: Capuder, F. 20(4)	281
Earthquake resistant design of cohesive earth slopes. Martin, G.R.: Taylor, P.W. 4(1)	51
Earthquake-induced pressures on a rigid wall structure. Wood, J.H. 8(3)	175
Earthquakes and tall buildings. Jennings, P.C. 3(2)	51
Earthquakes, landslides, and large dams in New Zealand. Adams, J. 14(2)	93
Eccentric beam to column junctions. Mead, F.H. 3(1)	24
Effect of wall base rotation on behaviour of reinforced concrete frame-wall building. Daisuke Kato: Shunsuke Otani: Hideo Katsumata: Hiroyuki Aoyama. 17(2)	106
Effects of hoop reinforcement in steel and reinforced concrete composite sections. Suzuki, T.: Takiguchi, K.: Ichinose, T.: Okamoto, T. 17(3)	198
Errata - amendments to Procedure for the analysis and design of ductile reinforced concrete frame buildings of moderate height, by R.L. Williams. Vol 8. No.4 9(1)	88
Estimation of base isolated structure responses. Lee, D.M.: Medland, I.C. 11(4)	234
Evaluation of ductility of structures and structural assemblages from laboratory testing. Park, R. 22(3)	155
Evaluation of shear and flexural deformations of flexural type shear walls. Hisahiro Hiraishi. 17(2)	135
Experimental study on five-story full size apartment house of reinforced concrete walled frames. Yorihiro Ohsaki: Makoto Watabe: Yutaka Magsushima. 4(3)	377
Foundations for capacity designed structures. Taylor, P.W.: Williams, R.L. 12(2)	101
Further comments on seismic design loads for bridges. Berrill, J.B.: Priestley, M.J.N.: Peek, R. 14(1)	3
High voltage circuit breaker supported on a base isolating tripod for earthquake protection. Safi, B.F.: Pham, L.T.: Busby, M.J. 22(3)	145
Horizontal timber diaphragms for wind and earthquake resistance. Smith, P.C.: Dowrick, D.J.: Dean, J.A. 19(2)	135
Hysteresis loops for timber structures. Dowrick, D.J. 19(2)	143
Hysteretic modelling of moment-resisting nailed timber joints. Kivell, B.T.: Moss, P.J.: Carr, A.J. 14(4)	233
Identification of research needs for improving the aseismic design of building structures. Bertero, V.V. 9(1)	1
Inelastic dynamic analysis of steel structures. Lord, J.: Hoerner, J.B.: Zayed, M. 8(4)	273
Inelastic dynamic analysis of two industrial buildings. Hutchison, D.L.: Spurr, D.D. 19(2)	83
Influence of foundation compliance on the seismic response of bridge piers. Priestley, M.J.N.: Park, R.: Heng, N.K. 12(1)	22
Lateral flexibility and seismic deflection estimates How good is good enough? Andrews, A.L. 1(1)	Unpaged
Letter - Editorial comment on Building Services. Rands, G.F. 7(1)	49

Letter - Editorial comment on Building Services. Blackwell, F.M. 7(1)	50	Prestressed concrete seismic design. Williamson, K.E. 2(3)	251
Letter - Lateral flexibility and seismic deflection estimates How good is good enough? by A.L. Andrews (Vol 1(1)). Crookes, S.I. 1(2)	21	Prestressed concrete seismic design. Blakeley, R.W.G. 6(1)	2
Masonry construction for earthquakes. Holmes, I.L. 1(1)	Unpaged	Progress report on cyclic load tests on prestressed partially prestressed and reinforced concrete interior beam-column assemblies. Park, R.: Thompson, K.J. 8(1)	12
Masonry infill panels subjected to cyclic in-plane loading. Leuchars, J.M.: Scrivener, J.C. 9(2)	122	Real-time simulated earthquake motion of high rise structures. Lord, J. 3(2)	95
Maximum yield stress in reinforced concrete frames. Mackenzie, D.S. 2(3)	267	Recent developments in seismic design of reinforced concrete buildings in Japan. Aoyama, H. 24(4)	333
Moment redistribution in continuous beams of earthquake resistant multistorey reinforced concrete frames. Paulay, T. 9(4)	205	Recommendations for the design and construction of base isolated structures. Blakeley, R.W.G.: Charleson, A.W.: Hitchcock, H.C.: Megget, L.M.: Priestley, M.J.N.: Sharpe, R.D.: Skinner, R.I. 12(2)	136
Motions of rigid bodies and criteria for overturning by earthquake excitations. Yuji Ishiyama. 17(1)	24	Recommendations for the design and detailing of ductile prestressed concrete frames for seismic loading prepared by the Seismic Committee of the N.Z. Prestressed Concrete Institute. 9(2)	89
Multidirectional seismic response of a curved highway bridge model. Williams, D.: Godden, W.G. 9(2)	97	Recommendations for the seismic design of petrochemical plants. Norton, J.A.: Gillies, A.G.: Edmonds, F.D. 15(2)	105
N.Z. Parliament Buildings seismic protection by base isolation. Poole, R.A.: Clendon, J.E. 25(3)	147	Reduction and distribution of lateral seismic inertia forces on base isolated multistorey structures. Andriono, T.: Carr, A.J. 24(3)	225
Nailed moment joints in timber structures. Bryant, A.H.: Gibson, J.A.: Mitchell, T.N.: Thurston, S.J. 14(4)	223	Reinforced concrete beam-column joints for seismic loading. Fenwick, R.C.: Irvine, H.M. 10(3)	121
Non-linear dynamic analysis and design concepts for RC beams under impulsive loads. Miyamoto, A.: King, M.E.: Fujii, M. 22(2)	98	Reinforced concrete beam-column joints for seismic loading. Fenwick, R.C.: Irvine, H.M. 10(4)	174
Normal modes of a "cylindrical valley" of alluvium. Stephenson, W.R. 22(2)	76	Reinforced concrete seismic design. Hollings, J.P. 2(3)	217
Notes on bridges and earthquakes. Wilson, J.B. 1(2)	92	Reinforced masonry - seismic behaviour and design. Scrivener, J.C. 5(4)	143
Notes on the New Zealand earthquake loading provisions. Kolston, D. 8(2)	102	Reinforced masonry shear walls: cyclic load tests in contraflexure. Thurston, S.J.: Hutchison, D.L. 15(1)	27
NZNSSEE study group for structures of limited ductility. <i>See</i> NZNSSEE.		Report on the second (1978) microzonation conference. Bentley, R.J. 12(1)	72
NZ contributions to the international workshop on the seismic design and retrofitting of reinforced concrete bridges, Bormio, Italy, April 2-5, 1991. Park, R.: Chapman, H.E.: Cormack, L.G.: North, P.J. 24(2)	139	Research into seismic retrofit of reinforced concrete bridge columns. Priestley, M.J.N.: Seible, F. 25(3)	203
NZNSSEE discussion group on reinforced concrete walls and diaphragms. <i>See</i> NZNSSEE.		Research requirements related to the design of seismic resistant highway bridges. Jennings, D.N. 15(3)	154
NZNSSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames. <i>See</i> NZNSSEE.		Response of ductile reinforced concrete frames located in Zone C. Paulay, T.: Carr, A.J.: Tompkins, D.N. 13(3)	209
NZNSSEE discussion group on the seismic design of bridges. <i>See</i> NZNSSEE.		Review of code developments for earthquake resistant design of concrete structures in New Zealand. Park, R. 14(4)	177
NZNSSEE study group for structures of limited ductility. <i>See</i> NZNSSEE.		Rocking motion of a slender elastic body on rigid floor. Ichinose, T. 19(1)	18
NZNSSEE study group for the seismic design of steel structures. <i>See</i> NZNSSEE.		Rubber bearings in base-isolated structures: a summary paper Tyler, R.G. 24(3)	251
On California structural steel seismic design. Popov, E.P. 20(1)	7	Second Conference on Tall Buildings in Seismic Regions. May 16 and 17, 1991, Los Angeles, California, U.S.A. Brunsdon, D.R. 24(3)	207
Optimum design of reinforced concrete shear walls. Hutchison, D.L.: Van Geldermalsen, T.J. 17(3)	185	Seismic behaviour of a reinforced concrete portal frame sustaining gravity loads. Megget, L.M.: Fenwick, R.C. 22(1)	39
Outline of earthquake provisions in the recently revised Japanese building code. Hiroyuki Aoyama. 14(2)	63	Seismic behaviour of unreinforced masonry walls. Priestley, M.J.N. 18(2)	191
P-delta actions in seismic resistant structures. Fenwick, R.C.: Davidson, B.J.: Chung, B.T. 25(1)	56	Seismic considerations in the design of cryogenic pressure vessels. Webster, J. 16(4)	306
P-delta effects in medium height moment resisting steel frames under seismic loading. Tjondro, J.A.: Moss, P.J.: Carr, A.J. 23(4)	305	Seismic design committee. 11(1)	64
Post-elastic seismic response of a reinforced concrete frame. Walpole, W.R.: Shepherd, R. 1(2)	102	Seismic design considerations of the properties of New Zealand manufactured steel reinforcing bars. Andriono, T.: Park, R. 19(3)	213
Prediction of post-elastic seismic response of structures by a mode superposition technique. Gillies, A.G.: Shepherd, R. 16(3)	222	Seismic design in reinforced concrete: the state of the art in New Zealand. Paulay, T. 21(3)	208
Preliminary tests on an energy absorbing element for braced structures under earthquake loading. Tyler, R.G. 16(3)	201	Seismic design of gravity retaining walls. Elms, D.G.: Richards, R. 12(2)	114
Present status of the Railway Technical Research Institute and seismic research and designing in the Japanese National Railways. Tatsuo Nishiki. 3(4)	143		

Seismic design of high rise buildings. McKenzie, G.H.F. 4(2)	222	Strength and ductility in reinforced concrete frames designed with Mexican codes. Rodriguez, M. 23(3)	184
Seismic design of masonry buildings - background to the draft masonry design code DZ4210. Priestley, M.J.N. 13(4)	329	Structural examination of high rise buildings in Japan. Toshihiko Hisada. 1(1)	Unpaged
Seismic design of masonry structures to the new provisional New Zealand Standard NZS 4230P. Priestley, M.J.N. 18(1)	1	Support structure design for New Zealand Forest Products Ltd's No. 5 recovery boiler. Sharpe, R.D. 20(1)	2
Seismic design of pallet racking systems. Brown, B.J. 16(4)	291	Tauranga Harbour crossing, Stella Passage bridge - seismic design. Bloxam, M.J.: North, P.J. 23(3)	220
Seismic design of prestressed concrete buildings. Nishiyama, M. 23(4)	288	Technical note: Advances in earthquake engineering. O'Leary, A.J. 13(3)	310
Seismic design of public buildings. Shephard, R.B.: Glogau, O.A. 2(4)	391	Tests on an axially loaded steel energy absorber. Tyler, R.G.: Heine, A.J. 17(1)	47
Seismic design of South Brighton Bridge - a decision against mechanical energy dissipators. Priestley, M.J.N.: Stockwell, M.J. 11(2)	110	The capacity design of reinforced concrete hybrid structures for multistorey buildings. Paulay, T.: Goodsir, W.J. 19(1)	1
Seismic design of storage tanks. Priestley, M.J.N.: Wood, J.H.: Davidson, B.J. 19(4)	272	The centre of earthquake loading on tall buildings. Irvine, H.M. 9(4)	195
Seismic design of timber structures study group review, March 1986. Williams, R. 19(1)	40	The cyclic yield response of a steel star plate cruciform joint. Croad, R.N.: Mead, F.H.: Shepherd, R. 8(3)	204
Seismic forces in base-isolated masonry structures. Priestley, M.J.N.: Crosbie, R.L.: Carr, A.J. 10(2)	55	The design and construction of the Bank of New Zealand, Wellington, New Zealand. Smith, I.C.: Spring, K.C.F.: Sidwell, G.K. 8(2)	142
Seismic hazard analysis and design loads. Berrill, J.B. 18(2)	139	The design of public buildings. Glogau, O.A. 5(4)	128
Seismic hazard estimates for the Auckland area, and their design and construction implications. Dowrick, D.J. 25(3)	211	The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea. Jury, R.D.: Hollings, J.P.: Fraser, I.A.N. 15(3)	123
Seismic performance of two full-size reinforced concrete beam-column joint units. Blakeley, R.W.G.: Megget, L.M.: Priestley, M.J.N. 8(1)	38	The development of the design of the ANZ Head Office building, Lambton Quay, Wellington. Sharpe, R.D.: Binney, J.R.: McNaughton, D.J. 12(3)	204
Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. Priestley, M.J.N. 10(1)	1	The ductility of structural walls. Paulay, T.: Goodsir, W.J. 18(3)	250
Seismic resistant joints for reinforced concrete structures. Fenwick, R.C. 14(3)	145	The energy dissipation effects of redundant members in silos under earthquakes. Li Zhiming: Geng Shujiang. 20(4)	269
Seismic response of elevated water reservoirs. Hunt, B.: Priestley, M.J.N. 15(2)	68	The influence of bridge geometry on the seismic behaviour of bridges on isolating bearings. Moss, P.J.: Carr, A.J.: Cooke, N.: Tan Fun Kwai. 19(4)	255
Seismic response of low-rise buildings. Moss, P.J.: Carr, A.J.: Buchanan, A.H. 19(3)	180	The New Zealand Loadings Code and its application to the design of seismic resistant prestressed concrete structures. Butcher, G.W. 9(3)	162
Seismic response of structures free to rock on their foundations. Priestley, M.J.N.: Evison, R.J.: Carr, A.J. 11(3)	141	The objective of the New Zealand Seismic Design Code. Glogau, O.A. 5(4)	113
Seismic risk and design criteria. Hatrick, A.V. 13(1)	14	The performance of a ductile moment resisting connection between a precast concrete column and a timber beam. Dean, J.A. 19(2)	111
Seismic shear loading at flexural capacity in cantilever wall structures. Blakeley, R.W.G.: Cooney, R.C.: Megget, L.M. 8(4)	278	The seismic behaviour of plywood sheathed shearwalls. Dean, J.A.: Stewart W.G.: Carr, A.J. 19(1)	48
Seismic stability of reinforced earth retaining walls. Bracegirdle, A. 13(4)	347	The seismic design of an industrial chimney with rocking base. Sharpe, R.D.: Skinner, R.I. 16(2)	98
Seismic strengthening of existing reinforced concrete buildings in Japan. Shunsuke Sugano. 14(4)	209	The seismic design of industrial plants. Evison, R.D.: Mowat, A.F. 15(4)	171
Shear modulus Gs. Hughes, D.K. 20(1)	63	The seismic performance of energy absorbing dampers in building structures. Key, D.E. 17(1)	38
Shear reinforcement of reinforced concrete inelastic interior beam-column joints. Ichinose, T. 20(2)	116	The seismic performance of steel encased reinforced concrete bridge piles. Park, R.J.T.: Priestley, M.J.N.: Walpole, W.R. 16(2)	123
Slenderness effects in earthquake resisting frames. Andrews, A.L. 10(3)	154	The seismic response of inelastic structures. Sharpe, R.D.: Carr, A.J. 8(3)	192
Sliding-vibrating responses of elastic structures (and see Errata). Fu Yu-An. 21(3)	190	The seismic response of nonstructural elements in buildings. Arnold, C. 24(4)	306
Some aspects of shear wall design. Paulay, T. 5(3)	89	The seismic restraint of building services - a code of practice. Upritchard, G.J. 12(2)	94
Some comments on reinforced concrete structures forming column hinge mechanisms. Kelly, T.E. 10(4)	186	The shear strength of shear walls. Paulay, T. 3(4)	148
Some limitations of modal analysis in seismic design. Shepherd, R. 2(3)	284	The specification of earthquake resistance for electricity system equipment. Hitchcock, H.C. 6(4)	178
Some possible revisions to the seismic provisions of the New Zealand Concrete Design Code for Moment Resisting Frames. Cheung, P.C.: Paulay, T.: Park, R. 25(1)	37		
Steel design. Butcher, G.W. 6(2)	71		
Steel seismic design. Butcher, G.W. 3(2)	60		

The structural check of high rise building design. Edwards, W.P. 5(2)	52
The task of earthquake resistance design - a divergent problem. Garden, R.J.P. 4(2)	331
Theorisation of structural behaviour with a view to defining resistance and ultimate deformability. Park, R. 6(2)	52
Timber sheathed walls for wind and earthquake resistance. Dowrick, D.J.: Smith, P.C. 19(2)	123
Treatment of earthquake accelerograms. Boyce, W.H. 3(4)	163
Two dimensional nonlinear site response analyses. Larkin, T.: Marsh, J. 25(3)	222
Uniaxial dynamic analysis of a six storey reinforced concrete framed structure. Kelly, T.E. 10(1)	37
United States/New Zealand/Japan/China collaborative research project on the seismic design of reinforced concrete beam-column-slab joints. Park, R.: Hopkins, D.C. 22(2)	122
Use of yield ratio response spectra to design yielding members for improving earthquake resistance of brittle structure. Gilmour, R.M.: Hitchcock, H.C. 4(2)	285

SEISMIC HAZARDS (includes seismic risk)

Brief review of modern earthquake engineering. Ferry Borges, J.: Despeyroux, J.: Maeda, Y.: Mazilu, P.: Robinson, J.R. 4(3)	397
Case studies: earthquake risk buildings. <i>See</i> Earthquake Risk Buildings.	
Developments in studies of earthquake risk. Adams, R.D. 8(1)	1
Earthquake and business interruption: a policy for survival? Jacob, P. 22(4)	232
Earthquake engineering in regions of low seismicity. Pappin, J.W. 24(4)	317
Earthquake risk buildings - lessons from experience. Hopkins, D.C.: Robertson, T.W. 14(2)	54
Earthquake risk buildings in Wellington. Bentley, R.J. 11(3)	200
Glossary of terms for probabilistic seismic-risk and hazard analysis. 19(3)	155
How well is the insurance industry in New Zealand served by existing research and technology? Smith, W.D. 23(2)	134
Letter - Tsunami risk. Garden, R.J.P. 1(2)	97
New Zealand seismic hazard analysis. Matuschka, T.: Berryman, K.R.: O'Leary, A.J.: McVerry, G.H.: Mulholland, W.M.: Skinner, R.I. 18(4)	313
Planning for disaster. Hodge, W.C. 22(4)	239
Progress in earth science research of benefit to the earthquake insurance industry Berryman, K.R.: Darby, D.J. 23(2)	130
Refurbishing earthquake risk buildings in U.S.A. Leadbeater, D.B. 14(2)	43
Reliability-based risk factors. Elms, D.G. 13(1)	3
Revised estimates of earthquake hazard in New Zealand. Smith, W.D.: Berryman, K.R. 16(4)	259
Seismic effects on nuclear installations introduction, summary and recommendations (<i>see</i> Industrial Plants). 11(3)	161
Seismic hazard analysis and design loads. Berrill, J.B. 18(2)	139
Seismic hazard estimates for the Auckland area, and their design and construction implications. Dowrick, D.J. 25(3)	211
Seismic risk and design criteria. Hatrick, A.V. 13(1)	14
Seismic risks to linear structures. Eiby, G.A. 11(3)	203
Separation of non-structural components in buildings. Glogau, O.A. 9(3)	141

Suspended ceilings: the seismic hazard and damage problem and some practical solutions. Clarke, W.D.: Glogau, O.A. 12(4)	292
Techniques and parameters for earthquake risk assessment. Algermissen, S.T. 22(4)	202
The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions. Rynn, J.M.W.: Brennan, E.: Hughes, P.R.: Pedersen, I.S.: Stuart, H.J. 25(2)	77
The June 28, 1991 Sierra Madre California earthquake. Shepherd, R. 24(4)	279
The role of reinsurance in earthquake risk assessment. Porro, B. 22(4)	219
The role of science and engineering in mitigating natural hazards. Press, F. 18(2)	115
The role of the international reinsurance broker. Greig, J.S. 22(4)	227
Tsunami risk in New Zealand. Eiby, G.A. 1(2)	98
Uncertainties in attenuation relations for New Zealand seismic hazard analysis. McVerry, G.H. 19(1)	28
Vulnerability and seismic risk assessment of buildings following the 1989 Newcastle, Australia, earthquake. Chandler, A.M.: Pappin, J.W.: Coburn, A.W. 24(2)	116
What are the main uncertainties in estimating earthquake risk? Vere-Jones, D. 16(1)	39

SEISMIC ZONING

A philosophy of seismic zoning Eiby, G.A. 4(1)	171
A seismicity model for New Zealand. Peek, R.: Berrill, J.B.: Davis, R.O. 13(4)	355
Book review - Basic concepts of seismic codes. Published by IAEE, Vol 1, 1980. Smith, W.D.: Paulay, T. 14(3)	173
Case studies: earthquake risk buildings (and <i>see</i> Earthquake Risk Buildings). 1. Strengthening of State Trinity Centre, Christchurch. Evans, D.S. 16(2)	162
D.S.I.R. microzoning programme. Adams, R.D. 2(3)	282
Developments in studies of earthquake risk. Adams, R.D. 8(1)	1
Earthquake and business interruption: a policy for survival? Jacob, P. 22(4)	232
Earthquake risk buildings - lessons from experience. Hopkins, D.C.: Robertson, T.W. 14(2)	54
Earthquake risk buildings in Wellington. Bentley, R.J. 11(3)	200
Editorial - Macrozoning for earthquake engineering. Andrews, A.L. 5(3)	ii
Evaluation of dynamic ground characteristics and seismic microzoning. Yoshikazu Kitagana: Yutaka Matsushima. 17(1)	15
Formidable echo. Savarensky, F.F. 3(3)	107
Glossary of terms for probabilistic seismic-risk and hazard analysis. 19(3)	155
How well is the insurance industry in New Zealand served by existing research and technology? Smith, W.D. 23(2)	134
Letter - Tsunami risk. Garden, R.J.P. 1(2)	97
Microzoning for earthquake effects in the Wellington City area. Adams, R.D. 5(3)	106
NZNSEE discussion group on the seismic design of bridges (and <i>see</i> NZNSEE). Section 2: Design earthquake loading and ductility demand. Berrill, J.B.: Priestley, M.J.N.: Chapman, H.E. 13(3)	232
On the observation, characterisation and predictive GIS mapping of strong ground shaking for seismic zoning (a case study in the San Francisco Bay region, California). Borchardt, R.D. 24(4)	287
Planning for disaster. Hodge, W.C. 22(4)	239
Progress in earth science research of benefit to the earthquake insurance industry Berryman, K.R.: Darby, D.J. 23(2)	130

Refurbishing earthquake risk buildings in U.S.A. Leadbeater, D.B. 14(2)	43	Calculating static deformations from quick-release accelerograms. Douglas, B.M.: Maragakis, E.A.: Nath, B. 23(4)	239
Reliability-based risk factors. Elms, D.G. 13(1)	3	Computer processing of New Zealand strong- motion accelerograms. Hodder, S.B. 16(3)	234
Response of ductile reinforced concrete frames located in Zone C. Paulay, T.: Carr, A.J.: Tompkins, D.N. 13(3)	209	Developments in studies of earthquake risk. Adams, R.D. 8(1)	1
Revised estimates of earthquake hazard in New Zealand. Smith, W.D.: Berryman, K.R. 16(4)	259	Discussion - The importance of surface waves in strong ground motion, by W.D. Smith. Vol 10(4). Stephenson, W.R. 11(2)	131
Seismic effects on nuclear installations introduction, summary and recommendations. (<i>See Industrial Plants.</i>) 11(3)	161	Distribution of scatter in New Zealand accelerograph data. Berrill, J.B. 18(2)	151
Seismic hazard estimates for the Auckland area, and their design and construction implications. Dowrick, D.J. 25(3)	211	Earthquake induced resonant motion of alluvium. Stephenson, W.R. 7(3)	144
Seismic microzoning in New Zealand. Stephenson, W.R. 4(1)	43	Earthquake recording instrument: type M.O.2 strong motion accelerograph. Bunce, G.K. 2(3)	308
Seismic risk and design criteria. Hatrick, A.V. 13(1)	14	Edgcombe earthquake - some notes on its source, ground motions, and damage in relation to safety. Dowrick, D.J. 21(3)	198
Seismic risks to linear structures. Eiby, G.A. 11(3)	203	Edgcombe earthquake: reconnaissance report. Pender, M.J.: Robertson, T.W. 20(3)	201
Seismotectonics and earthquake risk macrozoning in New Zealand. Suggate, R.P. 12(1)	3	Engineering seismology. Stephenson, W.R. 2(1)	24
Suspended ceilings: the seismic hazard and damage problem and some practical solutions. Clarke, W.D.: Glogau, O.A. 12(4)	292	Formidable echo. Savarensky, F.F. 3(3)	107
Technical note: A note on the Hutt Valley strong- motion microzone network. Tyler, R.G.: Hefford, R.T. 15(3)	160	Intensities: a strictly subjective view. Eiby, G.A. 9(3)	181
Techniques and parameters for earthquake risk assessment. Algermissen, S.T. 22(4)	202	Microtremor recording techniques. Parton, I.M.: Taylor, P.W. 6(2)	87
The 1989 Newcastle, Australia, earthquake: the facts and the misconceptions. Rynn, J.M.W.: Brennan, E.: Hughes, P.R.: Pedersen, I.S.: Stuart, H.J. 25(2)	77	Microzone effects in the Hutt Valley in records from a strong-motion accelerography array. Sriharan, S.: McVerry, G.H. 25(4)	246
The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea. Jury, R.D.: Hollings, J.P.: Fraser, I.A.N. 15(3)	123	New Zealand earthquakes and plate tectonic theory. Walcott, R.I. 12(2)	87
The insurance industry's role in town planning. Fowler, M. 23(3)	165	On the observation, characterisation and predictive GIS mapping of strong ground shaking for seismic zonation (a case study in the San Francisco Bay region, California). Borchardt, R.D. 24(4)	287
The role of reinsurance in earthquake risk assessment. Porro, B. 22(4)	219	Paleoseismicity of the Wellington fault. Grapes, R. 21(1)	12
The role of the international reinsurance broker. Greig, J.S. 22(4)	227	Prediction of seismic wave amplitudes using the phase-front parabolic approximation. Haines, A.J. 17(2)	145
Tsunami risk in New Zealand. Eiby, G.A. 1(2)	98	Preliminary field observations of the Chilean earthquake of 3 March 1985 Dowrick, D.J. 18(2)	119
Vulnerability and seismic risk assessment of buildings following the 1989 Newcastle, Australia, earthquake. Chandler, A.M.: Pappin, J.W.: Coburn, A.W. 24(2)	116	Principal earthquakes in New Zealand during the year(s) 1972, 1973, 1975, 1979 (<i>see Earthquakes in New Zealand</i>).	
What are the main uncertainties in estimating earthquake risk? Vere-Jones, D. 16(1)	39	Procedures for operating the New Zealand strong- motion accelerograph network. Hefford, R.T.: Randel, P.M. 16(1)	45
Who says earthquakes don't happen here? Adams, R.D. 7(2)	52	Properties of aftershock sequences. Adams, R.D. 1(2)	113
SEISMOLOGY		Reconnaissance field investigation of the Landers earthquake (Ms 7.5) of June 28, 1992, San Bernadino County, California, USA. Berryman, K. 25(3)	230
A history of anti-seismic measures in New Zealand. Eiby, G.A. 8(4)	255	Seismic risks to linear structures. Eiby, G.A. 11(3)	203
A preliminary seismological report (<i>Inangahua earthquake 1968</i>). Adams, R.D.: Eiby, G.A.: Lowry, M.A. 2(1)	9	Seismotectonics and earthquake risk macrozoning in New Zealand. Suggate, R.P. 12(1)	3
A revision of attenuation relationships for Modified Mercalli intensity in New Zealand earthquakes. Dowrick, D.J. 24(3)	210	Strategies for strong motion earthquake recording in New Zealand. Stephenson, W.R. 12(3)	269
An immediate field survey of the San Fernando, Los Angeles earthquake, February 9, 1971. Adams, R.D. 4(3)	335	Strong motion data centre. Denham, D.: Small, G.R. 4(1)	15
Analysis of microtremor records. Parton, I.M.: Taylor, P.W. 6(3)	96	Strong motion records of the Milford Sound earthquake 1976 May 4. Hodder, S.B.: Skinner, R.I.: Hefford, R.T.: Randal, P.M. 11(3)	184
Anomalous intensities due to the Korakonui earthquake, 5 December, 1976. Eiby, G.A. 10(4)	167	Strong motion seismology. Hudson, D.E. 10(3)	113
Application of microtremor measurements to earthquake engineering. Parton, I.M.: Taylor, P.W. 6(4)	170	Strong-motion earthquake recording in New Zealand. Skinner, R.I.: Stephenson, W.R.: Hefford, R.T. 4(1)	31
		Strong-motion earthquake records. Taylor, P.W. 7(2)	53
		Suggested extensions of the New Zealand strong motion accelerograph network. Berrill, J.B. 12(3)	264

Surface wave magnitudes of some New Zealand earthquakes 1901-1988. Dowrick, D.J.:	
Smith, E.G.C. 23(3)	198
Technical note - A note on the 1976, Gazli accelerogram. Berrill, J.B. 10(4)	238
Technical note: Intensity of shaking generated by large shallow New Zealand earthquakes.	
Andrews, A.L.: Butcher, G.W. 25(4)	358
Technical note: A note on the Hutt Valley strong-motion microzone network. Tyler, R.G.: Hefford, R.T. 15(3)	160
Technical note: Computer analyses of New Zealand earthquake accelerograms - Volume 1. Beck, J.L.:	
Randal, P.M.: Hefford, R.T. 15(1)	46
Technical note: Strong motion record from Turangi, 5 March 1984. Hodder, S.B. 17(2)	154
Technical note: strong-motion instrumentation and records in the Wanganui earthquake swarm.	
McVerry, G.H.: Hefford, R.T. 15(4)	216
The Dunedin earthquake, 9 April 1974, Part 1 (and see Earthquakes in New Zealand): seismological studies. Adams, R.D.: Kean, R.J. 7(3)	115
The importance of surface waves in strong ground-motion. Smith, W.D. 10(4)	170
The Milford Sound earthquake of 1976 May 4.	
Eiby, G.A. 11(3)	191
The MO2A strong-motion accelerograph.	
Hefford, R.T.: Tyler, R.G.: Skinner, R.I. 13(4)	374
The New Zealand seismograph network.	
Adams, R.D. 1(2)	116
The New Zealand strong motion earthquake recorder network. Hefford, R.T.: Randal, P.M.: Skinner, R.I.:	
Beck, J.L.: Tyler, R.G. 12(3)	256
Treatment of earthquake accelerograms.	
Boyce, W.H. 3(4)	163
Who says earthquakes don't happen here?	
Adams, R.D. 7(2)	52

SOILS *see* Ground response, Geology

STANDARDS

1975 Seminar on NZS 4203.	
Code philosophy. Glogau, O.A. 9(1)	43
Code provisions related to soils and foundations.	
Taylor, P.W. 9(1)	68
Design loadings. Butcher, G.W. 9(1)	56
Dynamic aspects of the Code for the design of earthquake resistant buildings Skinner, R.I. 9(1)	63
Parts and portions of buildings. Kolston, D. 9(1)	74
Seismic torsional effects on buildings. Elms, D.G. 9(1)	79
Wind loading. O'Donovan, C.J. 9(1)	84
A general introduction to the seismic design problem.	
Garden, R.J.P. 2(3)	202
A history of anti-seismic measures in New Zealand.	
Eiby, G.A. 8(4)	255
A message from the Standards Association of New Zealand. Edwards, G.H. 2(3)	270
A new building control system - its nature and some implications. Hall, C.W. 23(3)	168
A new draft code for seismic design of buildings in Indonesia. Fraser, I.A.N. 16(3)	247
A note about base shear. Andrews, A.L. 2(2)	171
A note about N.Z.S. 1900 building codes and changes. Hitchcock, E.H. 2(3)	271
A review of the new code provisions for separation of elements and buildings. Blakeley, R.W.G. 7(3)	130
Agadir, Morocco, reconstruction work six years after the earthquake of February 1960.	
Falconer, B.H. 1(2)	72
An earthquake code for plumbing?	
McKenzie, G.H.F. 7(1)	50

Assessment of earthquake response from modal analysis. McKenzie, G.H.F. 3(2)	89
Behaviour of lifts - the Wellington earthquake November 1, 1968. McKenzie, D.J. 2(3)	278
Book review - Basic concepts of seismic codes. Published by IAEE, Vol 1, 1980. Smith, W.D.:	
Paulay, T. 14(3)	173
Classification of high earthquake risk buildings	
Draft Code of Practice 2 March 1972. 5(2)	37
Code provisions for confining steel in potential plastic hinge regions of columns in seismic design. Park, R.: Priestley, M.J.N. 13(1)	60
Codes for seismic design of prestressed concrete.	
Williamson, K.E. 2(3)	277
Comparative analyses of a multi-storey frame and wall using the current and draft loading codes.	
Fenwick, R.C.: Davidson, B.J. 22(4)	181
Comparison of recent New Zealand and United States seismic design provisions for reinforced concrete beam-column joints and test results from four units designed according to the New Zealand code. Park, R.: Milburn, J.R. 16(1)	3
Confined columns. Glogau, O.A. 3(4)	181
Considerations for a "design" earthquake.	
Evans, G.L. 5(2)	47
Cost effectiveness of code base shear requirements for reinforced concrete frame structures.	
Elms, D.G.: Silvester, D. 11(2)	85
Cyclic load testing of two refined reinforced concrete beam-column joints. Blakeley, R.W.G.:	
Edmonds, F.D.: Megget, L.M.: Wood, J.H. 12(3)	238
Design loads - readers' views. Williamson, K.E.:	
Andrews, A.L. 3(3)	126
Design of shear walls for seismic resistance.	
Armstrong, I.C. 10(1)	17
Discussion - Assessment of earthquake response from modal analysis, by G.H.F. McKenzie.	
Shepherd, R. 3(2)	90
Discussion - Classification of high earthquake risk buildings Draft Code of Practice, 2 March 1972.	
Bluck, B.C. 5(3)	108
Discussion - Seismic design of public buildings, by R.B. Shephard and O.A. Glogau. Vol 2(4).	
Edwards, W.P. 3(2)	91
Discussion of paper 'Comparison of recent New Zealand United States seismic design provisions for reinforced concrete beam-column joints and test results for four units designed according to the New Zealand Code', by R Park & J R Milburn. Fenwick, R.C.: Hopkins, D.C. 17(1)	69
Discussion: Reinforced masonry shear walls: cyclic load tests in contraflexure, by S.J. Thurston and D.L. Hutchison (Vol 15(1)). Priestley, M.J.N. 15(2)	97
Draft revision of NZS 4203:1984: seismic provisions.	
Hutchison, D.L.: Andrews, A.L.: Butcher, G.W.:	
Kolston, D. 19(3)	158
Ductile reinforced concrete frames - some comments on the special provisions for seismic design of ACI 318-71 and on capacity design. Park, R.:	
Paulay, T. 8(1)	70
Earthquake risk buildings - lessons from experience.	
Hopkins, D.C.: Robertson, T.W. 14(2)	54
Eccentric beam to column junctions. Mead, F.H. 3(1)	24
Evaluation of earthquake response of low-rise structures using design codes and local specifications. Hutchinson, G.L.: Navidi, A. 16(4)	331
Floor response of yielding structures.	
Kelly, T.E. 11(4)	255
Further comments on seismic design loads for bridges.	
Berrill, J.B.: Priestley, M.J.N.: Peek, R. 14(1)	3

- Maximum yield stress in reinforced concrete frames.
Mackenzie, D.S. 2(3) 267
- Notes on the New Zealand earthquake loading provisions. Kolston, D. 8(2) 102
- NZNSSEE discussion group on seismic design of ductile moment resisting reinforced concrete frames (and *see* NZNSSEE).
Section G Columns - evaluation of actions.
Paulay, T. 10(2) 85
Section K Parts, portions and secondary elements.
Allardice, N.W. 10(2) 102
- Outline of earthquake provisions in the recently revised Japanese building code. Hiroyuki Aoyama. 14(2) 63
- Prestressed concrete seismic design.
Blakeley, R.W.G. 6(1) 2
- Recommendations for the seismic design of petrochemical plants. Norton, J.A.:
Gillies, A.G.: Edmonds, F.D. 15(2) 105
- Refurbishing earthquake risk buildings in U.S.A.
Leadbeater, D.B. 14(2) 43
- Reinforced concrete beam-column joints for seismic loading. Fenwick, R.C.: Irvine, H.M. 10(4) 174
- Reinforced masonry shear walls: cyclic load tests in contraflexure. Thurston, S.J.:
Hutchison, D.L. 15(1) 27
- Reliability-based risk factors. Elms, D.G. 13(1) 3
- Review of code developments for earthquake resistant design of concrete structures in New Zealand. Park, R. 14(4) 177
- Seismic code development for steel structures.
Krawinkler, H. 20(2) 127
- Seismic design considerations of the properties of New Zealand manufactured steel reinforcing bars. Andiono, T.: Park, R. 19(3) 213
- Seismic design of masonry buildings - background to the draft masonry design code DZ4210.
Priestley, M.J.N. 13(4) 329
- Seismic design of masonry structures to the new provisional New Zealand Standard NZS 4230P.
Priestley, M.J.N. 18(1) 1
- Seismic design of public buildings. Shephard, R.B.:
Glogau, O.A. 2(4) 391
- Seismic design of storage tanks. Priestley, M.J.N.:
Wood, J.H.: Davidson, B.J. 19(4) 272
- Seismic design of timber structures study group review, March 1986. Williams, R. 19(1) 40
- Seismic resistance of reinforced concrete masonry shear walls with high steel percentages.
Priestley, M.J.N. 10(1) 1
- Seismic response of structures free to rock on their foundations. Priestley, M.J.N.:
Evison, R.J.: Carr, A.J. 11(3) 141
- Seismic risk and design criteria. Hatrick, A.V. 13(1) 14
- Seismic shear loading at flexural capacity in cantilever wall structures Blakeley, R.W.G.:
Cooney, R.C.; Megget, L.M. 8(4) 278
- Slenderness effects in earthquake resisting frames. Andrews, A.L. 10(3) 154
- Some possible revisions to the seismic provisions of the New Zealand Concrete Design Code for Moment Resisting Frames. Cheung, P.C.: Paulay, T.:
Park, R. 25(1) 37
- Standards Association of New Zealand Comments on chapter 8 of NZSS 1900. Garden, R.J.P. 5(2) 51
- Strength and ductility in reinforced concrete frames designed with Mexican codes. Rodriguez, M. 23(3) 184
- The development of seismic zones and the evaluation of lateral loadings for earthquake resistant design of buildings in Papua New Guinea. Jury, R.D.: Hollings, J.P.:
Fraser, I.A.N. 15(3) 123
- The need for a strengthening code. Bluck, B.C. 7(2) 88
- The new draft concrete design code.
McKenzie, G.H.F. 11(3) 181
- The New Zealand Loadings Code and its application to the design of seismic resistant prestressed concrete structures.
Butcher, G.W. 9(3) 162
- The objective of the New Zealand Seismic Design Code. Glogau, O.A. 5(4) 113
- The October 1, 1987 Whittier Narrows earthquake.
Shepherd, R. 20(4) 255
- The seismic design of industrial plants.
Evison, R.D.: Mowat, A.F. 15(4) 171
- The seismic restraint of building services - a code of practice. Upritchard, G.J. 12(2) 94
- The structural performance of houses in earthquakes.
Cooney, R.C. 12(3) 223
- The task of earthquake resistance design - a divergent problem. Garden, R.J.P. 4(2) 331
- ## STEEL
- A design criteria of beam-to-column joint panels.
Kato, B. 7(1) 14
- A tenacious base isolation system using round steel bars. Tyler, R.G. 11(4) 273
- Advances in design of eccentrically braced frames.
Popov, E.P.: Kasai, K.: Engelhardt, M.D. 20(1) 22
- Behaviour of a prestressed concrete interior beam-column assembly under cyclic loading:
Unit 1 test results. Park, R.: Thompson, K.J. 6(4) 158
- Behaviour of steel beam-column connections, made using bolted end plates. Johnstone, N.D.:
Walpole, W.R. 15(2) 82
- Computer-aided structural analysis and design of the 37-storey Los Angeles Bonaventure Hotel.
Nicoletti, J.P.: Jhaveri, D.P.: Emkin, L.Z.:
Mesley, R.C. 12(3) 212
- Cyclic loading tests on steel portal frame knee joints. Beamish, M.J. 20(1) 42
- Discussion - Seismic resistance of reinforced concrete masonry shear walls with high steel percentages, by M.J.N. Priestley (Vol 10(1)).
Glogau, O.A. 11(1) 70
- Discussion and authors' reply: P-delta effects in medium height moment resisting steel frames under seismic loading. (23(4) p.305) Fenwick, R.C. 25(1) 70
- Effects of hoop reinforcement in steel and reinforced concrete composite sections. Suzuki, T.:
Takiguchi, K.: Ichinose, T.: Okamoto, T. 17(3) 198
- Further notes on a steel energy-absorbing element for braced frameworks. Tyler, R.G. 18(3) 270
- Inelastic dynamic analysis of steel structures.
Lord, J.: Hoerner, J.B.: Zayed, M. 8(4) 273
- Letter to the editor. Page, G.G. 7(2) 90
- Maximum yield stress in reinforced concrete frames.
Mackenzie, D.S. 2(3) 267
- NZNSSEE study group for structures of limited ductility (and *see* NZNSSEE): 2. Design of building structures of limited ductility 2.4 Structural steel.
Spring, K.C.F. 19(4) 305
- NZNSSEE study group for the seismic design of steel structures. *See* NZNSSEE.
- On California structural steel seismic design.
Popov, E.P. 20(1) 7

P-delta effects in medium height moment resisting steel frames under seismic loading. Tjondro, J.A.: Moss, P.J.: Carr, A.J. 23(4)	305
Recent developments in seismic design of reinforced concrete buildings in Japan. Aoyama, H. 24(4)	333
Seismic code development for steel structures. Krawinkler, H. 20(2)	127
Seismic design considerations of the properties of New Zealand manufactured steel reinforcing bars. Andiono, T.: Park, R. 19(3)	213
Seismic resistance of reinforced concrete masonry shear walls with high steel percentages. Priestley, M.J.N. 10(1)	1
Shake table tests of an industrial building. Takanashi, K.: Ohi, K.: Sakai, Y. 20(1)	53
Steel design. Butcher, G.W. 6(2)	71
Steel seismic design. Butcher, G.W. 3(2)	60
Stress-strain model for grade 275 reinforcing steel with cyclic loading. Thompson, K.J.: Park, R. 11(2)	101
Stress-strain model for prestressing steel with cyclic loading. Thompson, K.J.: Park, R. 11(4)	209
Tapered steel energy dissipators for earthquake resistant structures. Tyler, R.G. 11(4)	282
Technical note - Testing of small rectangular hollow sections having welded connections. Hutchinson, D.L. 14(4)	253
Technical note: Local buckling of universal beam flanges. Thurston, S.J. 15(2)	96
The behaviour, overview of damage and retrofit of steel buildings after the earthquakes of September 1985. Martinez-Romero, E. 20(1)	30
The cyclic yield response of a steel star plate cruciform joint. Croad, R.N.: Mead, F.H.: Shepherd, R. 8(3)	204
The design and construction of the Bank of New Zealand, Wellington, New Zealand. Smith, I.C.: Spring, K.C.F.: Sidwell, G.K. 8(2)	142
The seismic performance of steel encased reinforced concrete bridge piles. Park, R.J.T.: Priestley, M.J.N.: Walpole, W.R. 16(2)	123
The use of Grade 380 steel for transverse confirming reinforcement in columns. Zahn, F.A.: Park, R.: Priestley, M.J.N. 20(2)	99
Theorisation of structural behaviour with a view to defining resistance and ultimate deformability. Park, R. 6(2)	52

STRONG MOTION SEISMOLOGY

Computer processing of New Zealand strong-motion accelerograms. Hodder, S.B. 16(3)	234
Discussion - The importance of surface waves in strong ground motion, by W.D. Smith. Vol 10(4). Stephenson, W.R. 11(2)	131
Distribution of scatter in New Zealand accelerograph data. Berrill, J.B. 18(2)	151
Earthquake recording instrument: type M.O.2 strong motion accelerograph. Bunce, G.K. 2(3)	308
Formidable echo. Savarensky, F.F. 3(3)	107
Microzone effects in the Hutt Valley in records from a strong-motion accelerography array. Sritharan, S.: McVerry, G.H. 25(4)	246
On the observation, characterisation and predictive GIS mapping of strong ground shaking for seismic zonation (a case study in the San Francisco Bay region, California). Borchardt, R.D. 24(4)	287
Procedures for operating the New Zealand strong-motion accelerograph network. Hefford, R.T.: Randel, P.M. 16(1)	45
Strategies for strong motion earthquake recording in New Zealand. Stephenson, W.R. 12(3)	269

Strong motion data centre. Denham, D.: Small, G.R. 4(1)	15
Strong motion records of the Milford Sound earthquake 1976 May 4. Hodder, S.B.: Skinner, R.I.: Hefford, R.T.: Randal, P.M. 11(3)	184
Strong motion seismology. Hudson, D.E. 10(3)	113
Strong-motion earthquake recording in New Zealand. Skinner, R.I.: Stephenson, W.R.: Hefford, R.T. 4(1)	31
Strong-motion earthquake records. Taylor, P.W. 7(2)	53
Suggested extensions of the New Zealand strong motion accelerograph network. Berrill, J.B. 12(3)	264
Technical note - A note on the 1976, Gazli accelerogram. Berrill, J.B. 10(4)	238
Technical note: A note on the Hutt Valley strong-motion microzone network. Tyler, R.G.: Hefford, R.T. 15(3)	160
Technical note: Computer analyses of New Zealand earthquake accelerograms -Volume 1. Beck, J.L.: Randal, P.M.: Hefford, R.T. 15(1)	46
Technical note: Strong motion record from Turangi, 5 March 1984. Hodder, S.B. 17(2)	154
Technical note: strong-motion instrumentation and records in the Wanganui earthquake swarm. McVerry, G.H.: Hefford, R.T. 15(4)	216
The importance of surface waves in strong ground-motion. Smith, W.D. 10(4)	170
The MO2A strong-motion accelerograph. Hefford, R.T.: Tyler, R.G.: Skinner, R.I. 13(4)	374
The New Zealand strong motion earthquake recorder network. Hefford, R.T.: Randal, P.M.: Skinner, R.I.: Beck, J.L.: Tyler, R.G. 12(3)	256
Treatment of earthquake accelerograms. Boyce, W.H. 3(4)	163

TIMBER

A simulated earthquake test of a timber house. Tracey, W.J. 2(3)	289
Developments in design of wood structures for earthquake resistance. Buchanan, A.H. 16(2)	156
Horizontal timber diaphragms for wind and earthquake resistance. Smith, P.C.: Dowrick, D.J.: Dean, J.A. 19(2)	135
Hysteresis loops for timber structures. Dowrick, D.J. 19(2)	143
Hysteretic modelling of moment-resisting nailed timber joints. Kivell, B.T.: Moss, P.J.: Carr, A.J. 14(4)	233
Nailed moment joints in timber structures. Bryant, A.H.: Gibson, J.A.: Mitchell, T.N.: Thurston, S.J. 14(4)	223
Seismic design of timber structures study group review, March 1986. Williams, R. 19(1)	40
The seismic behaviour of plywood sheathed shearwalls. Dean, J.A.: Stewart W.G.: Carr, A.J. 19(1)	48
The structural performance of houses in earthquakes. Cooney, R.C. 12(3)	223
Timber sheathed walls for wind and earthquake resistance. Dowrick, D.J.: Smith, P.C. 19(2)	123

TSUNAMIS

Letter - Tsunami risk. Garden, R.J.P. 1(2)	97
Tsunami risk in New Zealand. Eiby, G.A. 1(2)	98

VOLCANOES

Frequency of eruptions at New Zealand volcanoes. Latter, J.H. 18(1)	55
Principal earthquakes in New Zealand during the year 1975. 9(2)	135